

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 11 Mar 2019)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHB3552Z/11/03/2019 15:28**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER UNDER COVER	20.00	0.00	*228.00 FL <i>UNT</i>
2	1		*REAR BUMPER SIDE BRACKET RH	20.00	0.00	*24.60 FL <i>XSK</i>
						Sub Total (S\$) 252.60
						- List Item Discount on L Items (S\$) 50.52
						Total Parts (S\$) 202.08

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHB3552Z/11/03/2019 15:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS