

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TPRES/ODRES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD1227R Yr Regt: 22 Mar, 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~o~~ / Prime Mover /

Truck / Trailer or

Make: Hyundai 230 S.C. 1582Colour: Silver A/C: Ins 6 / Std / NI / NASp. Reading: 174.53 T/Radio: Ins 8 / Std / NI / NA

Eng/No: _____

C/No: TMAP2814VHJ127856Gen. Cond: Good / 6 / Poor / BurntSteering: Inor 6 / Jammed / Leaked / Burnt orBrake: Inor 6 / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD 6 / orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxx3

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 27/4/19 D.O.I. 4/3/19Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4 DO1 CTZ

5

P/P \$725.76

6 OUT

R (\$3,105.14/81%)

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199507195R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI19004053/K1jb3

Date: 05.03.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD1227R


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04.03.2019 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,830.92
Revised Estimate Amount	: S\$	725.76
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SHD1227R
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Scheme:	Taxi (Company)
Vehicle Make:	HYUNDAI
Vehicle Model:	I30 GDH 1.6 TCI 5DR DCT
Chassis No.:	TMAD281UVHJ127856
Propellant:	Diesel
Engine No.:	D4FBGZ122109
Engine Capacity:	1582 cc
Maximum Power Output:	100.0 kW (134 bhp)
Maximum Laden Weight:	1940 kg
Unladen Weight:	1496 kg
Year Of Manufacture:	2016
Original Registration Date:	22 Mar 2017
Lifespan Expiry Date:	21 Mar 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid:	\$39,544.00
COE Expiry Date:	21 Mar 2025
Road Tax Expiry Date:	21 Mar 2019
PARF Eligibility Expiry Date:	21 Mar 2025
Inspection Due Date:	21 Sep 2019
Intended Transfer Date:	28 Feb 2019
CO2 Emission:	127.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$7,500.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 21 Mar 2019. You may renew the road tax from 22 Dec 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 21 Mar 2019, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 22 Mar 2019 to 21 Sep 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	2,635.00	-	2,635.00
Total Amount Payable:			2,660.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

27-Feb-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1227 R

1 pc	Emblem I30 ✓	\$	27.80
1 pc	Emblem CRDI ✓	\$	29.40
1 pc	Emblem Hyundai X	\$	29.40
1 pc	Rear bumper X <i>Repair</i>	\$	811.11
1 pc	Rear bumper sponge X	\$	79.20
1 pc	Rear bumper reinforcement X	\$	815.64
1 pc	Rear bumper reinforcement centre X	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 X	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @\$107.50 ✓	\$	215.00
		\$	2,191.15
		Less 20%	\$ 438.23
		\$	1,752.92

S/NETT

1 set	Rear bumper clips X	\$	48.00
1 set	Reverse sensor X	\$	280.00
1 set	Tailgate stickers ✓	\$	100.00

Sundry

To dismantle and replace reverse sensor and test system

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, tailgate & tailgate lower garnish, etc

To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish

To apply rustproofing on the repaired and replaced panels

Total \$ 3,830.92

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplies must be resurveyed and approved from Insurance Company

Ka/ni 11/11/19

4/3/19 1640h

2 Pys.

P/P After Repair photo

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

27-Feb-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1227 R

1 pc	Emblem I30	✓	\$	27.80
1 pc	Emblem CRDI	✓	\$	29.40
1 pc	Emblem Hyundai	X	\$	29.40
1 pc	Rear bumper	X	\$	811.11
1 pc	Rear bumper sponge	X	\$	79.20
1 pc	Rear bumper reinforcement	X	\$	815.64
1 pc	Rear bumper reinforcement centre	X	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	X	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @ \$107.50	X	\$	215.00
				\$ 2,191.15
Less 20%				\$ 438.23
				\$ 1,752.92

S/NETT

1 set	Rear bumper clips	X	\$	48.00
1 set	Reverse sensor	X	\$	280.00
1 set	Tailgate stickers	✓	\$	100.00

Sundry

To dismantle and replace reverse sensor and test system

To labour charge for dismantle and renew with the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, tailgate & tailgate lower garnish, etc

To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish

To apply rustproofing on the repaired and replaced panels

Total \$ 3,830.92

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalini 11/11/19

4/3/19 1640h

2 Pys.

P/P After Repair phh

14/3/19

check P4 \$ 725.76 / 2 Pys.

✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by Insurance Company

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.: SHD1227R
 Vehicle Type: H10 - Public Transport Taxi (Motor Car)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Scheme: Taxi (Company)
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Chassis No.: TMAD281UVHJ127856
 Propellant: Diesel
 Engine No.: D4FBGZ122109
 Engine Capacity: 1582 cc
 Maximum Power Output: 100.0 kW (134 bhp)
 Maximum Laden Weight: 1940 kg
 Unladen Weight: 1496 kg
 Year Of Manufacture: 2016
 Original Registration Date: 22 Mar 2017
 Lifespan Expiry Date: 21 Mar 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 PQP Paid: \$39,544.00
 COE Expiry Date: 21 Mar 2025
 Road Tax Expiry Date: 21 Mar 2019
 PARF Eligibility Expiry Date: 21 Mar 2025
 Inspection Due Date: 21 Sep 2019
 Intended Transfer Date: 28 Feb 2019
 CO2 Emission: 127.00 (g/km)
 CEV/VES Rebate Utilised: \$7,500.00
 Amount:
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -

The current road tax expiry is 21 Mar 2019. You may renew the road tax from 22 Dec 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 21 Mar 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 22 Mar 2019 to 21 Sep 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	2,635.00	-	2,635.00
Total Amount Payable:			2,660.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5107202885-001592

Cover : Third Party

1. Index mark and Registration Number of Vehicle : **SHD1227R**
Chassis Number : **TMAD281UVHJ127856**
2. Name of Policyholder : **PREMIER TAXIS PTE. LTD.**
3. Effective Date of Insurance : **01 Feb 2019**
4. Expiry Date of Insurance : **31 Jan 2020**
5. Persons or Classes of Persons entitled to drive*
 - (a) The Policyholder.
 - (b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use*
 - (a) Use as a Taxi.
 - (b) Use for social domestic and pleasure purposes.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)	: N/A
EXCESS (SECTION II)	: S\$3,500
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : **HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)**
Date of Issue : **01 Feb 2019 09:37 hrs**

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19004053/K1jb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 11-07-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGP 7572C	Veh. Inspected	SHD 1227R
Policy No.	DMPCSN1131081807	Coverage (\$)	0.00
Claim No.	SNM19D201013	Excess (\$)	0.00
Assign From		Assign Date	04/03/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I30	c.c	1582
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	TMAD281UVHJ127856	Colour	SILVER
Odometer	174153	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	MAXXIS	6 mm
L/H Front Tyre	195/65 R15	MAXXIS	6 mm
R/H Rear Tyre	195/65 R15	MAXXIS	6 mm
L/H Rear Tyre	195/65 R15	MAXXIS	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/02/2019	Inspection Date	04/03/2019
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1227R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	EMBLEM I30	NECESSARY	27.80	27.80
1	EMBLEM CRDI	NECESSARY	29.40	29.40
1	EMBLEM HYUNDAI	NOT NECESSARY	29.40	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	811.11	-
1	REAR BUMPER SPONGE	SERVICEABLE	79.20	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	815.64	-
1	REAR BUMPER REINFORCEMENT CENTRE	SERVICEABLE	79.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20	SERVICEABLE	104.40	-
2	REAR BUMPER N/S & O/S REFLECTOR @\$107.50	SERVICEABLE	215.00	-
	LESS 20% DISCOUNT		-438.23	-11.44
			1,752.92	45.76
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	SET TAILGATE STICKERS (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			478.00	120.00
LABOUR				
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK - OUT ,STRAIGHTEN ,REPAIR,RESHAPE OF THE END PANEL,TAILGATE & TAILGATE LOWER GARNISH ,ETC.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		700.00	200.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE ,TAILGATE LOWER GARNISH.		700.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,600.00	560.00
GRAND TOTAL			3,830.92	725.76

Report Ref No. CC3/CTI19004053/K1jb3n2



RECOMMENDED COST OF REPAIRS			725.76
-----------------------------	--	--	--------

Report Ref No. CC3/CTI19004053/K1jb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.