

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

27-Feb-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1227 R

1 pc	Emblem I30 ✓	\$	27.80
1 pc	Emblem CRDI ✓	\$	29.40
1 pc	Emblem Hyundai X	\$	29.40
1 pc	Rear bumper X <i>Repair</i>	\$	811.11
1 pc	Rear bumper sponge X	\$	79.20
1 pc	Rear bumper reinforcement X	\$	815.64
1 pc	Rear bumper reinforcement centre X	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 X	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @\$107.50 ✓	\$	215.00
		\$	2,191.15
		Less 20%	\$ 438.23
		\$	1,752.92

S/NETT

1 set	Rear bumper clips X	\$	48.00
1 set	Reverse sensor X	\$	280.00
1 set	Tailgate stickers ✓	\$	100.00
Sundry		\$	50.00 20
To dismantle and replace reverse sensor and test system		\$	80.00 X
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, tailgate & tailgate lower garnish, etc		\$	700.00 200
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish		\$	700.00 360
To apply rustproofing on the repaired and replaced panels		\$	120.00 X
Total		\$	3,830.92

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka/ni 11/11/19
4/3/19 1640h
2 Reps.
PIP
After Repair photo