

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

4-Mar-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1181 M

1 pc	Bonnet grille	X		\$	385.00
1 pc	Support panel	X		\$	645.00
1 pc	Front bumper	/		\$	531.00
1 pc	Front bumper emblem	/		\$	44.00
1 pc	Front bumper centre grille	?		\$	174.00
1 pc	Front bumper lower stiffer	X n/s		\$	134.00
1 pc	Front bumper tow hook cover	/		\$	14.00
1 pc	Front bumper lip	/		\$	52.00
1 pc	Front bumper inner sponge	/		\$	110.00
1 pc	Front bumper reinforcement	X		\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00	n/s x o/s	/	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00	n/s x o/s	/	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	n/s x o/s	/	\$	32.00
1 pc	o/s headlamp	/		\$	1,028.00
1 pc	Front bumper o/s fog lamp cover	/		\$	66.00
1 pc	Front bumper o/s protector	/		\$	51.00
1 pc	Engine under cover- Front	?		\$	44.00
1 pc	Engine under cover- n/s	?		\$	174.00
1 pc	Engine under cover- o/s	?		\$	144.00
1 pc	Washer tank motor	?		\$	48.00
1 pc	Washer tank	?		\$	47.00
1 pc	Front o/s fender	/		\$	384.00
1 pc	Front o/s fender inner shield	/		\$	120.00
1 pc	Front o/s wheel cover	X		\$	116.00
				\$	4,735.00
				Less 10%	\$ 473.50
					\$ 4,261.50

S/NETT

1 pc	Front no. plate with casing	X		\$	50.00
1 pc	Front bumper clips	/		\$	48.00
1 pc	Front o/s head lamp lower clip	/		\$	6.00
1 pc	Front o/s head lamp side clip	/		\$	3.00
1 pc	Front o/s fender sticker	X		\$	30.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1181 M

Sundry	\$	50.00 20
Towing Fee	\$	50.00 /
To check for wiring and to focus head lamps	\$	80.00 20
To top up aircon gas	\$	120.00 X
To do wheel alignment	\$	80.00 X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the bonnet, etc.	\$	900.00 600
To putty and spray painting on front bumper, bonnet, front o/s fender, bonnet grille.	\$	900.00 540
To apply rustproofing on the repaired and replaced panels.	\$	200.00 50
	\$	<u>6,958.50</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalish 100K
 M 4/3/19 1700 hrs.
 4 Days
 4/5
 After Repair photo

LKK Auto Tuning & Repairs

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

S. No. 123

Date: