

ASS. REC. BY:

REF:

CS/CT119004057/Ksd3n2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

05/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SJS 3484K

Insured:

SLM 4217E

at Workshop m/s

CHUAN HO

Tel:

9069 1985

of

SIM

Policy No:

Claim No:

DMPPHQ 18 - 005537

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

LWP1

11/3/19 after 12pm

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle - IN / OUT

Date/Time

Action/Instruction (

) Estimate

SJS 3484K x

SLM 4217E x

REF:

C71

CAYMAN

ASSIGNMENT

From:

Date:

11/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

STS 3454K

at Workshop m/s

Chuan Ho Auto

of

160 s/m Drive #07-09 s/m Drive

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

89800.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WPI

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

STS 3454K

Yr Regn:

08 / 09

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Mit Lanza GLX

1586

Colour:

White

A/C:

Insured / Std / Nil / NA

Sp Reading:

159356

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

JMYSTCS3494008037

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ Std A/Rim / ☐ STD A/Rim or

Tyre Size:

F:

R:

195/50R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

16/12/18

D.O.I.

11/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 15

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/3 11:15 8:22 am email & call
(1st 2413.12 Red - 52%)

RECEIVED 14 MAR 2019

Date/Time, File Pass to?

14/03/19

1)

Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.F. (\$)

2,200/- 1/5

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

1) 1000.00

2) 1000.00

3) 1000.00

4) 1000.00

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Week-end (\$)

220

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 5 March 2019 9:35 AM
To: assignments
Subject: FW: SJS 3454 K / SLM 4217 E

11/3/19 after 12pm

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 5 March 2019 9:32 AM
To: CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: SJS 3454 K / SLM 4217 E

OUT

Without Prejudice

Dear Sir,

We pri. Pls provide all relevant information.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: CHUAN HO AUTO SERVICE [<mailto:chuanhoautoservice@gmail.com>]

Sent: Tuesday, 5 March, 2019 9:30 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Fwd: SJS 3454 K / SLM 4217 E

Hi,

I would like to arrange for survey.

Please let us know which survey firm you'll be appointing.

Thank you.

Regards,

Sharin

CHUAN HO AUTO SERVICE

160 SIN MING DRIVE, #07-09 SIN MING DRIVE (S) 575722

Hp: 9069 1985

----- Forwarded message -----

From: **Irene Tay** <irene.tay@sg.cntaiping.com>

Date: Wed, Feb 20, 2019 at 10:53 AM

Subject: RE: SJS 3454 K / SLM 4217 E

To: CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com>

WITHOUT PREJUDICE

Dear Sir/Mdm,

Liability is down on our insured.

We are prepared to do a direct settlement with you.

Thank you.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: CHUAN HO AUTO SERVICE [mailto:chuanhoautoservice@gmail.com]

Sent: Wednesday, 20 February, 2019 10:51 AM

To: Irene Tay <irene.tay@sg.cntaiping.com>

Subject: Fwd: SJS 3454 K / SLM 4217 E

Hi Irene,

Please let us know liability for this case.

Thank you.

Regards,

Sharin

CHUAN HO AUTO SERVICE

160 SIN MING DRIVE, #07-09 SIN MING DRIVE (S) 575722

Hp: 9069 1985

----- Forwarded message -----

From: **CHUAN HO AUTO SERVICE** <chuanhoautoservice@gmail.com>

Date: Mon, Feb 18, 2019 at 4:16 PM

Subject: Fwd: SJS 3454 K / SLM 4217 E

To: <claimsdept@sg.cntaiping.com>, <irene.tay@sg.cntaiping.com>

Hi Irene,

Any updates on this?

Please do keep us posted as it has been a few months to check Liability,

Thank you.

Regards,

Sharin

CHUAN HO AUTO SERVICE

160 SIN MING DRIVE, #07-09 SIN MING DRIVE (S) 575722

Hp: 9069 1985

----- Forwarded message -----

From: **CHUAN HO AUTO SERVICE** <chuanhoautoservice@gmail.com>

Date: Mon, Jan 28, 2019 at 1:00 PM

Subject: Fwd: SJS 3454 K / SLM 4217 E

To: <irene.tay@sg.cntaiping.com>

Cc: <claimsdept@sg.cntaiping.com>

Hi Irene,

Any updates on this case?

Thank you.

Regards,

Sharin

CHUAN HO AUTO SERVICE

160 SIN MING DRIVE, #07-09 SIN MING DRIVE (S) 575722

Hp: 9069 1985

----- Forwarded message -----

From: **CHUAN HO AUTO SERVICE** <chuanhoautoservice@gmail.com>

Date: Thu, Jan 17, 2019 at 2:21 PM

Subject: Fwd: SJS 3454 K / SLM 4217 E

To: <irene.tay@sg.cntaiping.com>

Hi Irene,

Please refer to attached.

Thank you.

Regards,

Sharin

CHUAN HO AUTO SERVICE

160 SIN MING DRIVE, #07-09 SIN MING DRIVE (S) 575722

Hp: 9069 1985

----- Forwarded message -----

From: **CHUAN HO AUTO SERVICE** <chuanhoautoservice@gmail.com>

Date: Wed, Dec 19, 2018 at 9:49 AM
Subject: SJS 3454 K / SLM 4217 E
To: <claimsdept@sg.cntaiping.com>

To : Officer In Charge,

Please refer to attached for New Claim.

We would like to propose Direct Settlement.

Please check for us the liability before we proceed with repair.

Thank you.

Regards,

Sharin

CHUAN HO AUTO SERVICE

160 SIN MING DRIVE, #07-09 SIN MING DRIVE (S) 575722

Hp: 9069 1985

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5679D

Vehicle Details

Vehicle No.: SJS3454K
Vehicle to be Exported: No
Intended Deregistration Date: 12 Mar 2019
Vehicle Make: MITSUBISHI
Vehicle Model: LANCER 1.6 CVT SPORTS GLX AIRBAG 2WD 4DR
Primary Colour: White
Manufacturing Year: 2009
Engine No.: 4C18KC7791
Chassis No.: JMYSTCS3A9U006037
Maximum Power Output: 79.0 kW (105 bhp)
Open Market Value: \$13,982.00
Original Registration Date: 12 Aug 2009
First Registration Date: 12 Aug 2009
Transfer Count: 0
Actual ARF Paid: \$13,982.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 11 Aug 2019
PARF Rebate Amount: \$6,991.00

Intended COE Rebate Details

COE Expiry Date: 11 Aug 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$13,658.00
COE Rebate Amount: \$565.00
Total Rebate Amount: \$7,556.00

The information contained herein is correct as at 12 Mar 2019

OK

CHUAN HO AUTO SERVICE
SIN MING AUTO CITY
160 SIN MING DRIVE #07-09
SINGAPORE 575722

Not Withheld
61 Day 82200k
Putting After Paint
4 days

ESTIMATE : SJS 3454 K

Vehicle & Document Information

Date: 19/12/2018

Vehicle No: SJS 3454 K

Make/Model: MITSUBISHI LANCER

S/N	Description	Qty	Repairer's Est	Revised Est
1	FRONT BUMPER <i>681.00</i>	1	\$ 980.00	<i>Bz</i> 980.00 ✓
2	HEADLAMP RH <i>586</i>	1	\$ 655.00	<i>W</i> 655.00 ✓
3	FRONT GRILLE BASE	1	\$ 165.00	<i>cm</i> 165.00 ✓
4	FRONT GRILLE NET RH	1	\$ 120.00	<i>h</i> 120.00 X
5	FRONT GRILLE NET LH	1	\$ 120.00	<i>h</i> 120.00 X
6	FRONT BUMPER BRACKET	1	\$ 80.00	<i>n</i> 80.00 X
7	FOG LAMP COVER LH	1	\$ 40.00	<i>h</i> 40.00 X
8	FOG LAMP LH	1	\$ 650.00	<i>h</i> 650.00 X
9	BONNET	1	\$ 780.00	<i>n</i> 780.00 X
10	FENDER RH <i>490.00</i>	1	\$ 680.00	<i>Bu</i> 680.00 ✓
11	FRONT BUMPER LOWER GRILLE	1	\$ 88.00	<i>h</i> 88.00 X
12	FRONT BUMPER LOWER GRILLE GARNISH RH	1	\$ 60.00	<i>h</i> 60.00 X
13	FRONT BUMPER LOWER GRILLE GARNISH LH	1	\$ 60.00	<i>h</i> 60.00 X
14	FRONT PANEL	1	\$ 780.00	<i>n</i> 780.00 X

Parts Total : \$ 5,258.00

-20% *108* \$ 1,051.60

Total : \$ 4,206.40

1	ANTIRUST PROOFING, GALVANISING SPOT WIELD	\$ 300 100.00
2	TO CHECK LIGHTING, WIRING & FUSES	\$ 200 180.00
3	LABOUR TO DISMANTLE PARTS AND REPLACE	\$ 450 580.00
4	TO PUTTY, PRIMER AND RE-SPRAY AFFECTED PARTS	\$ 600 800.00

Labour Total : \$ 1,560.00

6392.20

TOTAL :	\$ 5,766.40
-20%	\$ 1,153.28
GRAND TOTAL :	\$ 4,613.12
LUMP SUM :	\$ 4,600.00

CHUAN HO AUTO SERVICE



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119004057/KSD3N2

Date: 19/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SJS3454K	Insured Vehicle No :	SLM4217E
Date of Loss:	16/12/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS3454K	Engine No:	4G18KC7791
Make & Model:	MITSUBISHI LANCER, 1.6 CVT SPORTS GLX (A)	Chassis No:	JMYSTCS3A9U006037
Reg. Date:	12/08/2009 (Man. Year: 2009)	Odometer:	159356 km
Colour:	White		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50R15	Rear Tyre Size:	195/50R15
Front Left Side:	Toyo 8 mm	Rear Left Side:	Toyo 8 mm
Front Right Side:	Toyo 8 mm	Rear Right Side:	Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,732.20	1,729.80	3,002.40	63.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,100.00	560.00	33.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,392.20	2,829.80	3,562.40	55.73
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	6,392.20	2,200.00	4,192.20	65.58

INSPECTION

Date of Assignment:	14/03/2019	
Date Inspected:	11/03/2019	Inspected At:
		Chuan Ho Auto Service (HQ)
		Blk 11 # 01-85, Sector B Sin Ming Ind Estate
		Singapore 575655

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Mar 2019)
Parts:	143	mitsubishi LANCER 1.6 CVT SPORTS GLX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS3454K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	980.00 FL	*681.00 FL
2	1		*HEADLAMP RH	Cut	655.00 FL	*586.00 FL
3	1		*FRONT GRILLE BASE	Cracked	165.00 FL	*165.00 FL
4	1		*FRONT GRILLE NET RH	Serviceable	120.00 FL	*- FL
5	1		*FRONT GRILLE NET LH	Serviceable	120.00 FL	*- FL
6	1		*FRONT BUMPER BRACKET	Repair	80.00 FL	*- FL
7	1		*FOG LAMP COVER LH	Serviceable	40.00 FL	*- FL
8	1		*FOG LAMP LH	Serviceable	650.00 FL	*- FL
9	1		*BONNET	Repair	780.00 FL	*- FL
10	1		*FENDER RH	Buckled	680.00 FL	*490.00 FL
11	1		*FRONT BUMPER LOWER GRILLE	Serviceable	88.00 FL	*- FL
12	1		*FRONT BUMPER LOWER GRILLE GARNISH RH	Serviceable	60.00 FL	*- FL
13	1		*FRONT BUMPER LOWER GRILLE GARNISH LH	Serviceable	60.00 FL	*- FL
14	1		*FRONT PANEL	Repair	780.00 FL	*- FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	5,258.00	1,922.00
- List Item Discount on L Items 10.00/10.00% (S\$)	525.80	192.20
Total Parts (S\$)	4,732.20	1,729.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTIRUST PROOFING,GALVANISING SPOT WIELD	New	100.00	30.00
2	TO CHECK LIGHTING,WIRING & FUSES	New	180.00	20.00
3	LABOUR TO DISMANTLE PARTS AND REPLACE	New	580.00	450.00
4	TO PUTTY,PRIMER AND RE-SPRAY AFFECTED PARTS	New	800.00	600.00
Gross Labour Cost (\$\$)			1,660.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >