

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 8555Y

DATE 2/3/2019 10:38

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (RH) ✓			\$ 2,201.10
	Rocker Panel Outer Garnish (RH) <i>x repair</i>			\$ 341.40
	<i>Front Door (RH) x repair</i>			
	SUB TOTAL			\$ 2,542.50
	LESS 20% <i>75%</i>			\$ 508.50
	DISCOUNTED TOTAL			\$ 2,034.00
	Rear Door Advertisement Logo (RH) ✓			\$ 100.00
	Rear Door Comfortdelgro & Apps Sticker (RH) ✓			\$ 80.00
	Front Door Coloured Comfort Logo (RH) ✓			\$ 75.00
	Front Door Advertisement Logo (RH) ✓			\$ 100.00
				\$ 355.00
	Labour Charge			
	Panel Beating			\$ 400.00 <i>200</i>
	Spray Painting Charge			\$ 250.00 <i>600</i>
	Wiring Charge			\$ 50.00 <i>x</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	TOTAL LABOUR			\$ 1,250.00
	ESTIMATE TOTAL			\$ 3,639.00

Kahm Klay

4/3/19 1015h

3 Reps

PIP

Before Paint photo

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.