

ASS. REC. BY:

REF: C/CTI19004061/Kqd3n2

Special Instruction:

Surveyor

ASSIGNMENT (Office)From (Person): Chong Boon Sen of _____ Date/Time: 5/3/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGW 4682B Insured: XE 4258Lat Workshop m/s Lye Designs Tel: _____of 10 Ang Mo Kio rd Park 2A #04-04 Amk AutopointPolicy No: DMCVSN18276118000 Claim No: SNM19D201039C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 2/3/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SGW 4682B / XE 4258L NA/CTI19003919/24 D.O.A. : 02/3/19
	LI Lnp 8555d email B confirmed (Red \$466411, 46%)

ASS. REC. BY:

REF: C721

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGW 40823 Yr Regn: 07, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 523i c.c. 2497

Colour:

M. Blue A/C: Insured / Std / NI / NA

Sp. Reading

8753P T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA NU12020 CN 23547

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: 225/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

4 mm

L/Bal.

7 mm

L/Bal.

4 mm

D.O.A.

2/3/19

D.O.I.

5/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

cls body

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 30 APR 2019

Date/Time, File Pass to?

☐

: Prel. Report

1) 30/4 11:45 AM

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Fixings

Others

TOTAL

220

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format:

MER-TP

Lump Sum / I.B.I. (\$)

5550

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 4 March 2019 5:43 PM
To: assignments
Subject: FW: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SGW 4682 B AND XE 4258 L ON 2 MARCH 2019 ALONG PIE EXIT 20B AT ABOUT 1836 HOURS
Attachments: image005.emz; image007.emz

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Kenneth

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 4 March 2019 5:40 PM
To: Elaine Toh <Elainetoh@visionlawllc.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SGW 4682 B AND XE 4258 L ON 2 MARCH 2019 ALONG PIE EXIT 20B AT ABOUT 1836 HOURS

Without Prejudice
Save as to costs

Dear Elaine ,

We use LKK.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]

Sent: Monday, 4 March, 2019 5:28 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: RE: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SGW 4682 B AND XE 4258 L ON 2 MARCH 2019 ALONG PIE EXIT 20B AT ABOUT 1836 HOURS

Importance: High

Our Ref: SGW 4682 B (et)
WITHOUT PREJUDICE

Dear Boon Sen,

We refer to your email of even date informing that you wish to conduct a pre-repair survey and to your List of Surveyors.

Our client confirm appointment of ADRIAN LING as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : Lye Designs
10 Ang Mo Kio Industrial Park 2A
#04-04 AMK Autopoint
Singapore 568047
Contact: Siew Hoon @ 64833353 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802



FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

Appointed surveyor
(Name & Signature)

Date & Time of Inspection :

cc: SGW 4682 B – By fax: 64842457 only

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: Monday, 4 March, 2019 5:11 PM

To: Elaine Toh

Subject: RE: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SGW 4682 B AND XE 4258 L ON 2 MARCH 2019 ALONG PIE EXIT 20B AT ABOUT 1836 HOURS

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]

Sent: Monday, 4 March, 2019 4:50 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>

Subject: PRE REPAIR SURVEY --- ACCIDENT INVOLVING SGW 4682 B AND XE 4258 L ON 2 MARCH 2019 ALONG PIE EXIT 20B AT ABOUT 1836 HOURS

Importance: High

Our Ref: SGW 4682 B (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by **FOO HAY KHIM** to notify you of a road traffic accident on 2 March 2019 at about 1836 hours along PIE exit 20B involving our client's vehicle registration number SGW 4682 B and vehicle registration number XE 4258 L driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SGW 4682 B – By fax: 64842457 only

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAUTO)

From: Siew Hoon <siewhoon@lyedesigns.com.sg>
Sent: Thursday, 25 April 2019 3:14 PM
To: Kenneth Kong (LKKAUTO)
Cc: SUR
Subject: RE: SGW4982B ESTIMATE BILL > Finalise COR \$5550, 6 days

Hi Kenneth,

We agree to finalise per recommendation.

Shiau Chan, pls note.

Thank you.

Warm Regards

Siew Hoon

Lye Designs

10 Ang Mo Kio Industrial Park 2A

#04-04 AMK Autopoint

Singapore 568047

T : 6483 3353

F : 6484 2457

E : siewhoon@lyedesigns.com.sg

W : www.lyedesigns.com.sg

From: Kenneth Kong (LKKAUTO) [mailto:KennethKong@lkkauto.com]
Sent: Thursday, 28 March 2019 9:24 AM
To: Siew Hoon
Subject: RE: SGW4982B ESTIMATE BILL > Finalise COR \$5900, 6 days

Attach finalised for SGW 4682B.

From: Siew Hoon [mailto:siewhoon@lyedesigns.com.sg]
Sent: Wednesday, 27 March, 2019 11:56 AM
To: Kenneth Kong (LKKAUTO)
Subject: RE: SGW4982B ESTIMATE BILL > Finalise COR \$5900, 6 days
Importance: High

Hi Kenneth,

Would like to finalise this case.

Based on your markings,

Parts: $6222.54 - 622.25(10\%) = \5600.29

Labour : $30+50+1000+750 = \$1830$

Total : $\$5600.29+1830 = \$7430.29 - 20\% = \$5944.23$

To finalise at Lump Sum \$5900 COR and 6 days of repairs.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/03/2019 15:09
Date Of Accident	02/03/2019 18:35
Exact Location Of Accident	EXIT 20B LORNIE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGW4682B
Insured/Policyholder	
Name Of Registered Owner	FOO HAY KHIM
NRIC No	S1304023J
Email Address	WILFHK2121@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97817782
Alternative Phone No	OTHERS-97817782

Vehicle Particulars

Manufacturer	BMW
Model	523I-2.5 XL (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8-V0018360-MVA
Cover Note Number	16/07/2018 - 18/07/2019

Driver

Name of Driver	JOSEPH G BENEDICT
NRIC No	S8809621E
Date Of Birth	13/03/1988
Occupation	INDOOR
Date Of Driving Pass	10/10/2007
Driving Experience	11 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91835813
Fax Number	
Contact Number	
EEmail Address	JOSEPH.G.BENEDICT@GMAIL.COM

Address	BLK 231 BUKIT BATOK EAST AVE 5 #07-91
Postcode	650231
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SON-IN-LAW
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : FOO CA-MAY GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	YES

Details of Witness 1

Name	FOO CA-MAY, S9033421B
Phone Number	97111330
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE4258L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RATHINAN SUBRAMANIYAN
NRIC/Passport Number	032135633
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

VEHICLE NO.: SGW 46828
INSURER: OBE
DATE & TIME: 02/03/19 @ 1835

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

5.05 pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 040319 1500

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

Danah (AMK) 04/03/19

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Rathinan was driving a sand truck and the collision occurred along the slip road of Exit 208. It was right before a left bend when his vehicle knocked into my vehicle. The place of the scene was near plastic barricades. His vehicle was parallel to my vehicle when he first moved into my lane. I came to a halt and his vehicle came into contact with the right side of my vehicle. Evidently, all damages occurred on the right side of the vehicle due to the incoming impact from Rathinan's vehicle. The car's mirror folded forward on impact, shattering the mirror. There was no room for his vehicle to make the lane change and it was a reckless decision on his part. He admitted to his fault which is supported by audio recordings provided. He had not checked his blind spot and did not see my vehicle. Damages were found on the tyre, side doors and rear wheel fender.

Vehicle No: SGW4682B (QBE)
Date & Time: 02/03/19 @ 7:35

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 04/03/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SGS/MC Sketch Plan Form V2 () Claim Own Policy () Claim Third Party () Reporting Only
() Claim ODP at other workshop ()

LD Lye Designs

(Panel Beating, Repair, Servicing & General Claim)
10, AMK Autopoint, #04-04 Ang Mo Kio, Ind. Park 2A, Singapore 368047
TEL : 6483 3353 FAX : 6484 2457 Email: ldemail@singnet.com.sg
Reg No: 52806993D

ESTIMATE

Not Authored
11pm @ 555ch
Passing After Paint

Date : 5-Mar-19

To :

Owner : Foo Hay Khim
Vehicle Reg. No. : SGW4628B
Make/Model : BMW 523i XL
Chasis No. : WBANU12020CW23547
Year Mfg : 2007
Date of Accident : 2-Mar-19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6 days

ESTIMATE COST OF REPAIR TO "BMW 523i" " REG. NO. SGW4682B"

Qty	List Items	Amount \$
1	RHF Side Mirror } 1933.50	CM 1,124.44 ✓
1	RHF Side Mirror Glass	Bu 1,059.23 ✓
1	RHF Side Mirror Cover	na 192.93 ✓
1	RHF Fender 988-70	Ry 1,124.37 ✓
1	RHF Fender Garnish	su 207.85 ✗
16	RHF Fender Garnish Clips	na 7.00 112.00 ✗
1	RHF Fender Signal Lamp	su 83.19 ✗
1	RHF Door 1888	Ry 2,164.50 ✓
1	RHF Door Handle(Big)	na 114.42 ✓
2	RHF Door Handle(Small)	na 160.17 ✓
1	RHF Door Rubber	108.54 su na 219.08 508.54 ✓
1	RHF Door Outer Chrome Moulding	na 282.48 ✓
1	RHF Door Regulator	su 487.65 ✗
1	RHF Door Motor	su 427.80 ✗
1	RHF Sideskirt	su 538.28 ✗
Sub-total		7,260.12 8298.39
Less 10%		-776.01
Total List Items		6,984.11 7468.55

Labour Charges

To refocus, re-wire headlamp, brake lights, bumper beam & check wirings	80.00	301
To remove, refix RH side mirror	50.00	✓
To putty and re-spray paint of the affected areas	1,600.00	1000.00
Panel beating, cut, weld, remove & replacing above parts	1,500.00	750.00
Total Labour	3,230.00	

ESTIMATE PARTS & LABOUR GRAND TOTAL \$

10,214.11

10698.55

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19004061/KQD3N2

Date: 07/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18276118000	
Claimant Vehicle No :	SGW4682B	Insured Vehicle No :	XE4258L	
Date of Loss:	02/03/2019	Nature of Claim:	TP	Claim No: SNM19D201039C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGW4682B	Engine No:	72624025N52B25AE
Make & Model:	BMW 523i, 2.5 XL (A)	Chassis No:	WBANU12020CW23547
Reg. Date:	19/07/2007 (Man. Year: 2007)	Odometer:	87539 km
Colour:	Metallic Blue		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,468.55	5,113.72	2,354.83	31.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,830.00	1,400.00	43.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,698.55	6,943.72	3,754.83	35.10
Approved Total (Overridden) (S\$)		5,550.00		
Nett Amount (S\$)	10,698.55	5,550.00	5,148.55	48.12

INSPECTION

Date of Assignment:	26/04/2019	
Date Inspected:	05/03/2019	Inspected At: Lye Designs (HQ) 10 Amk Autopoint #04-04, Ang Mo Kio Industrial Park 2A Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2019)
Parts: 143	BMW 523I 2.5 XL (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGW4682B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHF SIDE MIRROR}	Cracked	1,124.44 FL	*1,933.50 FL
2	1		*RHF SIDE MIRROR GLASS}	Broken	1,059.23 FL	*- FL
3	1		*RHF SIDE MIRROR COVER	Dented	192.93 FL	*192.93 FL
4	1		*RHF FENDER	Bent	1,124.37 FL	*988.70 FL
5	1		*RHF FENDER GARNISH	Serviceable	207.85 FL	*- FL
6	16		*RHF FENDER GARNISH CLIPS	Not Necessary	112.00 FL	*- FL
7	1		*RHF FENDER SIGNAL LAMP	Serviceable	83.19 FL	*- FL
8	1		*RHF DOOR	Bent	2,164.50 FL	*1,888.00 FL
9	1		*RHF DOOR HANDLE (BIG)	Dented	114.42 FL	*114.42 FL
10	1		*RHF DOOR HANDLE (SMALL)	Dented	160.17 FL	*160.17 FL
			(2 pcs)			
11	1		*RHF DOOR OUTER CHROME MOULDING	Necessary	282.48 FL	*282.48 FL
12	1		*RHF DOOR REGULATOR	Serviceable	487.65 FL	*- FL
13	1		*RHF DOOR MOTOR	Serviceable	427.80 FL	*- FL
14	1		*RHF SIDESKIRT	Serviceable	538.28 FL	*- FL
15	1		*RHF DOOR RUBBER (50%)	Necessary	197.17 FS	*109.54 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,276.48	5,669.74
- List Item Discount on L Items 10.00/10.00% (S\$)	807.93	556.02
Total Parts (S\$)	7,468.55	5,113.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REFOCUS, RE-WIRE HEADLAMP, BRAKE LIGHTS, BUMPER BEAM & CHECK WIRINGS.	New	80.00	30.00
2	TO REMOVE, REFIX RH SIDE MIRROR.	New	50.00	50.00
3	TO PUTTY AND RE-SPRAY PAINT OF THE AFFECTED AREAS.	New	1,600.00	1,000.00
4	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS.	New	1,500.00	750.00
Gross Labour Cost (S\$)			3,230.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >