

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Nett 7k

SIM MAY MAY MARILYN
BLK535 BUKIT PANJANG RING ROAD
#21-817
S 670535

TP ER
Cedlia

Date :20.04.2019
Vehicle no :SJD 6214 X
Make/Model :TOYOTA VIOS
Accident date :28.02.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>NE NEW</i>	1	\$ 87.2 X
2	Rear boot lid <i>Distorted</i>	1	\$ 642.6 ✓
3	Rear boot lid hinges @ \$62.70 <i>Best</i>	2	\$ 125.4 ✓
4	rear boot lid upper lock <i>Distorted</i>	1	\$ 112.2 ✓
5	Rear boot lid lower lock	1	\$ 22.1 ✓
6	Rear boot lid top spoiler <i>NE NEW</i>	1	\$ 800 X
7	Rear boot lid handle <i>Distorted</i>	1	\$ 150.9 ✓
8	Rear boot lid centre emblem	1	\$ 55.9 ✓
9	Rear boot lid VIOS emblem <i>NEC</i>	1	\$ 51.2 ✓
10	Rear boot lid SPORT emblem	1	\$ 40.3 ✓
11	rear boot lid E emblem	1	\$ 40.3 ✓
12	Rear boot lid weather strip <i>ut</i>	1	\$ 205.3 ✓
13	Rear number plate lamp @ \$69.20 <i>NE NEW</i>	2	\$ 138.4 X
14	Rear end panel <i>Distorted</i>	1	\$ 668.9 ✓
15	Rear end panel inner top garnish <i>Distorted</i>	1	\$ 234.9 ✓
16	Rear lamp @ \$450.90 <i>crushed</i>	2	\$ 901.8 ✓
17	Rear lamp housing @ \$122.80 <i>crushed</i>	2	\$ 245.6 ✓
18	Rear lamp rubber @ \$28.60 <i>NE</i>	2	\$ 57.2 ✓
19	Rear bumper <i>Distorted</i>	1	\$ 475.1 ✓
20	Rear bumper side holder @ \$108.40 <i>NE</i>	2	\$ 216.7 ✓
21	Rear bumper bracket @ \$74.20 <i>Best</i>	2	\$ 148.4 ✓
22	Rear bumper clips (1set) <i>NE</i>	1	\$ 50.30 ✓
23	Rear bumper reflector @ \$96.50 <i>crushed</i>	2	\$ 193 ✓
24	Rear fender @ \$989.60 <i>Repair</i>	1	\$ 989.6 X
25	Rear fender inner trim @ \$261.70 <i>RH torn</i>	2	\$ 523.4 X
26	Rear fender inner shield @ \$53.20 <i>torn</i>	2	\$ 106.4 ✓
27	Rear spare tyre top board <i>torn</i>	1	\$ 133.8 ✓
28	Rear spare tyre well <i>Repair</i>	1	\$ 741 X
29	Rear spare tyre well insulation @ \$321.30 <i>NE NEW</i>	3	\$ 963.9 X
30	Rear spare tyre well side sponge @ \$154.90 <i>Distorted</i>	2	\$ 309.8 ✓
31	Rear spare tyre well centre sponge <i>torn</i>	1	\$ 154.9 ✓
32	Rear exhaust pipe <i>NE NEW</i>	1	\$ 654.5 X

10240.7

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SIM MAY MAY MARILYN
BLK535 BUKIT PANJANG RING ROAD
#21-817
S 670535

Date :20.04.2019
Vehicle no :SJD 6214 X
Make/Model :TOYOTA VIOS
Accident date :28.02.2019

No	Description	Qty	Amount (\$S)
33	Rear exhaust pipe mounting	1	\$ 31.7
34	Rear exhaust pipe chrome	1	\$ 86.7
			\$ 10359.1
		Less 25% Disc	\$ 2589.8
		Total	\$ 7769.3

Special Nett Items

1	Rear boot lid camera	1	\$ 800
2	Rear number plate	1	\$ 50
3	rear number plate holder	1	\$ 50
4	Rear bumper reverse sensor	1	\$ 380
		Total	\$ 1280

Labour Cost

1	To supply rear windscreen sealant	\$ 50
2	To supply rear end panel inner sealant	\$ 200
3	Remove & reinstall rear windscreen	\$ 150
4	Remove & reinstall cushion & roof lining	\$ 200
5	Remove & reinstall petrol tank	\$ 150
6	Remove & reinstall reverse sensor	\$ 150
7	Remove & reinstall exhaust pipe	\$ 150
8	Remove & reinstall camera	\$ 100
9	Remove, replace & repair consistent to the accident	\$ 2800
10	Respray painting	\$ 1800
11	Tuff kote	\$ 150
	Total	\$ 5900

Grand total \$ 14949.3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 7526.85

h/s 6K

08Days

6K 08Days