

22/03/2002

ASS. REC. BY:

REF: CS/CT/119004070/Mgd322

Special Instruction:

Survivor:

ASSIGNMENT (Office)From (Person): Chong Boon Senof CAIDate/Time: 5/3/2019 09:42

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SP 9902L

Insured:

at Workshop m/s Jin Auto Service.Tel: 62898126of Blk 14 Peta Lane 10, #01-410/412Policy No: DmpCSN1824121500

Claim No:

Sum Insured:

Excess:

\$0

Make of Veh:

D.O.A. 28/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

06/3/19 @ 1:34pm revert to Chong Boon Sen via Meimen.

7/3/19 @ 10:49 and revert on adjust auditex.

7/3 @ 11:18am authorise repair by Boon Sen

7/3 @ 12:41pm inform Jouis via email. authorise repair excess \$110

ASS. REC. BY: Marcus

REF:

C11

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLP9902L
Tm Aut.

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

SSK.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS3148H

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLP9902L

Yr Regn:

2 ofType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Mer Benz C200 c.c. 1796

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

121128

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2040412A102616Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

28/2/19

D.O.I.

5/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 45302 19-2-201813/3/194/5 \$1700 confund

The repair cost will be US \$1350 (Red \$1614.28, 54%).

RECEIVED 13 MAR 2019

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

41) 13/3 11:00☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

Survey Fee:

220

Transportation:

) S + RS. SI

) Photos

) Others

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

220

Report Format :

MER-00

Lump Sum / I.B.I: (\$

1350)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Mar 2019 12:04 Sendback Est	04 Mar 2019 10:47 S\$2,964.28	05 Mar 2019 09:42 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	HENG LEY KANG, ID: S6873148H		
Vehicle Reg. No.:	SLP9902L	Date of Loss:	28/02/2019 00:00 - :59 [132 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No.:	DMPCSN1824121800 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/03/2019]		
Driver/Custodian:	HENG LEY KANG (/ Male) , NRIC: S6873148H Email:		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 7 March 2019 12:41 PM
To: jouis@jinauto.com.sg
Cc: SUR
Subject: SLP 9902L / OD CHINA TAI PING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLP 9902L(Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SLP9902L (SLP9902L)

OD

Feb 28 2019 12:00AM

[HENG LEY KANG]

Jin Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 07/03/2019 11:18 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$2119.28) - SLP9902L - Claim Handler: Chong Boon Sen

Approved:2119.28:authorise repair at \$2119.28

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 07 Mar 2019

Preliminary Advice

Vehicle No	: SLP9902L	Accident Date	: 28/02/2019
Make	: MERCEDES-BENZ C200 KOMPRESSOR	Policy No.	: DMPCSN1824121800
Assignment Date	: 05/03/2019	Excess	: S\$0.00
Date of Inspection	: 05/03/2019	Est. Duration of Repair	: 4.00
Inspection At	: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412 SINGAPORE 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,964.28
Revised Amount	:S\$	1,719.48
Check Items (Estimated)	:S\$	399.80
Total	:S\$	2,119.28

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	45,302.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,698.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 06 Mar 2019

Preliminary Advice

Vehicle No	: SLP9902L	Accident Date	: 28/02/2019
Make	: MERCEDES-BENZ C200 KOMPRESSOR	Policy No.	: DMPCSN1824121800
Assignment Date	: 05/03/2019	Excess	: S\$0.00
Date of Inspection	: 05/03/2019	Est. Duration of Repair	: 4.00
Inspection At	: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412 SINGAPORE 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,964.28
Revised Amount	:S\$	1,517.88
Check Items (Estimated)	:S\$	341.00
Total	:S\$	1,858.88

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	45,302.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,698.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 3148H

Vehicle Details

Vehicle No.: SLP9902L

Vehicle to be Exported: No

Intended Deregistration Date: 05 Mar 2019

Vehicle Make: MERCEDES BENZ

Vehicle Model: C 200 KOMPRESSOR

Primary Colour: Black

Manufacturing Year: 2007

Engine No.: 27195031005537

Chassis No.: WDD2040412A102616

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value: \$42,793.00

Original Registration Date: 20 Feb 2008

First Registration Date: 20 Feb 2008

Transfer Count: 2

Actual ARF Paid: \$47,073.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 19 Feb 2028

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

PQP Paid: \$50,578.00

COE Rebate Amount: \$45,302.00

Total Rebate Amount: \$45,302.00

The information contained herein is correct as at 05 Mar 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

▪ Illegal floor found in industrial building

▪ Nice / Rare Vehicle Registration Number

▪ Makan in Thailand

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



2.68%P.A Low Interest@Gv Finance. \$0 Admin Fees. \$2500 Downpayment Monthly \$638

GV Credit Pte Ltd StarAd

Think One Automobile

NEW & USED COMMERCIAL VEHICLES



Browse by Category

Sort by Date Posted

20 results/page

11 vehicles

Mercedes-Benz c200

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mercedes-Benz c200		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Mercedes-Benz	C-Class C200 (COE till 04/2021)	\$14,800	\$6,860 /yr	25-Apr-1997	1,998 cc	-	Luxury	Available
Good Running Condition. Selling As It Is. Silver Paintwork With Beige Interior. Own A Piece Of Classic Now.									
Auto Zoom Enterprise Pte Ltd									
Posted: 03-Mar-2019 Tags: 1997 Mercedes-Benz C200, 1997 mercedes-benz c200, Mercedes-Benz C200, mercedes-benz c200, Mercedes-Benz, C200, c200, Used Mercedes-Benz									
	Mercedes-Benz	C-Class C200K Avantgarde (New 10-yr COE)	\$65,800	\$6,570 /yr	23-Feb-2009	1,796 cc	-	Luxury	Available
Well Kept Condition. Excellent Condition Interior And Exterior. Low Mileage Done. View To Believe. In House/Bank Loan Available, Call Now For Viewing.									
Posted: 02-Mar-2019 Tags: 2009 Mercedes-Benz C200K, 2009 mercedes-benz c200k, Mercedes-Benz C200K, mercedes-benz c200k, Mercedes-Benz, C200K, c200k, Used Mercedes-Benz									
	Mercedes-Benz	C-Class C200K Avantgarde (New 10-yr COE)	\$62,800	\$6,270 /yr	23-Jan-2009	1,796 cc	-	Luxury	Available
Full Loan Available, New Leather, Ready Stock!									
Posted: 01-Mar-2019 Tags: 2009 Mercedes-Benz C200K, 2009 mercedes-benz c200k, Mercedes-Benz C200K, mercedes-benz c200k, Mercedes-Benz, C200K, c200k, Used Mercedes-Benz									
	Mercedes-Benz	C-Class C200K (New 5-yr COE)	\$47,800	\$9,550 /yr	23-Dec-2008	1,796 cc	113,216 km	Luxury	Available
High Loan With 3.98% - 4.25% Lowest Interest Guaranteed. Extremely Well Maintained By Owner! Sporty Yet Fuel Efficient! Quiet And Smooth Engine And Gearbox! 1 To 1 Exchange With High Trade In Value Av...									
Posted: 01-Mar-2019 Tags: 2008 Mercedes-Benz C200K, 2008 mercedes-benz c200k, Mercedes-Benz C200K, mercedes-benz c200k, Mercedes-Benz, C200K, c200k, Used Mercedes-Benz									
<div>GET YOUR COE RENEWAL LOAN</div>	Is your COE expiring? Let us help you renew it!								
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	Mercedes-Benz	C-Class C200K (COE till 01/2024)	\$47,800	\$9,860 /yr	08-Jan-2009	1,796 cc	122,741 km	Luxury	Available
Panoramic Roof Unit! Full View Of The Sky From Rear To Front! High Loan Available With The Lowest Interest Guaranteed For A COE Unit, Be Surprised. Extremely Well Maintained By Owner! Sporty Yet Fuel ...									
Posted: 01-Mar-2019 Tags: 2009 Mercedes-Benz C200K, 2009 mercedes-benz c200k, Mercedes-Benz C200K, mercedes-benz c200k, Mercedes-Benz, C200K, c200k, Used Mercedes-Benz									
	Mercedes-Benz	C-Class C200K (New 10-yr COE)	\$71,800	\$7,170 /yr	22-Jan-2009	1,796 cc	111,000 km	Luxury	Available
AA Trust Certified Quality 1 Owner Vehicle! Well Maintained By Previous Owner! The Perfect Executive Sedan That Suits Every And Any Occasion! Unit Comes With Diamond Grille Facelift! Powerful Engine A...									
AA Trust Automotive									
<div>Compare</div>									

https://www.sgcarmart.com/used_cars/listing.php?RGD=10&MOD=Mercedes-Benz c200&RPG=20&V... 05-Mar-19

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Claim Reference: Dmpcsn1824121800
Assessment number: SLP 9902L(MercedesC200
Version: 1810
Date calculated: 03/04/2019 10:08 AM

Full Report
Registration: SLP9902L
Printed: 04/03/2019 10:09 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	JOUIS SEOW	Currency:	SGD
Claim Reference:	Dmpcsn1824121800	Date of Incident:	2019-02-28
Estimated Repair Time:	14	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	C-CLASS (W204)
Sub Model:	C 200 COMPRESSOR
Model Sheet Number:	03 04 01
Registration:	SLP9902L
VIN number:	WDD2040412A102616
Odometer:	121128

Model Specs

FR A082./F078./R007.	MODEL 2008	RAIN SENSOR	DIPPING MIRROR
FOLDING DOOR MIRRORS	AUDIO SYSTEM 20 CD	LEATHER UPHOLSTERY	ALU DESIGN PARTS
EQUIPMENT AVANTGARDE	DRIVER SEAT MEMORY	L/F SEAT WITH MEMORY	STRG WHEEL LEATHER
LEATHER STRG WHEEL	H/DUTY ALTERNATOR	ENGINE PROTECTION	AUTO GEARBOX 5 SPEED
PARAMETER STEERING	CRUISE CONTROL	TYRES 225/45 WR 17	WHEELS 7.5J X 17 ALU
SPARE WHEEL	PARKTRONIC SYSTEM	RIGHT HAND DRIVE	TWO COAT METALLIC
CLEAR COAT HARD			

*Not Adherent
Mark
try L/S.
Excess?
5/3/19
4 day.*

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Claim Reference: Dmpcsn1824121800
Assessment number: SLP 9902L(MercedesC200
Version: 1810
Date calculated: 03/04/2019 10:08 AM

Full Report
Registration: SLP9902L
Printed: 04/03/2019 10:09 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
88-3956 01	RENEW R/FR WING INCLUDES: PARTITION PANEL R CPL REMOVE-- REFIT R/SIDE MEMBER TRIM DETACH/ATTACH		10.0	42.00
72-1515 01	RENEW R/F DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		33.0	138.60
72-1682 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH LOWER MOULDING)		1.0	4.20
72-2692 01	RENEW R/F DOOR HINGE/S		14.0	58.80
72-1691 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH DOOR SPEAKERS)		2.0	8.40
54-7989 02	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		2.0	8.40

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Claim Reference: Dmpcsn1824121800
 Assessment number: SLP 9902L(MercedesC200
 Version: 1810
 Date calculated: 03/04/2019 10:08 AM

Full Report
 Registration: SLP9902L
 Printed: 04/03/2019 10:09 AM

Code	Description	WU	Price SGD
2238	R/INN A-PILLAR REINF REPAIR	50.0*	210.00
2248	R/INNER A-PILLAR REPAIR	40.0*	168.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		15.20	152.0
Total of Labour			638.40

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	R/F WING NEW PART PAINTING	9.0	
	RIGHT FRONT DOOR NEW PART PAINTING	15.0	

Paint Material Per Part

Code	Description	Price SGD
0742	R/F WING NEW PART PAINTING	14.45
1482	RIGHT FRONT DOOR NEW PART PAINTING	39.73

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		24.0	
Preparation Main Work Metal	0.90	9.0	37.80
Total	10 WU/h	3.30	138.60

Material Cost - Paint	Price SGD
New Part Painting	54.18
Material-constant Metal	18.10
Total	72.28

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0742	R/F WING	204 880 1418	R X		425.00
0786	R/F WING MOULDING	204 690 3262	Rec ✓		18.00
0812	R/F WING BADGE	204 817 2720	rec ✓		33.00

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Claim Reference: Dmpcsn1824121800
 Assessment number: SLP 9902L(MercedesC200
 Version: 1810
 Date calculated: 03/04/2019 10:08 AM

Full Report
Registration: SLP9902L
Printed: 04/03/2019 10:14 AM

Code	Description	Part Number	Supplier	Price SGD
1482	RIGHT FRONT DOOR	204 720 6000 64	Bodys	850.00
1488	R/F UPPER DOOR HINGE	204 720 0237	11	83.00
1492	CABLE GUIDE	204 722 1549	11	125.00
1496	R/F LOWER DOOR HINGE	204 720 0437	11	67.00
1510	R/F DOOR SEAL	204 727 1187	nu	138.00
1578	R/F DOOR LOCK	204 720 1635	11	165.00
1662	R/F OUT WINDOW SEAL	204 725 1665	11	66.00
1682	R/F DOOR MOULDING	204 720 0280	11	45.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,015.00
u: Used parts	Total			2,015.00

Extras

Code	Description	Price SGD
1000	MISC (1)	100.00*
	Total Extras	100.00

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Claim Reference: Dmpcsn1824121800
Assessment number: SLP 9902L(MercedesC200
Version: 1810
Date calculated: 03/04/2019 10:08 AM

Full Report
Registration: SLP9902L
Printed: 04/03/2019 10:14 AM

Final Calculation

	SGD	SGD
Parts	2,015.00	
Total Parts		2,015.00
Labour Time Base 10 WU/h		
Total 152.0 WU X 42.00 SGD/h	638.40	
Total of Labour		638.40
Total Of Extras		100.00
Paint Work Time Base 10 WU/h		
Labour Cost 33.0 WU X 42.00 SGD/h	138.60	
Material Cost	72.28	
Total Paint Including Material		210.88
Repair Cost Excludes GST		2,964.28
GST (+7.0%)		207.50
Repair Cost Included GST		3,171.78

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
Assessment number: SLP 9902L(MercedesC200
Version: 1810
Date calculated: 03/07/2019 10:36 AM

Full Report
Registration: SLP9902L
Printed: 07/03/2019 10:36 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	Dmpcsn1824121800	Date of Incident:	2019-02-28
Estimated Repair Time:	14	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	C-CLASS (W204)
Sub Model:	C 200 COMPRESSOR
Model Sheet Number:	03 04 01
Registration:	SLP9902L
VIN number:	WDD2040412A102616
Odometer:	121128

Model Specs

FR A082./F078./R007.	MODEL 2008	RAIN SENSOR	DIPPING MIRROR
FOLDING DOOR MIRRORS	AUDIO SYSTEM 20 CD	LEATHER UPHOLSTERY	ALU DESIGN PARTS
EQUIPMENT AVANTGARDE	DRIVER SEAT MEMORY	L/F SEAT WITH MEMORY	STRG WHEEL LEATHER
LEATHER STRG WHEEL	H/DUTY ALTERNATOR	ENGINE PROTECTION	AUTO GEARBOX 5 SPEED
PARAMETER STEERING	CRUISE CONTROL	TYRES 225/45 WR 17	WHEELS 7.5J X 17 ALU
SPARE WHEEL	PARKTRONIC SYSTEM	RIGHT HAND DRIVE	TWO COAT METALLIC
CLEAR COAT HARD			

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
Assessment number: SLP 9902L(MercedesC200
Version: 1810
Date calculated: 03/07/2019 10:36 AM

Full Report
Registration: SLP9902L
Printed: 07/03/2019 10:36 AM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
88-3956 01	RENEW R/FR WING INCLUDES: PARTITION PANEL R CPL REMOVE-- REFIT R/SIDE MEMBER TRIM DETACH/ATTACH		10.0	42.00
72-1515 01	RENEW R/F DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		33.0	138.60
72-1682 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH LOWER MOULDING)		1.0	4.20
72-1691 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH DOOR SPEAKERS)		2.0	8.40
54-7989 02	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		2.0	8.40
2248	R/INNER A-PILLAR REPAIR		40.0*	168.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
 Assessment number: SLP 9902L(MercedesC200
 Version: 1810
 Date calculated: 03/07/2019 10:36 AM

Full Report
 Registration: SLP9902L
 Printed: 07/03/2019 10:36 AM

Code	Description	WU	Price SGD
1488	R/F UPPER DOOR HINGE CHECK		
1492	CABLE GUIDE CHECK		
1496	R/F LOWER DOOR HINGE CHECK		
1662	R/F OUT WINDOW SEAL CHECK		
Labour Cost		Hrs	WU
Panel / Mechanical Labour		8.80	88.0
Total of Labour			369.60

Paint

Paint Work		SYSTEM AZT		Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD		
	R/F WING NEW PART PAINTING	9.0			
	RIGHT FRONT DOOR NEW PART PAINTING	15.0			

Paint Material Per Part

Code	Description	Price SGD
0742	R/F WING NEW PART PAINTING	14.45
1482	RIGHT FRONT DOOR NEW PART PAINTING	39.73

Labour Cost - Paint		Hrs	WU	Price SGD
Factor		42.00 SGD/h		
Time Paint			24.0	
Preparation Main Work Metal		0.90	9.0	37.80
Total		10 WU/h	3.30	33.0

Material Cost - Paint		Price SGD
New Part Painting		54.18
Material-constant Metal		18.10
Total		72.28

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01
				Price SGD
0742	R/F WING	204 880 1418		0.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
 Assessment number: SLP 9902L(MercedesC200
 Version: 1810
 Date calculated: 03/07/2019 10:36 AM

Full Report
 Registration: SLP9902L
 Printed: 07/03/2019 10:36 AM

Code	Description	Part Number	Supplier	Price SGD
0786	R/F WING MOULDING	204 690 3262		18.00
0812	R/F WING BADGE	204 817 2720		33.00
1482	RIGHT FRONT DOOR	204 720 6000 64		850.00
1510	R/F DOOR SEAL	204 727 1187		138.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,039.00
u: Used parts	Total			1,039.00

Extras

Code	Description	Price SGD
1000	MISC (1)	100.00*
	Total Extras	100.00

Final Calculation

	SGD	SGD
Parts	1,039.00	
Total Parts		1,039.00
Labour Time Base 10 WU/h		
Total 88.0 WU X 42.00 SGD/h	369.60	
Total of Labour		369.60
Total Of Extras		100.00
Paint Work Time Base 10 WU/h		
Labour Cost 33.0 WU X 42.00 SGD/h	138.60	
Material Cost	72.28	
Total Paint Including Material		210.88
Repair Cost Excludes GST		1,719.48
GST (+7.0%)		120.36
Repair Cost Included GST		1,839.84

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
Assessment number: SLP 9902L(MercedesC200
Version: 1810
Date calculated: 03/07/2019 10:36 AM

Full Report
Registration: SLP9902L
Printed: 07/03/2019 10:36 AM

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-410/412

Singapore 539195

Tel: 6289 8126 Fax: 6287 0590

Email: Jin@jinauto.com.sg

Company Reg. No: 200704370C GST Reg.No: 200704370C

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SLP9902L
Policy No:	DMPCSN1824121800	Date of Loss:	28/02/2019
Vehicle Reg. No.:	SLP9902L	Driveable?	NO
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HENG LEY KANG		
Driver:	HENG LEY KANG		
Make/Model:	MERCEDES-BENZ C200 KOMPRESSOR, 1.8 (A)	Vehicle Reg. Date:	20/02/2008
Vehicle Colour:	BLACK		
Engine No:	27195031005537	Chassis No:	WDD2040412A102616
Odometer:	121128 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	MY CAR WAS PARKED ALONG ROADSIDE AND MY FRONT RH DOOR WAS OPEN UNFORTUNATELY SMC2564E HAD CAME BY AND HAD COLLIDED ONTO MY DOOR.		
Present Location:	JIN AUTO SERVICES PTE LTD (DEFU)		

COST OF CLAIMS	Amount
Parts	2,115.00
Miscellaneous Items	0.00
Labour	849.28
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,964.28
+ GST 7.00% (S\$)	207.50
Nett Amount (S\$)	3,171.78

This claim is handled by: JOUIS SEOW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 04 Mar 2019)**Parts:** 143 MERCEDES-BENZ C200 KOMPRESSOR 1.8 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Jin Auto Services Pte Ltd/SLP9902L/04/03/2019 10:47**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TOTAL PARTS	0.00	0.00	*2,015.00 F
2	1		*MISC	0.00	0.00	*100.00 F
Total Parts (S\$)						2,115.00

F=Franchise part.

Jin Auto Services Pte Ltd/SLP9902L/04/03/2019 10:47. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR & PAINT MATERIALS	New	589.48 849.28
Gross Labour Cost (S\$)			849.28

Jin Auto Services Pte Ltd/SLP9902L/04/03/2019 10:47. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
Assessment number: SLP 9902L(MercedesC200
Version: 1810
Date calculated: 03/12/2019 01:57 PM

Full Report
Registration: SLP9902L
Printed: 12/03/2019 1:57 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	Dmpcsn1824121800	Date of Incident:	2019-02-28
Estimated Repair Time:	14	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	C-CLASS (W204)
Sub Model:	C 200 COMPRESSOR
Model Sheet Number:	03 04 01
Registration:	SLP9902L
VIN number:	WDD2040412A102616
Odometer:	121128

Model Specs

FR A082./F078./R007.	MODEL 2008	RAIN SENSOR	DIPPING MIRROR
FOLDING DOOR MIRRORS	AUDIO SYSTEM 20 CD	LEATHER UPHOLSTERY	ALU DESIGN PARTS
EQUIPMENT AVANTGARDE	DRIVER SEAT MEMORY	L/F SEAT WITH MEMORY	STRG WHEEL LEATHER
LEATHER STRG WHEEL	H/DUTY ALTERNATOR	ENGINE PROTECTION	AUTO GEARBOX 5 SPEED
PARAMETER STEERING	CRUISE CONTROL	TYRES 225/45 WR 17	WHEELS 7.5J X 17 ALU
SPARE WHEEL	PARKTRONIC SYSTEM	RIGHT HAND DRIVE	TWO COAT METALLIC
CLEAR COAT HARD			

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
 Assessment number: SLP 9902L(MercedesC200
 Version: 1810
 Date calculated: 03/12/2019 01:57 PM

Full Report
 Registration: SLP9902L
 Printed: 12/03/2019 1:57 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection: 2019-03-05

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
88-3956 01	RENEW R/FR WING INCLUDES: PARTITION PANEL R CPL REMOVE-- REFIT R/SIDE MEMBER TRIM DETACH/ATTACH		10.0	42.00
72-1515 01	RENEW R/F DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		33.0	138.60
72-1682 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH LOWER MOULDING)		1.0	4.20
72-1691 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH DOOR SPEAKERS)		2.0	8.40
54-7989 02	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		2.0	8.40
2248	R/INNER A-PILLAR REPAIR		40.0*	168.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
 Assessment number: SLP 9902L(MercedesC200
 Version: 1810
 Date calculated: 03/12/2019 01:57 PM

Full Report
 Registration: SLP9902L
 Printed: 12/03/2019 1:57 PM

Code	Description		WU	Price SGD
	Labour Cost	Hrs	WU	
	Panel / Mechanical Labour	8.80	88.0	369.60
	Total of Labour			369.60

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
	R/F WING NEW PART PAINTING	9.0	
	RIGHT FRONT DOOR NEW PART PAINTING	15.0	

Paint Material Per Part

Code	Description	Price SGD
0742	R/F WING NEW PART PAINTING	14.45
1482	RIGHT FRONT DOOR NEW PART PAINTING	39.73

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	42.00 SGD/h			
Time Paint			24.0	
Preparation Main Work Metal		0.90	9.0	37.80
Total	10 WU/h	3.30	33.0	138.60

Material Cost - Paint	Price SGD
New Part Painting	54.18
Material-constant Metal	18.10
Total	72.28

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
0742	R/F WING	204 880 1418		0.00
0786	R/F WING MOULDING	204 690 3262		18.00
0812	R/F WING BADGE	204 817 2720		33.00
1482	RIGHT FRONT DOOR	204 720 6000 64		850.00
1510	R/F DOOR SEAL	204 727 1187		138.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
 Assessment number: SLP 9902L(MercedesC200
 Version: 1810
 Date calculated: 03/12/2019 01:57 PM

Full Report
Registration: SLP9902L
Printed: 12/03/2019 1:57 PM

Code	Description	Part Number	Supplier	Price SGD
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,039.00
u: Used parts	Total			1,039.00

Extras

Code	Description	Price SGD
1000	MISC (1)	100.00*
	Total Extras	100.00

Final Calculation

	SGD	SGD
Parts	1,039.00	
Total Parts		1,039.00
Labour Time Base 10 WU/h		
Total 88.0 WU X 42.00 SGD/h	369.60	
Total of Labour		369.60
Total Of Extras		100.00
Paint Work Time Base 10 WU/h		
Labour Cost 33.0 WU X 42.00 SGD/h	138.60	
Material Cost	72.28	
Total Paint Including Material		210.88
Repair Cost Excludes GST		1,719.48
GST (+7.0%)		120.36
Repair Cost Included GST		1,839.84

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
Assessment number: SLP 9902L(MercedesC200
Version: 1810
Date calculated: 03/12/2019 01:57 PM

Full Report
Registration: SLP9902L
Printed: 12/03/2019 1:57 PM

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS





































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Mar 2019 Sendback Est	04 Mar 2019 10:47 S\$2,964.28	05 Mar 2019 09:42 Edit Adj Rpt	S\$1,350.00 Edit Estimates	S\$1,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: HENG LEY KANG , ID: S6873148H									
Vehicle Reg. No.: SLP9902L		Date of Loss: 28/02/2019 00:00 - :59 [132 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SLP9902L		Policy/Cover Note No.: DMPCSN1824121800 (Comprehensive)							
		Excess: S\$0.00							
Repairer: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/03/2019]									
Driver/Custodian: HENG LEY KANG (/ Male) , NRIC: S6873148H Email:									
Adj Asg. Remarks: SURVEY REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (07/03/2019): Alert - Adj Mandate Approved (S\$2119.28) - SLP9902L - Claim Handler: Chong Boon ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLP9902L (SLP9902L)
OD
Feb 28 2019 12:00AM
[HENG LEY KANG]
Jin Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	04/03/19 10:47	Repairer Estimates	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/19 13:31	Adjuster Immediate Advice	 Load HTM	
2	07/03/19 10:42	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/19 13:33	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	06/03/19 13:33	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/03/19 13:33	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/03/19 13:33	General View	 Load JPG	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
					<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	01/03/19 12:05	E-filed GIA report		Load PDF	
2	06/03/19 11:23	AUDATEX		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/03/19 13:33	ESTIMATE		Load PDF	
2	07/03/19 10:38	audatex report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19004070/UQD3E2

Date: 14/03/2019

REFERENCE

Insured/Claimant: HENG LEY KANG Policy No: DMPCSN1824121800
Date of Loss: 28/02/2019 Nature of Claim: OD Claim No: SLP9902L

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP9902L**
Make & Model: MERCEDES-BENZ C200 KOMPRESSOR, 1.8 (A) Engine No: 27195031005537
Reg. Date: 20/02/2008 (Man. Year: 2007) Chassis No: WDD2040412A102616
Colour: Black Odometer: 121128 km
Engine Capacity: 1796 cc
Market Value/New Car Price: S\$55,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,115.00	1,139.00	976.00	46.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	849.28	580.48	268.80	31.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,964.28	1,719.48	1,244.80	41.99
Approved Total (Overridden) (S\$)		1,350.00		
	(S\$)	2,964.28	1,350.00	54.46
+ GST 7.00/7.00% (S\$)	207.50	94.50	113.00	54.46
Nett Amount (S\$)	3,171.78	1,444.50	1,727.28	54.46

INSPECTION

Date of Assignment: 05/03/2019 Present Location: Jin Auto Services Pte Ltd (Defu)
Date Inspected: 05/03/2019 Inspected At: Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2019)
Parts:	143	MERCEDES-BENZ C200 KOMPRESSOR 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP9902L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		2,015.00 F	*1,039.00 F
2	1		*MISC		100.00 F	*100.00 F
					Total Parts (S\$)	2,115.00
						1,139.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR & PAINT MATERIALS	New	849.28	580.48
Gross Labour Cost (S\$)			849.28	580.48

Report was unsubmitted during this print-out.

< END OF ESTIMATES >