

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
Assessment number: SLP 9902L(MercedesC200
Version: 1810
Date calculated: 03/07/2019 10:36 AM

Full Report
Registration: SLP9902L
Printed: 07/03/2019 10:37 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	Dmpcsn1824121800	Date of Incident:	2019-02-28
Estimated Repair Time:	14	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	C-CLASS (W204)
Sub Model:	C 200 COMPRESSOR
Model Sheet Number:	03 04 01
Registration:	SLP9902L
VIN number:	WDD2040412A102616
Odometer:	121128

Model Specs

FR A082./F078./R007.	MODEL 2008	RAIN SENSOR	DIPPING MIRROR
FOLDING DOOR MIRRORS	AUDIO SYSTEM 20 CD	LEATHER UPHOLSTERY	ALU DESIGN PARTS
EQUIPMENT AVANTGARDE	DRIVER SEAT MEMORY	L/F SEAT WITH MEMORY	STRG WHEEL LEATHER
LEATHER STRG WHEEL	H/DUTY ALTERNATOR	ENGINE PROTECTION	AUTO GEARBOX 5 SPEED
PARAMETER STEERING	CRUISE CONTROL	TYRES 225/45 WR 17	WHEELS 7.5J X 17 ALU
SPARE WHEEL	PARKTRONIC SYSTEM	RIGHT HAND DRIVE	TWO COAT METALLIC
CLEAR COAT HARD			

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
Assessment number: SLP 9902L(MercedesC200
Version: 1810
Date calculated: 03/07/2019 10:36 AM

Full Report
Registration: SLP9902L
Printed: 07/03/2019 10:37 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
88-3956 01	RENEW R/FR WING INCLUDES: PARTITION PANEL R CPL REMOVE-- REFIT R/SIDE MEMBER TRIM DETACH/ATTACH		10.0	42.00
72-1515 01	RENEW R/F DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		33.0	138.60
72-1682 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH LOWER MOULDING)		1.0	4.20
72-1691 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH DOOR SPEAKERS)		2.0	8.40
54-7989 02	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		2.0	8.40
2248	R/INNER A-PILLAR REPAIR		40.0*	168.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
 Assessment number: SLP 9902L(MercedesC200
 Version: 1810
 Date calculated: 03/07/2019 10:36 AM

Full Report
 Registration: SLP9902L
 Printed: 07/03/2019 10:37 AM

Code	Description	WU	Price SGD
1488	R/F UPPER DOOR HINGE CHECK		
1492	CABLE GUIDE CHECK		
1496	R/F LOWER DOOR HINGE CHECK		
1662	R/F OUT WINDOW SEAL CHECK		
Labour Cost		Hrs	WU
Panel / Mechanical Labour		8.80	88.0
Total of Labour			369.60

Paint

Paint Work		SYSTEM AZT		Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD		
	R/F WING NEW PART PAINTING	9.0			
	RIGHT FRONT DOOR NEW PART PAINTING	15.0			

Paint Material Per Part

Code	Description	Price SGD
0742	R/F WING NEW PART PAINTING	14.45
1482	RIGHT FRONT DOOR NEW PART PAINTING	39.73

Labour Cost - Paint		Hrs	WU	Price SGD
Factor		42.00 SGD/h		
Time Paint			24.0	
Preparation Main Work Metal		0.90	9.0	37.80
Total		10 WU/h	3.30	33.0

Material Cost - Paint		Price SGD
New Part Painting		54.18
Material-constant Metal		18.10
Total		72.28

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01
				Price SGD
0742	R/F WING	204 880 1418		0.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
 Assessment number: SLP 9902L(MercedesC200
 Version: 1810
 Date calculated: 03/07/2019 10:36 AM

Full Report
 Registration: SLP9902L
 Printed: 07/03/2019 10:37 AM

Code	Description	Part Number	Supplier	Price SGD
0786	R/F WING MOULDING	204 690 3262		18.00
0812	R/F WING BADGE	204 817 2720		33.00
1482	RIGHT FRONT DOOR	204 720 6000 64		850.00
1510	R/F DOOR SEAL	204 727 1187		138.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 1,039.00
u: Used parts				Total 1,039.00

Extras

Code	Description	Price SGD
1000	MISC (1)	100.00*
	Total Extras	100.00

Final Calculation

	SGD	SGD
Parts	1,039.00	
Total Parts		1,039.00
Labour Time Base 10 WU/h		
Total 88.0 WU X 42.00 SGD/h	369.60	
Total of Labour		369.60
Total Of Extras		100.00
Paint Work Time Base 10 WU/h		
Labour Cost 33.0 WU X 42.00 SGD/h	138.60	
Material Cost	72.28	
Total Paint Including Material		210.88
Repair Cost Excludes GST		1,719.48
GST (+7.0%)		120.36
Repair Cost Included GST		1,839.84

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: Dmpcsn1824121800
Assessment number: SLP 9902L(MercedesC200
Version: 1810
Date calculated: 03/07/2019 10:36 AM

Full Report
Registration: SLP9902L
Printed: 07/03/2019 10:37 AM

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS