ASS, REC. BY:	REF: CS CMD1900HUF1 GHd3 Special Instruction.
· urvA or	ASSIGNMENT (Office)
From (Person); Estimated Cost:	Ornance Dong of CIMD Detertions: +43/2019.
ob/TP/WS/TP	RES/OD RES/EVA/INV/MV/CS
To Inspect Vehicle	NO. SMD BOBOL Insured: STM FR39 P
	Cas Garage Tel: 64845050. + Ave 6 405-20 uTPV01020553 Claim No: CMTD1901160 A1607
Policy No: D18	MTPV01020553 Claim No: CMTD1901163 206
Sum Insured:	Execus:
Make of Veh: (Client's Record)	D.O.A. 1/3/5019
CA / REV / REI	- / REV 24 HRS H.O.D. Endorsement:
Date/Time;	Person Conficted: Vehicle (N) OUT
Date/Time Act	on/Instruction (V) [Slimate.
SN	10.5250L-X
2	M 7839P-X
0-10	Revised preli advise M9 email
, N	cole chang. Cas @ gmail. com
	mp Sum \$3150 -, 4 days confirm with Alan,

Days Of Repair:

Add Fee:

Resurvey No. of Trip:

Site Irrap (\$

Interview (\$ Tean have (\$

Miller and the

Survey Fee

la aesportation

i Thote

350

361

Preli. Report

Final Report

Report Format:

Lunes Opini / LB C (S

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

WONG, LEE SIN LORRIANCE

Date: 08 Mar 2019

Preliminary Advice

Insured Vehicle No : SJM7839P

TP Vehicle No

: SMD5250L

Accident Date

:S\$

: 01/03/2019

Assignment Date

Make

: HYUNDAI ELANTRA

: 04/03/2019

Date of Inspection

: 05/03/2019

Est. Duration of Repair

: 4.00

Inspection At

: CAS GARAGE PTE LTD (HQ)

NO.1, KAKI BUKIT AVE 6, #02-22 AUTOBAY

SINGAPORE 417883

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,609.36
Revised Amount	:S\$	3,862.96
Check Items (Estimated)	:S\$	318.48
Total	:S\$	4,181.44

Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our	adjusted amount.	We have also confirmed	excess and	policy	coverage.	Kindly	
-----	----------------------------------	------------------	------------------------	------------	--------	-----------	--------	--

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Survey on WP (x)

...CLAIM SUBFOLDER...(New Assignment)

AIM SUB	FOLDER TRA		Ads Assigned	Adi Rot	Adj Subn	nitted	Ins Auth'ed	Status		
Case	02 Mar 2019	Est Submitted	04 Mar 2019 15:16	1103 5301				New As Cancel	signment Case	
			Assign							
	Main	Re	eference		Claim Details		Documen	ts	Sh	IIA wor
-	THE RESIDENCE OF THE PERSON OF	OF DESCRIPTION OF THE PARTY OF	Kenned Link & Arms & Ma	September 1	Print Hall Bridge Bridge	[Created	d by insurer]			
CLAIM S	JBFOLDER DI	ETAILS	T-1: 1	659765867	5, Email: NOEMA		•			
Insured:		G KEE, ID: S75		039703007	J, Lindin Har					
Main Claimant:	CHEN CO	NGHONG, ID:	S7063843F		Tev seed	103 /30	19 18:00 - :59			
Vehicle Re	g. SMD52	50L			Date of Loss:	01/03/20	18:0059			
No.: Claim Typ	e: TP / CM	TD1901162			Policy/Cover Note No.:	D18MTP\	/01020553 (Third	Party Only)	
Vehicle Re	sJM7839	P			Policy No. (Claimant):					
(Insured)					Excess:	1	111	84WW	MIN	n col
Bundalana.	Cae Gar	ne Pte Ltd (HO)	No.1, Kaki Bukit	t Ave 6, #02	2-22 Autobay, 417	883 Kaki E	and the second s			
Repairer: Handling Insurer:	Sompo I	nsurance Singar	ore Pte. Ltd. (HQ) - Tel: 6	3461 6555 [Har	idled by W	ONG, LEE SIN	ORRIANC	E - 6329 5	175]
Adjuster:	LKK Aut	o Consultants Pt	e Ltd (HQ) - Te	1: 6256-356	1 [Final Rpt	due 13/	03/2019]			
Driver/Cu dian (Insured)	LOH HON				el: +6597658675			7		
ASSOCI	ATED MAIL R	ECEIVED						View All	Compose	Case Ma
	no mail for th									
Triefe and	a mo man ror tr							-		
ALL AS	SOCIATED TA	ASKS E				View A			New Task	Comple
Due D			k Group Su	bject H	andler Assig	ned By	Completed	On Cr	eated On	Dan
No resul			200							



XGQ

Denise Tay (LKKAuto)

From:

Muhammad Asyraf Noor Azman <muhammad.asyraf@hyundaimotors.com.sg>

Sent:

Wednesday, 15 May 2019 6:12 PM

To:

Denise Tay (LKKAuto)

Subject:

RE: CHECK PART PRICE,

Hi,

86611-F2000 86631-F2030 COVER ASSY-RR BUMPER UPR BEAM-RR BUMPER

459.4

294.8

85770-F2000TRY

TRIM-TRANSVERSE RR

59.8

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]

Sent: Wednesday, May 15, 2019 12:14 PM

To: Muhammad Asyraf Noor Azman Subject: CHECK PART PRICE,

Dear Asyraf,

Can help me check part price.

SMD 5250L

C/No: KMHD841CMJU738788

Bootlid

Rear bumper reinforcement

Rear bumper

Rear end panel top garnish

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAuto)

From:

Muhammad Asyraf Noor Azman <muhammad.asyraf@hyundaimotors.com.sg>

Sent:

Saturday, 27 July 2019 7:54 AM

To:

Denise Tay (LKKAuto)

Subject:

RE: CHECK PART PRICE,

Hi Denise,

Soryy for the late reply.

PANEL ASSY-TRUNK LID

1782.4

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]

Sent: Friday, July 26, 2019 4:01 PM To: Muhammad Asyraf Noor Azman Subject: RE: CHECK PART PRICE,

Hi Asyraf,

As spoken, appreciated your help.

SMD 5250L

C/No: KMHD841CMJU738788

Hyundai Elantra

Boot lid

A million thanks

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhammad Asyraf Noor Azman < muhammad.asyraf@hyundaimotors.com.sg >

Sent: Wednesday, 15 May 2019 6:12 PM

To: Denise Tay (LKKAuto) < denisetay@lkkauto.com>

Subject: RE: CHECK PART PRICE,

Hi,

86611-F2000	COVER ASSY-RR BUMPER UPR	459.4
86631-F2030	BEAM-RR BUMPER	294.8
85770- F2000TRY	TRIM-TRANSVERSE RR	59.8

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]

Sent: Wednesday, May 15, 2019 12:14 PM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	3843F
Vehicle Details	
Vehicle No.:	SMD5250L
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	G4FGJU247461
Chassis No.:	KMHD841CMJU738788
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,477.00
Original Registration Date:	24 Aug 2018
First Registration Date:	24 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$12,477.00
Intended PARF Rebate Details	的复数 医水杨素 医多种性 医多种性 医多种性 医多种性 医多种性 医多种性
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2028
PARF Rebate Amount:	\$9,357.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,798.00
COE Rebate Amount:	\$31,980.00
Total Rebate Amount:	\$41,337.00

The information contained herein is correct as at 06 Mar 2019

ОК

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Mobile Number Fax Number

Contact Number

EMail Address

Gender

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- ort at the centre and to copies of the report being made available

aforesaid.	ACCIDENT STATEMENT
	ACCIDENT STATEMENT
Date Of Report	02/03/2019 13:30
Date Of Accident	01/03/2019 18:40
Exact Location Of Accident	SLIP RD AT BUANGKOK GREEN TWDS YIO CHU KANG RD.
Country/State of Loss	SINGAPORE
THE PARTY OF THE P	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SMD5250L
Insured/Policyholder	
Name Of Registered Owner	CHEN CONGHONG
NRIC No	S7063843F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90252346
Alternative Phone No	OFFICE-90252346
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	ELANTRA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2195315
Cover Note Number	
Driver	
Name of Driver	CHEN CONGHONG
NRIC No	S7063843F
Date Of Birth	17/08/1970
Occupation	INDOOR
Date Of Driving Pass	08/08/2011
Driving Experience	7 YEARS AND 6 MONTHS

MALE

NOEMAIL

(LOCAL) +65-90252346

OFFICE-90252346

Address

BLK 571 HOUGANG ST 51 #06-115

Postcode

530571

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

5

Passenger 1

NAME:

: CHEN ZUYING

GENDER:

: FEMALE

Passenger 2

NAME:

: HUANG BI YU

GENDER:

: FEMALE

Passenger 3

NAME:

: CHEN ZU LI

GENDER:

: FEMALE

Passenger 4

NAME:

: CHEN ZU GEN

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 01/03/2019 AT ABOUT 1842 HRS, I WAS TRAVELLING ALONG BUANGKOK GREEN TOWARDS YIO CHU KANG ROAD, UPON REACHING THE SLIP ROAD, I SLOWED DOWN AND STOPPED DUE TO THE TRAFFIC AHEAD. SUDDENLY I HEARD A LOUD BANG FROM BEHIND AND WHEN I ALIGHTED I REALISED IT WAS VEHICLE B WHO HIT THE REAR PORTION OF MY VEHICLE CAUSIND DAMAGE TO MY VEHICLE

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJM7839P

Vehicle Make/Model/Colour

Details Of Properties Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

VEH B PRIVATE CAR LOU HONG KEE PHILIP

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3 Information provided must be as <u>Invinfy</u>; and accurate as <u>possuple</u>. Any witful misrepresentation or withholping of material (acts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any lake importing may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurence. Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 2 By the indgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and so copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)
 - Londerstand, acknowledge, agree and consent that:
 - (a) My inswer, my workshop and the General Insurance Association of Singapore ("GRA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set but in this [Gern] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident (all insurers) have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the first rest lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/surfacility (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (iii) investigating the accident and/or my daims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my staims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, nancling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to chilect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) impless and information may/can be disclosed by any of the incurers and/or GIA to their third party service providers or agents (including their tawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be coherred and used to compile daims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (c) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder s Signature

Date & Time:

Oriver's Signature (If driver is not the policyholder) Date & Time;

Reporting Centre Personnel's Signature Name

NRIC/FIN No.



On 01.03.2019 at about 1842 hours, I was travelling along Buangkok Green towards Yio Chu Kang Road . Upon reaching the slip road, I slowed down and stopped due to the traffic ahead.

Suddenly I heard a loud bang from behind and when I alighted I realized it was vehicle (B) who hit the rear portion of my vehicle (A) causing damages to my vehicle.

Vehicle (A) :SMD5250L

Vehicle (B): SJM7839P

LETTER OF UNDERTAKING

LIWE, CHEN CONG HONG	, the owner of vehic	le no
My/Our Insurance is under M/s AXA Inclaim under my/our Policy or against the such a claim to M/s AXA Insurance Pte within 14(fourteen) days of occurrence	e Third Party and if the fo Ltd with all relevant fact	rmer shall submit s and documents
My/Our Third Party claim is handle by to	my/our preferred worksho	op,
Signed and Acknowledge by:		
Nric no. & signature of policyholder	Company stamp	02-03-20/9 Date



nsurance Compar	ny: SOMPO INSURANCE SINAPORE PTE LTD (MOTOR CLAIMS DEPARTMENT) Auto Consultation of 1 • To resurve, before	Itants her	nce notify ng:		
Address:	NO 50, RAFFLES PLACE, #05-01/06 display damage				
tudi ess.	SINGAPORE LAND TOWER, S(048623) of all a S				
elephone:	64616555 Four 63257047 Party Survey	S Constit	nout Prejudice basis	o dom se	
elephone.	No rilegal modifical	ion(s) is all	owed	0.001111.00	
	Supplementary de is subject to final a		n Insurance Company		
Make/ Model :	HYUNDAI ELANTRA	Date:		0	8.01.2019
	Acknowledged by Re	pairer			
Chassis No:	KMHD841CMJU738788 Signature:	Vehic	le No:	S	MD5250L
	Units.			_	
Date/Time of Acc	ide01.03.2019/ 1840				
	200 100 100 100 100 100 100 100 100 100				
Materials Cost/	Spare Parts Cost TO BE COMPLETED BY SERV	ICE ADV	ZISOD		
		ICE ADV	Terro tre verse menoricus	PARTS	100000 SEP - MEEDINGS
ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	DISCOU	FINAL PRICE
1	BOOTLID / BT	1	\$ 7 1,620.40	20%	\$ 1,296.32
2	BOOTLID REFLECTORS X (A/A/	2	\$ X 708.60	20%	\$ 566.88
3	BOOTLID INNER TRIM X	1	\$ X 326.60	20%	\$ 261.28
4	BOOTLID EMBLEM "ELANTRA" / 155	1	\$ -7 90.30	20%	\$ 72.24
5	BOOTLID EMBLEM "S" /	55 I	\$ / ? 55.60	20%	\$ 44.48
6	BOOTLID LOGO / 755	1	\$ 7 60.50	20%	\$ 48.40
7	BOOTLID INNER LOCK	. 1	\$ X 243.60	20%	\$ 194.88
8	BOOTLID LOWER LATCH X	Y 1	\$ X 25.80	20%	\$ 20.64
9	BOOTLID SMART KEY ANTENNA X	1	\$ X 236.50	20%	\$ 189.20
10	BOOTLID WEATHERSTRIP # / Tw		\$~ 7 212.90	20%	\$ 170.32
11	REAR BUMPER / CL 459.40 469.	1	\$ 608.20	20%	\$ 486.56
12	REAR BUMPER RETAINERS X	2	\$ X 126.60	20%	\$ 101.28
13	REAR BUMPER BRACKETS X	2	\$ 185.20	20%	\$ 148.16
14	REAR BUMPER BOTTOM / Got . 380-		\$ 7 380.80	20%	\$ 304.64
15	REAR BUMPER LOWER COVER X VA	1	\$ 116.30	20%	S 93.04
16	REAR BUMPER LOWER COVER X VA REAR BUMPER REINFORCEMENT REAR BUMPER REINFORCEMENT BRACKI	K 8 1	\$ 398.10	20%	\$ 318.48
17	REAR BUMPER REINFORCEMENT BRACKI	N	× 98.60	20%	\$ 78.88
19		P 2		20%	\$ 85.44
20		1 2	\$ \(\sqrt{806.60} \)	20%	\$ 645.28
21	REAR FENDER INNER COWLING X N/	2	\$ \$202.60	20%	\$ 162.08
22	REAR END PANEL TOP CAPNISH TO	0	\$ \$ 453.10	20%	\$ 362.48
23	REAR END PANEL TOP GARNISH	0	\$ 148.60	20%	\$ 118.88
24	REAR SILENCER BOX	1	\$ \$\square 606.20	20%	\$ 484.96
25	REAR SILENCER BOX MOUNTING X	N 2	\$ y 96.20	20%	\$ 76.96
26	REAR FLOOR PANEL /	1	\$ \(\) 1,033.40 \$ \(\) 326.10	20%	\$ 826.72 \$ 260.88
25			S V 326.10	1 /31/0	\$ 260.88
27 Total List Price (REAR FLOOR PANEL TOP BOARD	1	X 520.10	2070	S 7,419.36

New Burper nefletor PH / Cur

No colections. Known 20 cas agrant com

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINA	L PRICE \$
1	REAR NUMBER PLATE WITH CASING	SCLISET	\$ 50.00	S	50.00
2	REAR BUMPER CLIPS / ME	1 SET	\$ 30.00	\$	30.00
3	REAR END PANEL TOP GARNISH CLIPS	X 1 SET	\$ 30.00	\$	30.00
4		C SET	\$ 250.00	\$	250.00
5	REVERSE CAMERA X	1 SET		S	300.00
6	REAR FENDER COWLING SET X	V 2 SET	\$ 60.00	\$	60.00
7	REAR TAILAMP CLIPS ×	2 SET	\$ 60.00	\$	60.00
8	END PANEL INSULATOR SEAL X	2 SET	\$ 80.00	S	80.00
otal Special Nett				S	860.00

abour Works/ Panel Beating Related Works Job Scope	Q)uotation
O RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGN ALL PARTS	s	1,600.00
		400
Spray Painting Job Scope	T (Quotation (
TO RESPRAY AFFECTED AREAS	S	1,600.00
Others Cost (Accident Repair Related Expenses)		600
Job Scope	C	Quotation
TO TUFFCOAT AFFECTED AREA	\$	200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	S	150.00
REAR CHASSIS ALIGNMENT	S	120.00
TO REMOVE/ REFIT WIRING CHECKS	\$	120.00
TO CONDUCT WATER LEAKAGE TEST	S	150.00
TO REMOVE/ REPLACE REAR SILENCER BOX	\$	120.00
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	S	150.00
IO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTEINS	S	120.00
TO REMOVE AND REPLACE TAILGATE MECHANISM	-	
TO REMOVE AND REPLACE TAILGATE MECHANISM Total Others Cost GRAND TOTAL	\$	1,130.00 12,609.36

CAS GARAGE PTE LTD

UEN 201828067M 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan

Direct Contact: +65 8782 7171 Email: allangoh.cas@gmail.com

Fax: 6509 9501 TEL: 64842220

(47ays. 8/3/2)
(apsur repair.

After repair photos.

Gno Q: af - 82880282 3115.20

05/3/19.

Lup Sum 43,501- 5N \$ 290.00

Lup Sum 43,501- 5N \$ 290.00

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/SMO19004071/GTD3N2

G4FGJU247461

7461 km

KMHD841CMJU738788

Date:

31/07/2019

REFERENCE

Handling Insurer:

Sompo Insurance Singapore Pte.

Ltd.

Policy No:

D18MTPV01020553

Engine No:

Chassis No:

Odometer:

Claimant

SMD5250L

Insured Vehicle No:

SJM7839P

Vehicle No: Date of Loss:

01/03/2019

Nature of Claim:

TP

Claim No:

CMTD1901162

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Reg. Date:

SMD5250L

Make & Model:

HYUNDAI ELANTRA, 1.6 (A)

24/08/2018 (Man. Year: 2018)

Silver

Colour: Engine Capacity:

1591 cc

Market Value/New Car

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

195/65 R15 Nexen 8 mm Rear Tyre Size: Rear Left Side:

195/65 R15 Nexen 8 mm

Front Right Side:

Nexen 8 mm

Rear Right Side:

Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 8,279.36 0.00	Adjuster's 2,782.16 0.00	5,497.20 0.00	Diff % 66.40
Labour Paintwork Labour	4,330.00 0.00	1,170.00 0.00	3,160.00 0.00	72.98
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	12,609.36	3,952.16 3,150.00	8,657.20	68.66
Nett Amount (S\$)	12,609.36	3,150.00	9,459.36	75.02

INSPECTION

Date of Assignment:

04/03/2019

Date Inspected:

05/03/2019 Inspected At:

Cas Garage Pte Ltd (HQ)

No.1, Kaki Bukit Ave 6, #02-22 Autobay

Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Jul 2019)

Parts: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD5250L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,620.40 FL	*1,620.40 FL
2	2		*BOOTLID REFLECTORS	Not Necessary	708.60 FL	*-FL
3	1		*BOOTLID INNER TRIM	Not Necessary	326.60 FL	*- FL
4	1		*BOOTLID EMBLEM ELANTRA	Necessary	90.30 FL	*55.00 FL
5	1		*BOOTLID EMBLEM S	Necessary	55.60 FL	*55.00 FL
6	1		*BOOTLID LOGO	Necessary	60.50 FL	*55.00 FL
7	1		*BOOTLID INNER LOCK	Not Necessary	243.60 FL	*-FL
8	1		*BOOTLID LOWER LATCH	Not Necessary	25.80 FL	*-FL
9	1		*BOOTLID SMART KEY ANTENNA	Not Necessary	236.50 FL	*-FL
10	1		*BOOTLID WEATHERSTRIP	Twisted	212.90 FL	*135.00 FL
11	1		*REAR BUMPER	Deformed	608.20 FL	*459.40 FL
12	2		*REAR BUMPER RETAINERS	Not Necessary	126.60 FL	*-FL
13	2		*REAR BUMPER BRACKETS	Not Necessary	185.20 FL	*-FL
14	1		*REAR BUMPER BOTTOM	Cut	380.80 FL	*380.80 FL
15	1		*REAR BUMPER LOWER COVER	Not Necessary	116.30 FL	*-FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	398.10 FL	*294.80 FL
17	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	98.60 FL	*-FL
18	2		*REAR MUDGUARDS	Not Necessary	106.80 FL	*-FL
19	2		*TAILLAMPS	Not Necessary	806.60 FL	*-FL
20	2		*REAR FENDER INNER COWLING	Not Necessary	202.60 FL	*-FL
21	1		*REAR END PANEL	Repair	453.10 FL	*-FL
22	1		*REAR END PANEL TOP GARNISH	Deformed	148.60 FL	*59.80 FL
23	1		*REAR SILENCER BOX	Not Necessary	606.20 FL	*-FL
24	2		*REAR SILENCER BOX MOUNTING	Not Necessary	96.20 FL	*-FL
25	1		*REAR FLOOR PANEL	Not Necessary	1,033.40 FL	*-FL
26	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	326.10 FL	*-FL
27	1		*REAR BUMPER REFLECTOR RH (NPA)	Cut	0.00 FL	*-FL
28	1		*SET REAR NUMBER PLATE WITH CASING	Scratched	50.00 FS	*40.00 FS
29	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
30	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	
31	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
32	1		*SET REVERSE CAMERA	Not Necessary	300.00 FS	*-FS
33	2		*SET REAR FENDER COWLING	Not Necessary	60.00 FS	*-FS
34	2		*SET REAR TAILLAMP CLIPS	Not Necessary	60.00 FS	*-FS
35	2 anchise	part. S=Spo	*SET END PANEL INSULATOR SEAL Nett. L=ListItemDisc.	Not Necessary	80.00 FS	*-FS
worlin's				Sub Total (S\$)		3,405.20
	- List Item Discount on L Items 20.00/20.00% (S\$)				1,854.84	623.04
				Total Parts (S\$)	8,279.36	2,782.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items		Walk of the Company o	
1	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGN ALL PARTS.	New	1,600.00	400.00
2	TO RESPRAY AFFECTED AREAS.	New	1,600.00	600.00
3	TO TUFF COAT AFFECTED AREA.	New	200.00	40.00
4	TO REMOVE / REFIT INTERIOR UPHOLSTERY.	New	150.00	60.00
5	REAR CHASSIS ALIGNMENT.	New	120.00	0.00
6	TO REMOVE / REFIT WIRING CHECKS.	New	120.00	30.00
7	TO CONDUCT WATER LEAKAGE TEST.	New	150.00	0.00
8	TO REMOVE / REPLACE REAR SILENCER BOX.	New	120.00	0.00
9	TO REMOVE / REPLACE REVERSE SENSORS AND DISTANCE SETTLING.	New	150.00	40.00
10	TO REMOVE AND REPLACE TAILGATE MECHANISM.	New	120.00	0.00
	Gross Labor	4,330.00	1,170.00	
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >