SMINOSPA			9119004ct2 Ksds IGNMENT (Office)	307 Special Instruction	(.)
From (Person	I Jas Man	ol	MZA	Unite/Time:	43/2019.
Estimated Co.	ul		Bill to:		
GD/TP/W	S/TP RES/OD 1	RESTEVATING	/MV/CS		
To Inspect Ve	chicle No. ST	LIFAST		Insued:	
at Workshop	mb S & H			Tel	
or 160 Stu	(おのずっの)				
Policy No.			Claim Ho:	SAMOLEBP	
Sum Insured			Excess.	NIL	
Make of Vela				D.O.A.	26/2/2019
CA / REV	0 / REP. / REV 24	Tine		11.O.D. End	1.1
Date/Time.	. HEL. / KISY 24		Secretary.		
Date Line.		Person Co	dacted;	Vehicle (IN)	007
Date/Time	Action/Instruction	m (V) (5	timate		
	SJKITOS	X - X			

ASS. REC. BY:	
Kenneth	ASSIGNMENT
From: Date:	The control of the co
Estimated Cost:	Veh No: SJK 1725 J Yr Regn: 05, 15
OD TP / WS / TP RES / OD RES / EVA / INV / MV	- M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
at Workshop m/s	Make: Volkswagen Jetto co 139
of	Colour A. Grey AC: Insured / Std / NI / NA
Insured:	Sp.Reading /0/25 7 T/Radio: Insured / Std / NI / NA
Policy No.	EngNo:
Claims No. +-	_ CNO: WUWZZZ16ZFM62864
Sum Insured: Excess: N.	Gen. Cond: Bood / Fair / Poor / Burnt
(Client's Record)	
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: NII / S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F;
Rumark: The yeh had common at the	R: 225/903R18
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PPIR / SUMI /
Bal. or Market Value: \$2531c	TOYO/YOKO or
IDAC Accident Rport: Consistent? : Yes or No	Eroni Rear
GIA / PR Seen: Consistent?: Yes or No	R/Bal. 6 mm R/Bal. 7 mm
To state it is to no	L/Bal. 1 mm L/Bal. 1
A DATE OF THE PARTY OF THE PART	D.O.A. 26/2/19 D.O.I. 5/3/19
1 7517 % SVELL TES OF NO	Survey held at
CA REV REP. 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OU	177 015
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
/ Fit poss To	
	22 B & days with kernette
(\$ 125.20 Red - 4%	2 days with kernety
	Monrollo
	The state of the s
	20/3/20
KEY	120/3
Staffere, File Pass 197	Days Of Repair:
Tyaist : Final Report	Resurvey No. of Trip:
ute/Time, File Raturn to?	Survey Fee: 160
Add Fee:	: Site Insp (\$)_s-Rs_si
	Interview (\$), Factors
eport Format :	Tech love (\$
ump Sum / I.B.I: (S 3, 067. 22 1/e)	Weekend (\$
	1014L [50]

Menn



Service Request Details

Claim

S9M01FBP

Reference

None 🖋

Loss Date

February 26, 2019

Report Date

Feb 27, 2019 12:00:00 AM

Request Date

March 4, 2019

Due Date

March 11, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration # SJK1725J LKK AUTO CONSULTANTS PTE LTD (OD) +

denn

Model

1.1.1

JETTA 1.4 TSI

Service Address

Primary Contact/Insured

BAN SIONG (BERNARD HUANG WANXIONG) BERNARD HUANG 234 WESTWOOD AVENUE, #12-35 THE FLORAVALE, 648361, Singapore 93835842

Claim Handler

TAN Jas 6568804844 jas.tan@axa.com.sg

Additional Instructions

S&H OD XS NIL

Messages Invoices History Documents Assessment Metrics Notes

New Message

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5602G
Vehicle Details	
Vehicle No.:	SJK1725J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Feb 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T TL 1632G5
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	CAXF50188
Chassis No.:	WVWZZZ16ZFM028645
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,557.00
Original Registration Date:	26 May 2015
First Registration Date:	26 May 2015
Transfer Count:	0
Actual ARF Paid:	\$7,557.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 May 2025
PARF Rebate Amount:	\$5,667.00
Intended COE Rebate Details	
COE Expiry Date:	25 May 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66.590.00
COE Rebate Amount:	\$41,566.00
Total Rebate Amount:	\$47,233.00
The information contained best in it consent on at 27 Cab 2010	

The information contained herein is correct as at 27 Feb 2019

Shirley Hiew (LKK Auto)

From:

Doris <doris@sh-motor.com>

Sent:

Monday, 25 March 2019 12:44 PM

To:

'Shirley Hiew (LKK Auto)'

Subject:

RE: SJK 1725J OD (AXA) DOA: 26/02/2019

Dear Shirley

Noted...Thank...Cost \$ 3,067.22 x 7% gst (\$3,281.93)

Thank

Doris

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Monday, 25 March 2019 12:18 PM

To: 'Doris'

Subject: FW: SJK 1725J OD (AXA) DOA: 26/02/2019

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Wednesday, 20 March 2019 1:56 PM To: 'Enquiry' <enquiry@sh-motor.com>

Cc: SUR <sur@lkkauto.com>

Subject: SJK 1725J OD (AXA) DOA: 26/02/2019

Hi Cynthia,

As spoken, please refer to the attachment.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Immediate Advice

To: AXA Insurance Pte Ltd Date: 06/03/2019

Survey Details:

Date of loss	26-Feb-19
Date of appointment	4-Mar-19
Date of survey	5-Mar-19
Location of survey	160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722

Vehicle Details:

Claim Type:	Own Damage	
Vehicle number	SJK 1725J	
Make and Model	VOLKSWAGEN JETTA GP 1.4 TSI 90 A/T TL 1632G5	
Date of registration	26-May-15	
Excess	\$0	
Market Value	\$53,000	
Parf Rebate	\$47,233	
Nett Loss	\$5,767	

Repair details:

Initial Estimate	3,192.42
------------------	----------

Proposed/Revised repair cost:

Parts	\$2,123.00
Check items (estimate)	\$966.72
Labour	\$80.20
Total	\$3,169.92
Lump Sum(if applicable)	\$

Number of days for repair	5 DAYS
---------------------------	--------



31 URLANE 1, 302-25 PAYA URLINDUSTRIAL PARK, SINGAPORE 408933 TEL+ (065) 62563561 FAX+ (065) 6256-015

Remarks:

DAMAC	SES CON	SISTENT, I	REPAIR CO	ST ECONO	MICAL. WE
HAVE A	UTHOR	IZE REPAIR	₹.		

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

LKK AUTO CONSULTANTS PTE LTD (OD) .



IA - SJK 1725J

Type

Question

Message

IA uploaded. Damages consistent, repair cost economical. We have authorize repair. Thanks. From : Shirley Hiew

Reply

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 5. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	27/02/2019 11:32
Date Of Accident	26/02/2019 13:45
Exact Location Of Accident	MARINA BOULEVARD TOWARDS MBS
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE

	Control Contro	
Vehicle Registration Number	SJK1725J	
Insured/Policyholder		

Name Of Registered Owner BERNARD HUANG BAN SIONG

NRIC No S8025602G Email Address NOEMAIL

Mobile Phone No. (LOCAL) +65-93835842 Alternative Phone No. OFFICE-93835842

Vehicle Particulars

Manufacturer VOLKSWAGEN Model JETTA 1.4 TSI

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy. for repair to your vehicle?

If No. Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number VPA/P1628874

Cover Note Number

Driver

Name of Driver BERNARD HUANG BAN SIONG

NRIC No S8025602G Date Of Birth 27/08/1980 Occupation INDOOR Date Of Driving Pass 12/08/2013

Driving Experience 5 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-93835842

Fax Number

Contact Number OFFICE-93835842

EMail Address NOEMAIL Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

ċ

General Information of the Accident

Type Of Accident COLLIDED INTO PEDESTRIAN

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident

1

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

VEC

ambulance?

YES

Was any other material or property damaged?

NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance:

NO

Number of Passengers (Including Driver)

5

Passenger 1

NAME:

: PASSENGER

GENDER:

: MALE

Passenger 2

NAME:

: PASSENGER

GENDER:

: MALE

Passenger 3

NAME:

PASSENGER

GENDER:

FEMALE

Passenger 4

NAME:

: PASSENGER

GENDER:

FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

Police Station Address

NANYANG N.P.C

ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-7929999 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

refer attached police report.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

Details of Witness 1

Page 2 of 18

Name

ANDY SIM

Phone Number

90303645

Email Address

Details of Witness 2

Name

MUZ

Phone Number

96247224

Email Address

DETAILS OF INJURED PERSON 1

Name

PEDESTRIAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worm?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any willul misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose end/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Pulicyholder's Signature Date & Time:


Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Senature Name:

NRIC/FIN No.







1.43

Report No. 1/20190227/2027

Police Station Of Origin Nanyang N.P.C. 2 Jurong West Avenue 5 SINGAPORE 649482 Tel No. 1800-7929899

Station Diary No. REPORT OF A TRAFFIC ACCIDENT Vide Report No. Date/Time Report Made A/20190228/0083 27/02/2019 09:15 Informant's Particulars 234 WESTWOOD AVE #12-35 SINGAPORE 648361 Address Name of Informant BERNARD HUANG BAN SIONG Contact No. Mobile: 93835842 ID Type / ID No. Home/Office: NRIC NO / 58025602G Email: Nationality SINGAPORE CITIZEN Type of Informant Date of Birth Age: Sex Driver 27/08/1980 38 Institution / School Name Male Language: Race English Chinese Driving Licence Information Occupation Date of Expiry Class: 3A Auditor (accounting)

General Information of the Accident Type of Location Date/Time of Drink. Injury T-Junction Accident: Type of Conveyed By Ambulance Drive: 26/02/2019 13:45 Accident No Location Junction of Road 1 and Road 2 MARINA BOULEVARD MARINA VIEW T-Junction of Marina Boulevard and Marine View Lamp post 10F Lamp Post Number: 10F Road Speed Limit Road Surface: Weather Clear Traffic Volume Traffic Control Traffic Flow Moderate Traffic Light - Working One Way Anyone conveyed by Type of Collision: ambulance Moving Vehicle Against - Pedestrian Yes

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJK1725J	Car	VOLKSWAGO N	JETTA GP 1.4 TSI 90 A/T TL 1632G5	Grey	Seriously Damaged	4

Details of V	ehicle Insurance			
	Insurance Company	Insurance No	Effective	Expiry Date
	AXA INSURANCE SINGAPORE PTE	P1628874	26/05/2018	25/05/2019



Police Station Of Origin: Nanyang N.P.C 2 Jurong West Avenue 5 SINGAPORE 649482 Tel No: 1800-7929999



2013

Report No. 1/20190227/2027

CONTINUATION OF REPORT

Any Pedestrian No of Pedestria		Use of Pec	iest/ian	Cross	ing: Not Used
Driver Name	BERNARD HUANG BAN SIONG		ID No.		S8025502G
Related Vehicle	SJK1725J (Car)		Conta	ct No.	93835842
Hospits//Clinic	NIL		Class Driving Licence Expiry	20 &	Class 3A Date of Expiry: Nil.
late Treatment	NIL ed Medical Leave NIL	Date Disci Degree of		NIL	

Brief Details.


On 25/02/2019 at about 1345hrs. I was driving my vehicle, SJK1725J along Marina Boulevard towards Marina Bay Sands. The weather was clear and the road was dry. The traffic volume was moderate and there were a total of 5 lanes along Marina Boulevard. I was driving at the most left lane, Lane 5. As I approached the T-Junction of Marina Boulevard and Marina View, I intended to proceed straight towards Marina Bay Sands and to turn left at the next junction. When I approached the T-Junction, the traffic light was red. While I was slowing down to stop behind the stop line, the traffic turned green. So I proceed forward about 20-30km/h. When I was about to cross the junction, one Female Chinese subject dashed towards from my right to the left. The woman was running outside of the pedestrian crossing. The impact resulted my windscreen cracked and damaged my vehicle's front portion.

The female subject was conscious during the whole incident. However, I saw that she suffered abrasions on her limbs. Ambulance came and conveyed her to Raffles Hospital. Traffic Police then came and advised me to lodge a Police report. My vehicle got no In-Car camera.

My colleagues who were in my vehicle during the accident were.
Emilia Lim. Hp: 83227543. Lee Wei Siew, Hp: 98199562, Isaac Lau, Hp. 91986178, Toh Hui Ting, Hp: 81130921

Two Pedestrians came forward and informed me that they saw the accident. They were standing at the left side of the traffic light pedastian crossing and was waiting for the green man to cross the road. Their details are: Andy Sim, Hp. 90303645 and Muz. Hp. 96247224

Sketch Plan #5



Police Station Of Origin Nanyang N.P.C 2 Jurong West Avenue 5 SINGAPORE 649482 Tel No. 1800-7929999 THE PERSONAL PROPERTY.

2.003

Health No. 1(2019)22712027

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT. Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report J / Staff Sgt LOW YONG CHIN	Signature Of Informant:
Signature Of Interpreter Not applicable	Date/Time: 27/02/2019 09:16
Officer In Charge Of Case TP / GIT / Staff Sgt SUFIYAN BIN KHAIRL	Classification Of Case
Authentication Stamp	SN 127
C) nore Pol	ice Farce

Claim Reference:

Full Report

Assessment number: SH/2019/057/02/025/OD

Registration: SJK1725J

Version: 1810

Printed: 27/02/2019 6:18 PM

Date calculated: 02/27/2019 06:18 PM

Summary Information

Claim

Location:

Printed by:

Claim Reference:

Estimated Repair Time: Actual Repair Days:

Singapore (SG)

SH Motor

Work Provider:

Currency: Date of Incident:

Hire Car Start:

Hire Car End:

AXA Insurance Pte Ltd

SGD

2019-02-26

Vehicle Details

Vehicle Manufacturer:

Model:

Sub Model: Model Sheet Number:

Registration:

VIN number: Odometer:

Model Specs

R/DOOR MIRROR W/ANG LIGHT SWITCHING AUTO DOOR TRIM IMIT LEATH

7-SPEED DSG TYRES 205/55 VR 16

STABILITY PROGRAM TWO COAT METALLIC VW

JETTA (163) BASE MODEL 06 J7 01

SJK1725J

WVWZZZ16ZFM028645

FROM 01/2015

PAINTED DOOR MIRROR HEATED DOOR MIRRORS LED TAILLAMP ON-BOARD COMPUTER

SERVOTRONIC WHEELS 6.53 X 16 HEAD AIRBAG

NEW ATT/PARTS PAINT

KEYLESS ENTRY

L/CONVEX DOOR MIRROR 8 SPEAKER

R/FOG LAMP

FRONT CENTRE ARMREST ALTERNATOR 140A 1.4 LTR 90 KW

SPARE WHEEL STEEL HD COOLING

Authory Rearry BEpains

CLIMATIC

EQUIPMENT CLOTH PASS AIRBAG SWITCH FRONT BRAKES 288X25 SEAT MOUNTING ISOFIX

Labour

	Time Base 10 WU/h	Price = 45.	00 SGD/h
Code	Description	WU	Price SGD
NO NUMBER	R + R LOCK CARRIER STRUT	3.0	13.50
63 29 19 00	R + R FRONT BUMPER COVER	6.0	27.00
50 55 19 50	R + R R/F WING (BUMPER COVER REMOVED) INCLUDES: R + R WHEELHOUSE SHELL	7.0	31.50
94 15 19 60	R + R R/HEADLAMP (FRONT BUMPER COVER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.50
94 15 16 00	ADJUST HEADLAMPS	3.0	13.50
55 22 19 00	REMOVE/REFIT BONNET PANEL	7.0	31.50

Claim Reference:

Full Report

Assessment number: SH/2019/057/02/025/OD

Registration: SJK1725J

Version: 1810

Printed: 27/02/2019 6:18 PM

Date calculated: 02/27/2019 06:18 PM

Code	Description		WU	Price SGD
55 22 55 53	INCLUDES: ADJUST BONNET CLEARANCES RENEW BONNET		5.0	22.50
33 22 33 33	(BONNET REMOVED) INCLUDES: R + R ALL PARTS		3.0	22.00
64 10 55 00	RENEW FRONT SCREEN INCLUDES: R + R A-PILLAR TRIMS, INTERIOR		25.0	112.50
	MIRROR, SUN VISORS AND INTERIOR LAMP	5		21.50
0283 1168	FRONT BUMPER REPAIR R/F UPP SIDE MEMBER REPAIR	5	10.0*	45.00 M
2264	R/OUT/UPP A-PILLAR REPAIR	na	10.0*	
	Labour Cost	Hrs	wu	301.50
	Panel / Mechanical Labour	8.70	87.0	391.50
	Total of Labour			391.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	24.0
	R/F WING NEW PART PAINTING	10.0
	FRONT BUMPER REPAIR PAINT PLASTIC	13.0
	R/OUT/UPP A-PILLAR REPAIR PAINTING <50%	8.0
	L/F WING SURFACE PAINT	5.0
	R/F UPP SIDE MEMBER SURFACE PAINT	4.0
	RIGHT FRONT DOOR SURFACE PAINT	7.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	77.92
0742	R/F WING NEW PART PAINTING	19.61
0283	FRONT BUMPER REPAIR PAINT PLASTIC	29.97
2264	R/OUT/UPP A-PILLAR REPAIR PAINTING <50%	3.55
0741	L/F WING SURFACE PAINT	9.46
1168	R/F UPP SIDE MEMBER SURFACE PAINT	2.49
1482	RIGHT FRONT DOOR SURFACE PAINT	18.92

Claim Reference:

Full Report

Assessment number: SH/2019/057/02/025/OD

Registration: SJK1725J

Version: 1810

Printed: 27/02/2019 6:18 PM

Date calculated: 02/27/2019 06:18 PM

Labour Cost - Paint Factor	45.00 SGD/h	Hrs	wu	Price SGD
Time Paint	15.50 565/11		71.0	
Preparation Main Work Metal		2.10	21.0	94.50
Preparation Comp. Work Plastic		0.80	8.0	36.00
Total	10 WU/h	10.00	100.0	450.00
Material Cost - Paint				Price SGD
New Part Painting				97.53
Repair Painting				3.55
Repair Painting Plastic				29.97
Surface-/Blend Paint				30.87
Material-constant Metal				18.10
Material-constant Plastic				12.70
Total				192.72

Spare Parts

Spare raits				
Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
0330	R/F BUMPER GUIDE	5C6 807 184 A		Pri 25.00
0471	BONNET	5C6 823 031 E		P4 575.00
0562	RIGHT HEADLAMP ASSY			cm 360.00
0742	R/F WING	5C6 821 106 A		A 320.00
Hard California				
0990	R/LOCK CARRIER STRUT			
1401	WINDSCREEN	5C6 845 011 BD NVB		650.00
1405	APPLICATOR	D 009 500 25		0.00
1409	CUTTING FILAMENT	357 853 999 B		0.00
1410	CLEANING SOLUTION	D 009 401 04		0.00
1411	WINDSCREEN BOND KIT	D 004 660 M2		0.00
1414	WINDSCREEN PRIMER	D 009 200 02		0.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,962.00
u: Used parts	Addition(+10.00%)			196.20
	Total			2,158.20

Claim Reference:

Full Report Registration: SJK1725J

Assessment number: SH/2019/057/02/025/OD

Version: 1810

Printed: 27/02/2019 6:18 PM

SCD

SCD

Date calculated: 02/27/2019 06:18 PM

Final Calculation

	SGD	360
Parts	1,962.00	
Addition(+10.00%)	196.20	
Total Parts	2	,158.20
Labour Time Base 10 WU/h		
Total 87.0 WU X 45.00 SGD/h	392.50 20150	
Total of Labour		391.50
Paint Work Time Base 10 WU/h		
Labour Cost 100.0 WU X 45.00 SGD/h	450.00	
Material Cost	192.72	
Total Paint Including Material		642.72
Repair Cost Excludes GST	3	,192.42
GST (+7.0%)		223.47
Repair Cost Included GST	3	,415.89

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

LEK Auto Consultable hence notify the Repairer of the following: + To returney before/after spray painting To display damaged part(s) during manney . Paids prices are subject to confirmation Their party survey is on a "Williast Projector" being No illigal modification(s) is allowed · Exportantes books must be nounered and is addput to first approval from Inscistor Concern Actinoxidaged by Ramilier

408933

Claim Reference:

Full Report Registration: SJK1725J

Assessment number: SH/2019/057/02/025/OD

Version: 1810

Date calculated: 03/20/2019 10:44 AM

Printed: 20/03/2019 11:02 AM

Summary Information

Claim

Location: Printed by: Singapore (SG)

KK LAU

Work Provider: Currency:

Date of Incident:

Hire Car Start: Hire Car End:

AXA Insurance Pte Ltd

SGD

2019-02-26

Vehicle Details

Actual Repair Days:

Estimated Repair Time:

Claim Reference:

Vehicle

Manufacturer:

VW

Model: Sub Model: JETTA (163) BASE MODEL

Model Sheet Number:

06 J7 01

Registration:

SJK1725J

VIN number:

WVWZZZ16ZFM028645

Odometer:

Model Specs

FROM 01/2015 R/DOOR MIRROR W/ANG LIGHT SWITCHING AUTO

DOOR TRIM IMIT LEATH

7-SPEED DSG

TYRES 205/55 VR 16 STABILITY PROGRAM

TWO COAT METALLIC

PAINTED DOOR MIRROR HEATED DOOR MIRRORS

LED TAILLAMP

ON-BOARD COMPUTER SERVOTRONIC WHEELS 6.5J X 16

HEAD AIRBAG NEW ATT/PARTS PAINT KEYLESS ENTRY

L/CONVEX DOOR MIRROR 8 SPEAKER

R/FOG LAMP

FRONT CENTRE ARMREST

1.4 LTR 90 KW

SPARE WHEEL STEEL

HD COOLING

CLIMATIC

EQUIPMENT CLOTH ALTERNATOR 140A

PASS AIRBAG SWITCH

FRONT BRAKES 288X25 SEAT MOUNTING ISOFIX

408933

Claim Reference:

Assessment number: SH/2019/057/02/025/OD

Version: 1810

Date calculated: 03/20/2019 10:44 AM

Full Report

Registration: SJK1725J

Printed: 20/03/2019 11:02 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody



Labour	Time Base 10 WU/h	Price = 45.	00 SGD/h
Code	Description	wu	Price SGD
63 29 19 00	R + R FRONT BUMPER COVER	6.0	27.00
50 55 19 50	R + R R/F WING (BUMPER COVER REMOVED) INCLUDES: R + R WHEELHOUSE SHELL	7.0	31.50
94 15 19 60	R + R R/HEADLAMP (FRONT BUMPER COVER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.50
94 15 16 00	ADJUST HEADLAMPS	3.0	13.50
55 22 19 00	REMOVE/REFIT BONNET PANEL INCLUDES: ADJUST BONNET CLEARANCES	7.0	31.50
55 22 55 53	RENEW BONNET (BONNET REMOVED) INCLUDES: R + R ALL PARTS	5.0	22,50
64 10 55 00	RENEW FRONT SCREEN INCLUDES: R + R A-PILLAR TRIMS, INTERIOR MIRROR, SUN VISORS AND INTERIOR LAMP	25.0	112.50

408933

Claim Reference:

Full Report

Assessment number: SH/2019/057/02/025/OD

Registration: SJK1725J

Version: 1810

Date calculated: 03/20/2019 10:44 AM

Printed: 20/03/2019 11:02 AM

Code	Description		WU	Price SGD
0990	R/LOCK CARRIER STRUT REMOVE AND REFIT		3.0*	13.50
0283	FRONT BUMPER REPAIR		5.0*	22.50
1168	R/F UPP SIDE MEMBER REPAIR		5.0*	22.50
	Labour Cost	Hrs	wu	
	Panel / Mechanical Labour	6.70	67.0	301.50
	Total of Labour			301.50

D	3	ě	n	ч	۴
	a	۰			٠
_	-	-	_	÷	-

Time Basis 10WU/h		
wu	Price SGD	
24.0		
10.0		
13.0		
8.0*		
5.0		
4.0		
7.0		
	13.0 8.0* 5.0 4.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	77.92
0742	R/F WING NEW PART PAINTING	19.61
0283	FRONT BUMPER REPAIR PAINT PLASTIC	29.97
2264	R/OUT/UPP A-PILLAR REPAIR PAINTING <50%	3.55
0741	L/F WING SURFACE PAINT	9.46
1168	R/F UPP SIDE MEMBER SURFACE PAINT	2.49
1482	RIGHT FRONT DOOR SURFACE PAINT	18.92

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	45.00 SGD/h			
Time Paint			71.0	
Preparation Main Work Metal		2.10	21.0	94.50
Preparation Comp. Work Plastic		0.80	8.0	36.00
Total	10 WU/h	10.00	100.0	450.00

408933

Claim Reference:

Full Report

Assessment number: SH/2019/057/02/025/OD

Registration: SJK1725J

Version: 1810

Date calculated: 03/20/2019 10:44 AM

Printed: 20/03/2019 11:02 AM

Material Cost - Paint	Price SGD
New Part Painting	97.53
Repair Painting	3.55
Repair Painting Plastic	29.97
Surface-/Blend Paint	30.87
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	192.72

Spare Parts

Spare raits				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0330	R/F BUMPER GUIDE	5C6 807 184 A		25.00
0471	BONNET	5C6 823 031 E		575.00
0562	RIGHT HEADLAMP ASSY	5C8 941 006		360.00
0742	R/F WING	5C6 821 106 A		320.00
1401	WINDSCREEN	5C6 845 011 BD NVB		650.00
1405	APPLICATOR	D 009 500 25		0.00
1409	CUTTING FILAMENT	357 853 999 B		0.00
1410	CLEANING SOLUTION	D 009 401 04		0.00
1411	WINDSCREEN BOND KIT	D 004 660 M2		0.00
1414	WINDSCREEN PRIMER	D 009 200 02		0.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,930.00
u: Used parts	Addition(+10.00%)			193.00
	Total			2,123.00

Extras		
Code	Description	Price SGD
2264	[LI]: R/OUT/UPP A-PI LLAR:	0.00*

408933

Claim Reference:

Full Report

Assessment number: SH/2019/057/02/025/OD

Registration: SJK1725J Printed: 20/03/2019 11:02 AM

Version: 1810

Date calculated: 03/20/2019 10:44 AM

Final Calculation

rillai Calculation		
	SGD	SGD
Parts	1,930.00	
Addition(+10.00%)	193.00	
Total Parts		2,123.00
Labour Time Base 10 WU/h		
Total 67.0 WU X 45.00 SGD/h	301.50	
Total of Labour		301.50
Total Of Extras		0.00
Paint Work Time Base 10 WU/h		
Labour Cost 100.0 WU X 45.00 SGD/h	450.00	
Material Cost	192.72	
Total Paint Including Material		642.72
Repair Cost Excludes GST		3,067.22
GST (+7.0%)		214.71
Repair Cost Included GST		3,281.93

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS



日美汽車私人有限公司

JAE AUTO PTE LTD

BIK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 198307741M



Arrange By













Wiper blade: NWB (Nippon Wiper blade), Siliper Made in Korea Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY

575722

TEL: 64534730 FAX: 64571931/62985995

ATTN: DORRIS ANG, CYNTHIA

TAX INVOICE	: AR	201903-0554
DATE	:	06/03/2019
CUSTOMER ID	1	S&H001
VEH REG. NO.	1	SJK17251
TERMS	:	30 days

PO NO.

PAGE NO.

Page 1 of 1

CURR.

SGD

eo erocum	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
SQ STOCKID 1. 5C6823031C/B/D/E JETTA	BONNET	WH WH	1	575.00	575.00
2. 5C6821106/A JETTA 2011	FENDER RH	WH WH	1	320.00	320.00
3. 5C6807184 JETTA 1.4	FRT BUMPER RETAINER RH	WH WH	1	25,00	25.00
4. 5C8941006 JETTA 1.4	HEADLAMP RH *941	WH WH	1	360.00	360.00



SUB-TOTAL : ADD GST 7.00 % 1.280.0 89.6

E.&OE

TOTAL AMOUNT SGD

1,369.6

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : WENWEI

This is computer generated document, No signature is required.



Goods Received in Good Order

Signature / Co Stampy Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Bix 3016 LIEF ROAD 1 #01-121 SINGAPORE 400M0 TEL: 87453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WHO EDPECT SUANA AND DESCRIPTION / ETAS SEC

M CO (1)

400

....









ant Directs \$417 9794

Dept Direct; 6417 6100

Dept Describer 2 Store

Wiper blade: NWB (Nippon Wiper blade), Bloper I Made in Korea Force: (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Jaco)

S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02

SIN MING AUTOCITY

575722

TEL: 64534730 FAX: 64571931/62985995

ATTN : DORRIS ANG, CYNTHIA

TAX INVOICE AR201903-0228 DATE 05/03/201

CUSTOMER ID : S&H00
VEH REG. NO. SJK1725
TERMS 30 day

PO NO.

PAGE NO. : Page 1 of

CURR. SGI

 SQ STOCKID
 DESCRIPTION
 StkLoc
 QTY
 U/PRICE
 AMOUN

 1. 5C6845011 NVB/BD NVB FRT W/S GLASS (NS)
 MO
 1
 650.00
 650.0

 JETTA 13"
 U86
 U86
 1
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0
 0</td

07 PMA

> SUB-TOTAL : ADD GST 7.00 %

650.00 45.50

E. & O.E

TOTAL AMOUNT SGD

SGD: 695.51 [E] 05/03/2019 2:42:43Plv

[P] 05/03/2019 2:44:14PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: ANG

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

Claim Reference:

Full Report

Assessment number: SH/2019/057/02/025/OD

Registration: SJK1725J Printed: 20/03/2019 10:44 AM

Version: 1810

Date calculated: 03/20/2019 10:44 AM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

Hire Car End:

AXA Insurance Pte Ltd

Printed by: KK LAU

Claim Reference: Estimated Repair Time:

Actual Repair Days:

Currency: Date of Incident: Hire Car Start:

SGD 2019-02-26

Vehicle Details

Vehicle

Manufacturer:

VW

Model: Sub Model: JETTA (163) BASE MODEL

Model Sheet Number:

06 J7 01 SJK1725J

Registration: VIN number:

WVWZZZ16ZFM028645

Odometer:

Model Specs

FROM 01/2015 R/DOOR MIRROR W/ANG

LIGHT SWITCHING AUTO DOOR TRIM IMIT LEATH

7-SPEED DSG

TYRES 205/55 VR 16 STABILITY PROGRAM TWO COAT METALLIC PAINTED DOOR MIRROR HEATED DOOR MIRRORS

LED TAILLAMP

ON-BOARD COMPUTER SERVOTRONIC

WHEELS 6.5J X 16 HEAD AIRBAG

NEW ATT/PARTS PAINT

KEYLESS ENTRY

L/CONVEX DOOR MIRROR 8 SPEAKER

R/FOG LAMP

1.4 LTR 90 KW

SPARE WHEEL STEEL

HD COOLING

CLIMATIC

EQUIPMENT CLOTH FRONT CENTRE ARMREST ALTERNATOR 140A PASS AIRBAG SWITCH FRONT BRAKES 288X25

SEAT MOUNTING ISOFIX

408933

Claim Reference:

Full Report Registration: SJK1725J

Assessment number: SH/2019/057/02/025/OD

Version: 1810

Date calculated: 03/20/2019 10:44 AM

Printed: 20/03/2019 10:44 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

AII Underbody



Labour

1445555555555555	Time Base 10 WU/h	Price = 45.	00 SGD/h
Code	Description		Price SGD
63 29 19 00	R + R FRONT BUMPER COVER	6.0	27.00
50 55 19 50	R + R R/F WING (BUMPER COVER REMOVED) INCLUDES: R + R WHEELHOUSE SHELL	7.0	31.50
94 15 19 60	R + R R/HEADLAMP (FRONT BUMPER COVER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.50
94 15 16 00	ADJUST HEADLAMPS	3.0	13.50
55 22 19 00	REMOVE/REFIT BONNET PANEL INCLUDES: ADJUST BONNET CLEARANCES	7.0	31.50
55 22 55 53	RENEW BONNET (BONNET REMOVED) INCLUDES: R + R ALL PARTS	5.0	22.50
64 10 55 00	RENEW FRONT SCREEN INCLUDES: R + R A-PILLAR TRIMS, INTERIOR MIRROR, SUN VISORS AND INTERIOR LAMP	25.0	112,50

408933

Claim Reference:

Full Report

Assessment number: SH/2019/057/02/025/OD

Registration: SJK1725J

Version: 1810

Date calculated: 03/20/2019 10:44 AM

Printed: 20/03/2019 10:44 AM

Code	Description		WU	Price SGD
0990	R/LOCK CARRIER STRUT REMOVE AND REFIT		3.0*	13.50
0283	FRONT BUMPER REPAIR		5.0*	22.50
1168	R/F UPP SIDE MEMBER REPAIR		5.0*	22.50
	Labour Cost	Hrs	wu	
	Panel / Mechanical Labour	6.70	67.0	301.50
	Total of Labour			301.50

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	24.0
	R/F WING NEW PART PAINTING	10.0
	FRONT BUMPER REPAIR PAINT PLASTIC	13.0
	R/OUT/UPP A-PILLAR REPAIR PAINTING <50%	8.0*
	L/F WING SURFACE PAINT	5.0
	R/F UPP SIDE MEMBER SURFACE PAINT	4.0
	RIGHT FRONT DOOR SURFACE PAINT	7.0
	UTOT TANAMATA CONTRACTOR STATE OF THE STATE	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	77.92
0742	R/F WING NEW PART PAINTING	19.61
0283	FRONT BUMPER REPAIR PAINT PLASTIC	29.97
2264	R/OUT/UPP A-PILLAR REPAIR PAINTING <50%	3.55
0741	L/F WING SURFACE PAINT	9.46
1168	R/F UPP SIDE MEMBER SURFACE PAINT	2.49
1482	RIGHT FRONT DOOR SURFACE PAINT	18.92

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	45.00 SGD/h			
Time Paint			71.0	
Preparation Main Work Metal		2.10	21.0	94.50
Preparation Comp. Work Plastic		0.80	8.0	36.00
Total	10 WU/h	10.00	100.0	450.00

Claim Reference:

Full Report

Assessment number: SH/2019/057/02/025/OD

Registration: SJK1725J

Version: 1810

Printed: 20/03/2019 10:44 AM

Date calculated: 03/20/2019 10:44 AM

Price SGD Material Cost - Paint 97.53 New Part Painting 3.55 Repair Painting 29.97 Repair Painting Plastic 30.87 Surface-/Blend Paint 18.10 Material-constant Metal 12.70 Material-constant Plastic 192.72 Total

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
couc			37078	
0330	R/F BUMPER GUIDE	5C6 807 184 A		25.00
0471	BONNET	5C6 823 031 E		575.00
0562	RIGHT HEADLAMP ASSY	5C8 941 006		360.00
0742	R/F WING	5C6 821 106 A		320.00
1401	WINDSCREEN	5C6 845 011 BD NVB		650.00
1405	APPLICATOR	D 009 500 25		0.00
1409	CUTTING FILAMENT	357 853 999 B		0.00
1410	CLEANING SOLUTION	D 009 401 04		0.00
1411	WINDSCREEN BOND KIT	D 004 660 M2		0.00
1414	WINDSCREEN PRIMER	D 009 200 02		0.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,930.00
u: Used parts	Addition(+10.00%)			193.00
	Total			2,123.00

			ra	
-	•	•		-

Code	Description	Price SGD
2264	[LI]: R/OUT/UPP A-PI LLAR:	0.00*

Page 4 of 5

Claim Reference:

Full Report

Assessment number: SH/2019/057/02/025/OD

Registration: SJK1725J

Printed: 20/03/2019 10:44 AM

Version: 1810

Date calculated: 03/20/2019 10:44 AM

Final Calculation

Title Galletian	SGD	SGD
Parts	1,930.00	
Addition(+10.00%)	193.00	
Total Parts		2,123.00
Labour Time Base 10 WU/h		
Total 67.0 WU X 45.00 SGD/h	301.50	
Total of Labour		301.50
Total Of Extras		0.00
Paint Work Time Base 10 WU/h		
Labour Cost 100.0 WU X 45.00 SGD/h	450.00	
Material Cost	192.72	
Total Paint Including Material		642.72
Repair Cost Excludes GST		3,067.22
GST (+7.0%)		214.71
Repair Cost Included GST		3,281.93

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS