## **Premium Automobiles**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### **Telefax**

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323

**Fax No** : 6841 1183 **Reference** : PA/OD/0272/2019/GW

**Date** : 2-Mar-19

Vehicle not in workshop. Kindly arrange for survey.

#### **AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Peh Chai Peng

Address : Blk 642 A Punggol Drive

: #11-345

Singapore 821642

Telephone : HP +65 81332230 Type of Claim : Own Damage Claims

 Policy No.
 : 2100445230-03

 Vehicle No
 : SGY 1128 U

 Model Code
 : A3 Sedan 1.4 TFSI

 Model / Year
 : 30/12/2015

 Engine No
 : CZC 504868

Chassis No : WAUZZZ8V5G1052582

Mileage :

Date In : Liability :

Excess Cost :

Estimated By : Johnny Boo / Allan Wu

Accident Date : 27-Feb-19

# Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

### Estimated Labour Charges for Accident Vehicle SGY 1128 U

| S/n | Nature of Jobs  |     | Estimated<br>Charges  | Surveyor's<br>Recommendation          |
|-----|---|-----|-----------------------|---------------------------------------|
| 1   | To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.          | S/N | \$<br>360.00 <b>~</b> | · · · · · · · · · · · · · · · · · · · |
| 2   | To dismantle and renew front bumper and rhs front fender. Re-organise crash management components. Reinstall all parts removed. |     | \$<br>1,800.00 /      | ر د د <i>ا</i>                        |
| 3   | To respray front bumper and rhs front fender.   |     | \$<br>1,500.00        | 1100                                  |
| 4   | To carry out diagnostic check.  | S/N | \$<br>192.00          | /                                     |
|     | TOTAL LABOUR CHARGES  | :   | \$<br>3,852.00        |                                       |

# **Premium Automobiles**

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

## Material List for Accident Vehicle Regn No. SGY 1128 U

|     |  |             | <b>Damaged Parts &amp; Prices</b> |        |  |  |
|-----|--|-------------|-----------------------------------|--------|--|--|
| S/N | Parts Description  | -           | S/Nett                            | Remark |  |  |
|     |  |             |                                   |        |  |  |
| 1   | FRONT BUMPER Page  | \$          | 1,830.00                          | ·.     |  |  |
| 2   | FRONT BUMPER FIXING PARTS  | \$          | 170.00 🖈                          |        |  |  |
| 3   | FRONT BUMPER COVER TRIM-RH   | \$          | 148.00 <b>x</b>                   |        |  |  |
| 4   | FRONT BUMPER GUIDE SECTION-RH  | \$          | 35.00 🗜                           |        |  |  |
| 5   | FRONT BUMPER AIR GUIDE GRILLE-RH   | \$          | 99.00 🖈                           |        |  |  |
| 6   | FRONT FENDER-RH  | \$          | 778.00                            |        |  |  |
| 7   | FRONT FENDER ATTACHEMENT PART-RH ?   | \$          | 65.00 ?                           |        |  |  |
| 8   | FRONT FENDER BRACKET-RH MM   | \$          | 35.00 🗡                           |        |  |  |
| 9   | FRONT FENDER BRACE-RH  | \$          | 88.00 ¥                           |        |  |  |
| 10  | FRONT WHEEL HOUSING LINER-RH 2   | \$          | 158.00 🗶                          |        |  |  |
| 11  | WHEEL HOSUING LINER ATTACHMENT PARTS $\mathcal{V}$   | \$          | 81.00 <b>+</b>                    |        |  |  |
| 12  | SUNDRIES ?   | \$          | 300.00                            |        |  |  |
|     | TOTAL SPARE PARTS CHARGES :  | \$ 3        | 3,787.00                          |        |  |  |
|     | TOTAL LABOUR CHARGES   | \$ 3        | 3,852.00                          |        |  |  |
|     | GRAND TOTAL  | \$ 7,639.00 |                                   |        |  |  |
|     | All charges are not inclusive of GST.  Legend: Remarks (OK) = Approved, Remarks (X) = Not approved |             |                                   |        |  |  |

## **Premium Automobiles**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

**Telefax** 

Name

Surveyed Date
Authorised Date

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorsed Ris, 04 Pays.

**Please Note** 

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant