

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: SNM19D201065C02 Date: 21st Feb 2020

Our Ref: CS1/CTI19004104/Eqd3e2

## M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBK 9482B INSURED VEHICLE: GX 4026R ACCIDENT DATE: 24/08/2018

We thank you for your instruction on 06/03/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBK 9482B from M/s Prudent Adjustors Services.
- b) Final Repair Bill of FBK 9482B from M/s Yew Heng Group Pte Ltd.
- c) Singapore Accident Statement of Vehicles FBK 9482B.
- d) Police Report of Vehicles FBK 9482B, FR 2113D and GX 4026R.
- e) Colour damaged vehicle photographs of FBK 9482B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: FBK 9482B

Make & Model

: Honda CB400SF Manual

Year of Registration

: 2016

Chassis Number

: NC421605041

**Engine Capacity** 

: 399 cc

- 2. We recommend that the repairs of the entire damage require about <u>2 (Two)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.