

TPAXA Henry Hee  
Poh Lin

Subject: GBD 8890A.

Date:

Toyota Dyna.  
KDY231898020.

|                                           |                                     |
|-------------------------------------------|-------------------------------------|
| Rear Number Plate Bert                    | 30(SN) ✓                            |
| Rear Number Plate Holder Rehd             | 30(SN) ✓                            |
| Rear Number Plate Bracket. Bert           | 196.90 ✓                            |
| Rear Number Plate Lamp. Hee nu            | 83.90 x                             |
| Reverse Sensor Ring                       | 280(SN) ✓ 200(SN)                   |
| Tailhup x02 Lt                            | 285.3x2 = 570.60 ✓                  |
| Tailhup Panel x02 Repair                  | 119.30x2 = 238.60 x                 |
| Stopper x02 Hee nu                        | 20x2 = 40(SN) x                     |
| Stopper Bracket x02 RH Bert               | 237.6x2 = 475.20. 237.60            |
| Tailgate Dented.                          | 1588 ✓                              |
| Tailgate Hinge x04 2 pieces bert          | 76.2x4 = 304.80 <sup>152.40</sup> x |
| Tailgate Side Lock x02 Bert               | 119.3x2 = 238.60 ✓                  |
| Tailgate Inner Aluminium Panel NMM        | 500(SN) x                           |
| Tailgate Inner Aluminium Panel Rivets NMM | <del>50(SN) x</del> 30(SN)          |
| Tailgate Reflective Stickers. NMM         | 100(SN) 30(SN).                     |
| 70km/h Stickers ?                         | 10(SN) ✓                            |
| 13 Pax Stickers. Hee                      | 10(SN) ✓                            |
| Dyna Stickers.                            | 45 ✓                                |
| Tailgate lower Panel Repair               | 545.10. x                           |
| Footrest Bracket. Bert                    | 200(SN) 120(SN)                     |
| Rear Exhaust Pipe. 2 x P                  | 585.20 x                            |
| Rear Exhaust Mounting Jdn                 | 38 x                                |

Tailgate  
Lower  
Panel Reflector  
x02  
30x45.60(SN)  
cluded

3029.10 S.N 520  
2281.82

Subject: 6BD8890A.

Date:

Panel Beating  
Spray Painting  
Wiring  
To underseal  
To remove reverse sensor  
To remove exhaust pipe

~~1200~~ 700.  
~~1000~~ 600  
~~50~~ 30  
150 X  
~~100~~ 50  
150 X

1380

total 4171.82  
L/S 3.3k  
05 days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: