

SM SPRAY PAINTING

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	SMH9544S	Excess.	NIL
Policy No.	5051940058-07	Coverage.	
Claiming Against.	SHD4783G		
Insured Under.	NTUC		

Vehicle Particulars & Condition

Make & Model	TOYOTA LEXUS GS350 LUXURY AUTO
Engine No.	2GR8821669
Chassis No.	JTHBE1BL105029029
Odometer	
Engine CC.	3456
Year Of Reg.	2013
Colour.	BLACK
Parf/COE Rebate.	\$ 99,957.00

*Not Authorized
date
2/3/19
6/3/19
Take photo. After rep
1 2 day.*

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

FRONT LH PORTION

General Information

Accident Date. 2/3/2019
Survey held at

Yew Tee Automobile Tech Pte Ltd
SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S417800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remarks

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR:

Days

SM SPRAY PAINTING

Qty.	Description Of Parts	Pricing
1	FRONT BUMPER	DIS \$ 783.21 ✓
1	FRONT BUMPER SENSOR LH	shut \$ 327.25 ✓
1	FRONT BUMPER SENSOR CENTRE LH	shut \$ 327.25 ✓
1	FRONT BUMPER TOWING COVER LH	Tron \$ 32.10 ✓
1	FRONT BUMPER FOG LAMP LH	320 \$ 264.50 ✓
1	FRONT BUMPER FOG LAMP GARNISH LH	Tron \$ 72.40 ✓
1	FRONT BUMPER FOG LAMP CHROME RIM LH	320 \$ 82.10 ✓
1	FRONT BUMPER CENTRE GRILLE	Tron \$ 164.12 ✓
1	FRONT GRILLE	CM \$ 878.18 ✓
1	FRONT GRILLE CHROME	CM \$ 369.10 ✓
1	FRONT GRILLE LOGO	REC \$ 459.90 ✓
1	FRONT GRILLE LOGO BASE	\$ 150.00 ?
1	FRONT GRILLE TOP SEAL	ner \$ 49.10 ✓
1	FRONT BUMPER SIDE RETAINER LH	CM \$ 72.40 ✓
1	FRONT BUMPER BRACKET LH	320 \$ 64.10 ✓
1	FRONT BUMPER SENSOR WIRE HARNESS	\$ 429.10 ?
1	FRONT BUMPER NOZZLE COVER LH	Tron \$ 25.70 ✓
1	FRONT BUMPER INNER SPONGE	Tron \$ 111.80 ✓
1	FRONT BUMPER REINFORCEMENT	\$ 429.10 ?
1	FRONT BUMPER REINFORCEMENT STAY LH	\$ 221.90 ?
1	FRONT BUMPER REINFORCEMENT STAY RH	11 \$ 221.90 X ?
1	FRONT BUMPER AIR DUCT FOR BRAKE LH	\$ 155.91 ?
1	FRONT HEADLAMP NOZZLE JET LH	CM \$ 537.10 ✓
1	FRONT HEADLAMP NOZZLE HEAD LH	CM \$ 72.40 ?
1	FRONT HEADLAMP NOZZLE HOSE LH TO RH	\$ 72.40 ✓
1	FRONT HEADLAMP LH	320 \$ 3,633.00 ✓
1	FRONT HEADLAMP BALLAST LH	\$ 673.00 ?
1	FRONT HEADLAMP HID BULB LH	320 \$ 680.80 ✓
1	FRONT HEADLAMP WIRE HARNESS	\$ 2,321.70 ?
1	BONNET	320 \$ 2,523.10 ✓
1	BONNET HINGE LH	320 \$ 72.40 ✓
1	BONNET HINGE RH	320 \$ 72.40 ✓
1	BONNET INSULATOR	Tron \$ 421.70 ✓
1	BONNET SEAL	ner \$ 72.40 ✓
1	FRONT FENDER LH	320 \$ 821.70 ✓
1	FRONT FENDER INNER SHIELD LH	Tron \$ 320.56 ✓
1	FRONT FENDER TOP GARNISH INNER LH	Tron \$ 152.40 ✓
1	FRONT FENDER TOP GARNISH INNER SEAL LH	Tron \$ 137.40 ✓
1	FRONT WHEEL RIM LH	10/320 \$ 2,211.70 8000.2
1	FRONT SHOCK ABSORBER LH	11 \$ 724.10 X
1	FRONT LOWER ARM LH	\$ 679.10 ?

SM SPRAY PAINTING

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	FRONT KNUCKLE ARM LH	\$ 592.40 ?
1	FRONT WHEEL HUB LH	\$ 691.70 ?
1	FRONT KNUCKLE ARM BEARING LH	\$ - ?
1	FRONT CROSSMEMBER	11 \$ 1,855.61 X
1	FRONT DASHBOARD	Torn \$ 1,736.50 /
1	STEERING AIR BAG	Accident \$ 1,873.66 /
1	DRIVER KNEE AIR BAG	Accident \$ 1,603.11 /
1	PASSENGER AIR BAG	Accident \$ 2,532.05 /
1	PASSENGER KNEE AIR BAG	Accident \$ - /
1	FRONT SEAT BELT LH	Accident \$ 842.71 /
1	FRONT SEAT BELT RH	Accident \$ 842.71 /
1	AIR BAG ECU	Accident \$ 721.70 /
1	FRONT CHASSIS AIR BAG SENSOR LH	Accident \$ 321.50 /
1	ENGINE BAY SIDE COVER LH	CR \$ 43.70 /
1	FRONT WINDSCREEN GLASS	320 \$ 1,981.00 /
1	FRONT WINDSCREEN GLASS MOULDING TOP	Accident \$ 30.00 /
1	FRONT WINDSCREEN RAIN SENSOR GEM	11 \$ - X
1	FRONT REAR VIEW MIRROR BRACKET	11 \$ - X
1	FRONT SIDE MIRROR LH CHROME MLD	11 \$ - X
1	AIR CON CONDENSER	\$ 1,541.39 ?
1	AIR CON CONDENSER SIDE COVER LH	721 \$ 72.10 /
1	FUSE BOX ASSY	11 \$ 3,260.70 X
1	FRONT WASHER TANK	1713 \$ 184.60 /
1	FRONT WASHER TANK TOP FILLER	\$ 41.70 ?
1	FRONT WASHER TANK MOTOR	232 \$ 234.65 /
1	FRONT WASHER TANK MOTOR FOR HEADLAMP NOZZLE	241 \$ 241.90 ?
1	FRONT WASHER TANK MOTOR FOR HEADLAMP NOZZLE HOSE	\$ 120.50 ?
1	FRONT SUPPORT PANEL	241 \$ 1,672.40 /
1	FRONT SUPPORT PANEL TOP GARNISH	241 \$ 286.41 /

List items \$ 45,215.18

Less 25% \$ 11,303.80

Sub Total \$ 33,911.39

SM SPRAY PAINTING

Qty.	Description Of Parts	Pricing
1	FRONT BUMPER CLIPS	RM \$ 25.00 ✓
1	FRONT NUMBER PLATE	320 \$ 45.00 40
1	BONNET INSULATOR CLIPS	RM \$ 45.00 ✓
1	FRONT FENDER INNER SHIELD CLIP	RM \$ 38.00 ✓
1	ERP BRACKET	RM \$ 12.00 ✓
1	FRONT WINDSCREEN SEALANT	RM \$ 60.00 40
1	FRONT TYRE LH 27 220	147 \$ 270.00 602
1	FRONT SUPPORT PANEL TOP GARNISH CLIP	RM \$ 20.00 ✓
1	FRONT FENDER TOP SIDE GARNISH CLIP	RM \$ 15.00 ✓
S/N		\$ 530.00

LABOUR

To apply undercoating on the repaired and replaced panel for rust protection.	\$ 100.00 ✓
To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 120.00 50
To Carry-Out Body Cavity Preservation.	\$ 60.00 ✓
To remove and refit front bumper sensors.	\$ 80.00 50
To dismantle and refit front windscreen glass.	\$ 100.00 ✓
Computer wheel alignment	\$ 100.00 ✓
To dismantle & refit front undercarriage	\$ 180.00 120
Computer set fault code, programming & coding	\$ 350.00 300
To dismantle front dashboard	\$ 350.00 260
To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 1,800.00 1200
To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 1,200.00 1100

LABOUR \$ 4,440.00

Sub Total. \$ 4,440.00

7% GST \$ 310.80

Grand Total \$ 4,750.80

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.