

Steve (LKK) w/L Mr. Jire 5/3/19 10.30 am
 83298813 19 days L/S

華豐

Name: ASHWANDI BIN ROSLAN Rec AF spray
 Address: Blk 223A Jurong East Street 21 #03-847 Singapore 601223
 Policy Number: P10080772R00

Date : 1/3/19
 Vehicle No : SJH5331B

Quotation for Reinstste / Repairs for vehicle

Parts Replacement - Cost Price

1 Pc	Front Bonnet / DD	\$	620.00
1 Pc	Front Bonnet Lock / BT	\$	85.00
1 Pc	Front R/H Bonnet Hinge / BT	\$	65.00
1 Pc	Front L/H Bonnet Hinge / BT	\$	65.00
1 Pc	Front Bumper / DD	\$	480.00
1 Pc	Front R/H Bumper Bracket / BR	\$	28.00
1 Pc	Front L/H Bumper Bracket / BR	\$	28.00
1 Pc	Front Support Panel / DD	\$	580.00
1 Pc	Front R/H Headlamp / BR	\$	520.00
1 Pc	Front L/H Headlamp / BR	\$	520.00
1 Pc	Front Bumper Grille / BR	\$	580.00
1 Pc	Front L/H Fender / DD	\$	255.00
1 Pc	Radiator / DD	\$	650.00
1 Pc	Air Condenser / DD	\$	680.00
1 Pc	Air Con Fan Motor / NAI	\$	185.00
1 Pc	Air Con Fan Blade / NAI	\$	85.00
1 Pc	Radiator Cowling / CR4	\$	155.00
1 Pc	Radiator Spare Tank / NAI	\$	105.00
1 Pc	Front Bumper Reinforcement / DD	\$	220.00
1 Pc	Throttle Housing / NAI	\$	750.00
1 Pc	Front L/H Fog Lamp / NAI	\$	220.00
1 Pc	Front Number Plate / BR	\$	30.00
1 Pc	Front Bumper Sponge / NAI	\$	110.00
1 Pc	Front Bumper Lower Cover / NAI	\$	85.00
1 Pc	Front Bonnet Insulator / CR4	\$	105.00
1 Pc	Front Bumper Lower Grille / BR	\$	125.00
1 Pc	Front Support Panel Top Garnish / CR4	\$	80.00
1 Pc	Rear Bumper / BR	\$	550.00
1 Pc	Rear R/H Bumper Retainer / BR	\$	28.00
1 Pc	Rear L/H Bumper Retainer / BR	\$	28.00
1 Pc	Rear Boot / DD	\$	780.00
1 Pc	Rear R/H Boot Hinge / BT	\$	55.00
1 Pc	Rear L/H Boot Hinge / BT	\$	55.00
1 Pc	Rear Boot Lock / BT	\$	85.00
1 Pc	Rear End Panel / DD	\$	480.00
1 Pc	Rear Flock Panel Insulator / NEC	\$	680.00
1 Pc	Rear R/H Tail Lamp / BR	\$	155.00
1 Pc	Rear L/H Tail Lamp / BR	\$	155.00
1 Pc	Rear R/H Side Lamp / BR	\$	120.00
1 Pc	Rear L/H Side Lamp / BR	\$	120.00

WAH HONG

1 Pc	Rear Exhasut Silencer / 00	\$	820.00
1 Pc	Rear Exhasut Center Pipe / 00	\$	850.00
1 Pc	Rear Exhasut Heat Shield / 00	\$	830.00
1 Pc	Rear Exhasut Rubber Mounting / TN	\$	16.00


Sub-Total : \$ 13,218.00

MISC & Labour & Charges

1 job	remove and replace all parts mentioned above and knocking and straighten up the necessary affected areas	\$	2,100.00 2000
1 job	spray painting on affected areas	\$	1,300.00

Labour's Total : \$ 3,400.00
Sub-Total : \$ 16,618.00
GST 7% : \$ 1,163.26
Grand Total : \$ 17,781.26

Thank You
Your Faithfully,




Michael Tee
Wah Hong Motors & Credit Pte Ltd
Tel : 6773 7377 Fax : 6896 6321

Email : michael@wahhong.sg