



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

TP INSURER:
LEE KAI HENG

India International Insurance Pte Ltd (HQ)

Singapore

Claimant Insurer:

Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP 0319-5422
Policy No:		Date of Loss:	01/03/2019
Vehicle Reg. No.:	SBL1111U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TAN SOON KIAT		
Make/Model:	TOYOTA VOXY HYBRID V, 1.8 (A)	Vehicle Reg. Date:	02/08/2017
Vehicle Colour:	WHITE	Chassis No:	ZWR800258040
Engine No:	2ZR1967339		
Odometer:	34707 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336		
Remarks:	VEHICLE NOT IN WORKSHOP		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	5,083.65
Miscellaneous Items	230.00
Labour	1,150.00
Paintwork Labour	800.00
Towing	0.00
Gross Total (\$\$)	7,263.65
+ GST 7.00% (\$\$)	508.46
Nett Amount (\$\$)	7,772.11

This claim is handled by: SOO LEONG KEAT

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Mar 2019)**Parts:** M1-MPV TOYOTA VOXY HYBRID V 1.8 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Car Care Pte Ltd/SBL1111U/05/03/2019 14:32**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR BOOT <i>12/201</i>	25.00	0.00	*1,680.40 FL ✓
2	1	NA	*REAR BOOT RUBBER	25.00	0.00	*380.60 FL ?
3	1	NA	*REAR BOOT TOP LOCK <i>17</i>	25.00	0.00	*360.70 FL X
4	1	NA	*REAR BOOT BOTTOM LOCK <i>17</i>	25.00	0.00	*130.40 FL X
5	1	NA	*REAR BOOT TOYOTA LOGO <i>17</i>	25.00	0.00	*158.70 FL X
6	1	NA	*REAR BOOT OUTER CHROME <i>17</i>	25.00	0.00	*1,088.40 FL X
7	2	NA	*REAR NUMBER PLATE LAMP <i>17</i>	25.00	0.00	*259.40 FL X
8	1	NA	*REAR BOOT GLASS MOULDING <i>121</i>	25.00	0.00	*130.60 FL X
9	1	NA	*REAR PANEL <i>17</i>	25.00	0.00	*850.60 FL X
10	1	NA	*REAR PANEL TOP GARNISH <i>17</i>	25.00	0.00	*240.60 FL X
11	1	NA	*REAR BUMPER <i>12/201</i>	25.00	0.00	*770.40 FL —
12	10	NA	*REAR BUMPER CLIPS <i>121</i>	25.00	0.00	*98.00 FL —
13	1	NA	*REAR BUMPER SIDE HOLDER - LH	25.00	0.00	*128.60 FL ?
14	1	NA	*REAR BUMPER SIDE HOLDER - RH	25.00	0.00	*128.60 FL ?
15	1	NA	*REAR BUMPER BRACKET - LH	25.00	0.00	*140.70 FL ?
16	1	NA	*REAR BUMPER BRACKET - RH	25.00	0.00	*140.70 FL ?
17	1	NA	*REAR BOOT HYBRID SYNERGY DRIVE LOGO <i>121</i>	25.00	0.00	*90.80 FL —
Sub Total (S\$)						6,778.20
- List Item Discount on L Items (S\$)						1,694.55
Total Parts (S\$)						5,083.65

F=Franchise part. L=ListItemDisc.

Progressive Car Care Pte Ltd/SBL1111U/05/03/2019 14:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR BUMPER SENSOR	220.00
2	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			230.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	600 800.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; CUT/WELD; REAR PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	450 800.00
3	TO TRANSFER REAR BUMPER SENSOR	New	50 100.00
4	TO CHECK WIRING	New	20.00
5	TO REMOVE; REFIT REAR BOOT GLASS	New	120 150.00
6	TO REMOVE; REFIT REAR GARNISH	New	80 80.00
Gross Labour Cost (\$\$)			1,950.00

Progressive Car Care Pte Ltd/SBL1111U/05/03/2019 14:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.