

3/5/2019

Repairer Estimates


PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 5408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

TP INSURER:
LEE KAI HENG

India International Insurance Pte Ltd (HQ)

Singapore

Claimant Insurer:

Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP 0319-5422
Policy No:		Date of Loss:	01/03/2019
Vehicle Reg. No.:	SBL1111U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TAN SOON KIAT		
Make/Model:	TOYOTA VOXY HYBRID V, 1.8 (A)	Vehicle Reg. Date:	02/08/2017
Vehicle Colour:	WHITE	Chassis No:	ZWR800258040
Engine No:	2ZR1967339		
Odometer:	34707 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		

Description of Accident/Loss

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Remarks:

VEHICLE NOT IN WORKSHOP

Present Location:

PROGRESSIVE CAR CARE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	5,083.65
Miscellaneous Items	230.00
Labour	1,150.00
Paintwork Labour	800.00
Towing	0.00
Gross Total (\$\$)	7,263.65
+ GST 7.00% (\$\$)	508.46
Nett Amount (\$\$)	7,772.11

This claim is handled by: SOO LEONG KEAT

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK A: to Consultants hence notify the Repairer of the following:

- To ins. survey before/after spray painting
- To display damaged part(s) during return
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be salvaged and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Mar 2019)

Parts: M1-MPV TOYOTA VOXY HYBRID V 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SBL1111U/05/03/2019 14:32

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR BOOT <i>12/2</i>	25.00	0.00	*1,680.40 FL <i>X</i>
2	1	NA	*REAR BOOT RUBBER <i>1A</i>	25.00	0.00	*380.60 FL <i>X</i>
3	1	NA	*REAR BOOT TOP LOCK <i>1A</i>	25.00	0.00	*360.70 FL <i>X</i>
4	1	NA	*REAR BOOT BOTTOM LOCK <i>1A</i>	25.00	0.00	*130.40 FL <i>X</i>
5	1	NA	*REAR BOOT TOYOTA LOGO <i>1A</i>	25.00	0.00	*158.70 FL <i>X</i>
6	1	NA	*REAR BOOT OUTER CHROME <i>1A</i>	25.00	0.00	*1,088.40 FL <i>X</i>
7	2	NA	*REAR NUMBER PLATE LAMP <i>1A</i>	25.00	0.00	*259.40 FL <i>X</i>
8	1	NA	*REAR BOOT GLASS MOULDING <i>1A</i>	25.00	0.00	*130.60 FL <i>X</i>
9	1	NA	*REAR PANEL <i>1A</i>	25.00	0.00	*850.60 FL <i>X</i>
10	1	NA	*REAR PANEL TOP GARNISH <i>1A</i>	25.00	0.00	*240.60 FL <i>X</i>
11	1	NA	*REAR BUMPER <i>12/2</i>	25.00	0.00	*770.40 FL <i>X</i>
12	10	NA	*REAR BUMPER CLIPS <i>12/2</i>	25.00	0.00	*98.00 FL <i>X</i>
13	1	NA	*REAR BUMPER SIDE HOLDER - LH <i>1A</i>	25.00	0.00	*128.60 FL <i>X</i>
14	1	NA	*REAR BUMPER SIDE HOLDER - RH <i>1A</i>	25.00	0.00	*128.60 FL <i>X</i>
15	1	NA	*REAR BUMPER BRACKET - LH <i>1A</i>	25.00	0.00	*140.70 FL <i>X</i>
16	1	NA	*REAR BUMPER BRACKET - RH <i>1A</i>	25.00	0.00	*140.70 FL <i>X</i>
17	1	NA	*REAR BOOT HYBRID SYNERGY DRIVE LOGO <i>12/2</i>	25.00	0.00	*90.80 FL <i>X</i>

F=Franchise part, L=List Item Disc

Sub Total (S\$)

6,778.20

- List Item Discount on L Items (S\$)

1,694.55

Total Parts (S\$)

5,083.65

Progressive Car Care Pte Ltd/SBL1111U/05/03/2019 14:32 Not valid without Reference section.
Generated using Merimen e-Claims IEAS

2770.2
 252
 2077.65

3/5/2019

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

- 1 1 REAR BUMPER SENSOR
2 1 OD/TP Case (Insurer)

su 220.00 X
su 10.00

Sub Total (\$\$) 230.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

- 1 TO RESPRAY PAINT ON ACCIDENT PORTIONS

Labour Items

- 2 TO KNOCK OUT DENTS; CUT/WELD; REAR PANEL; REMOVE; REPLACE ACCIDENT PARTS
3 TO TRANSFER REAR BUMPER SENSOR
4 TO CHECK WIRING
5 TO REMOVE; REFIT REAR BOOT GLASS
6 TO REMOVE; REFIT REAR GARNISH

New 600 800.00

New 450 800.00

New 50 100.00

New 20.00 ✓

New 120 150.00

New 60 80.00

Gross Labour Cost (\$\$) 1,950.00

Progressive Car Care Pte Ltd/SBL1111U/05/03/2019 14:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

1310
3387.55
2700