

17. Both damages are corresponding to their respective heights and are consistent to their nature of contact. However the damage pattern seen on both vehicles cannot conclusively determine which vehicle had caused the accident.

**Muhd Nazril***Senior Technical Investigator*
Ang Bryan Tani*AFF SAE-A, AMSOE AMIRTE, MATAI, Aff.Inst.AEA**Senior Technical Investigator**Technical Investigation & Reconstructionist (SAE-A)*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.