

2/20/2019

ASS. REF. BY:

REF:

CS/INC19004122/Evd352

Special Instruction:

SMA/Veh/PA

ASSIGNMENT (Office)

From (Person):

Cynthia Ang

of

INC

Date/Time:

5/3/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SMA 668P

Insured:

SLQ 199D

at Workshop m/s

Cheng Auto

Tel:

8666 7775

of

5 Soon Lee Street #01-62

Policy No:

Claim No:

MT/1034327-002

Sum Insured:

Excess:

Make of Vehc:

(Client's Record)

D.O.A.

1/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time:

Action/Instruction () Estimate

SMA 668P-X

SLQ 199D-X

Steve

SMA 668P

28/08/07

TP

7000/2

Add Fee: : Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend 15

$$) \quad S + R \rightarrow Cl$$

Photos.

1. 0.000000

2003

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 5 March 2019 11:48 AM
To: assignments@lkkauto.com
Subject: RE: TP CASES FARMED OUT TO LKK ON 05/03/2019

Dear Veron / Nivitha,

Resend with the following details.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Cynthia Ang
Sent: Tuesday, 5 March 2019 9:37 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Daniel Koh <daniel.koh@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 05/03/2019

Dear Veron / Nivitha,

Please assist to survey the vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Type	Survey Time	OI Veh	DOA	Ad Re
1	Rajeswary	MT/1034327-002	SMA668P	CHENG AUTO BODYWORKS	5 SOON LEE STREET #01-62 PIONEER POINT	/ 8666 7775	Physical Survey		SLQ199D	01/03/2019	
2	Wo Jessie	MT/1034312-002	SHA9591B	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	Guang / 94669828	Physical Survey		GBC6202E	02/03/2019	
3	Muhammad Airwan	MT/1033391-	XE2208U	SIN SHENG ENGINEERING SERVICES	3 TECH PARK CRESCENT TUAS TECH PARK SINGAPORE 638129	Susan / 6863 9595	Physical Survey		XE2810E	15/02/2019	
4	Muhammad Airwan	MT/1034432-001	SLD3960X	VERMOGEN ACE PTE LTD	6 BENOI ROAD, SINGAPORE 629904	Pila / 6358 3031	Physical Survey		SHC6854C	03/03/2019	

5	Thio Tse Kiat	MT/1034310-002	SLL9051M	VERMOGEN ACE PTE LTD	6 BENOI ROAD, SINGAPORE 629904	Pila / 6358 3031	Physical Survey		SMF1784D	01/03/2019
6	Azhari	MT/1034201-002	PC1981G	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	/ 62660555	Physical Survey	09:30-13:00	SJC6682H	28/02/2019
7	Rajeswary	MT/1034177-002	SLK4378J	WORLD AUTO PTE LTD	1 KRANJI LOOP SINGAPORE 739535	Daniel / 63621776	Physical Survey		SHD1446A	28/02/2019

Please contact workshops.

Please ack.

Thank You

With Regards

Cynthia Ang

Admin Assistant

Motor Insurance

T +65 6430 7900

www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

TP / Intuc Income
SURVEYOR COPY

ACORN19026501 / ETH02 Filed: The Ltd - Bukit Buro
ENTRY DATE & TIME: 01/03/2019 18:40
SUBMITTED BY: JACKSON TEO Ben Chye

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 01/03/2019 18:40
Date Of Accident 01/03/2019 14:10
Exact Location Of Accident ALONG AYE TOWARDS CITY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMA668P
Insured/Policyholder
Name Of Registered Owner ANG SIEW KIAT
NRIC No S1701739Z
Email Address ASKPETERANG@GMAIL.COM
Mobile Phone No (LOCAL) +65-98193902
Alternative Phone No OTHERS-98193902

Vehicle Particulars

Manufacturer TOYOTA
Model ESTIMA-2.4 AERAS (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number MT/00511406
Cover Note Number

Driver

Name of Driver ANG SIEW MENG
Work Permit No S7400814C
Date Of Birth 11/01/1974
Occupation INDOOR
Date Of Driving Pass 17/01/2014
Driving Experience 5 YEARS AND 1 MONTH
Gender MALE
Mobile Number (LOCAL) +65-96363367
Fax Number
Contact Number
Email Address PAULANG74@HOTMAIL.COM

Address	BLK 658 JURONG WEST ST 65 #03-640
Postcode	641658
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ199D
Vehicle Make/Model/Colour	TOYOTA ESTIMA ,
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MELVIN
NRIC/Passport Number	
Contact Number	96317257
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to the third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ON THE EXTREME LEFT LANE OF A1E TOWARDS CITY. Suddenly the car in front of me was damaged & brake I HAVE MANAGED TO TURN MY BRAKE TO A STOP BUT THE CAR BEHIND ME DIDN'T MANAGE TO STOP IN TIME AND HIT ME DRIVER, AND I CAME DOWN AND APPEARED TO ME SAYING IT WAS HIS FAULT.

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS** CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

- | | |
|-------------------------------------|----------------------------------|
| ☐ | - Reporting Only |
| ☐ | - Claim OD |
| ☐ | - Claim TP |
| ☒ | - Claim OD/ TP at other workshop |

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature
Date & Time

Driver's Signature
(if driver not the policyholder)
Date & Time 01/03/19

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1739Z
Vehicle Details	
Vehicle No.:	SMA668P
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	2AZF037461
Chassis No.:	ACR500038190
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$29,673.00
Original Registration Date:	28 Aug 2007
First Registration Date:	28 Aug 2007
Transfer Count:	4
Actual ARF Paid:	\$32,641.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2027
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$50,972.00
COE Rebate Amount:	\$43,202.00
Total Rebate Amount:	\$43,202.00

The information contained herein is correct as at 05 Mar 2019

OK

LOOKING FOR AN
INDEPENDENT SPECIALIST?

Find the specialty Workshops for your vehicle

Toyota Estima

Price Range ▾

Depreciation ▾

> 10 year(s) ▾

Vehicle Type ▾

Advanced Search

Home » Used Cars » Creative Auto » Toyota Estima 2.4A Aeras (COE till 12/2027)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

Leasing

YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE



6760 7117 8720 5000 8720 8000

Toyota Estima 2.4A Aeras (COE till 12/2027)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

CREATIVE
AUTO



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$60,800	
Depreciation	\$6,920 /yr	?
Reg Date	17-Dec-2007 (8yrs 9mths 11days COE left)	
Manufactured	2007	?
Mileage	140,000 km (12.5k /yr)	
Transmission	Auto	
Engine Cap	2,362 cc	
Road Tax	\$1,966 /yr	?
Power	125.0 kW (167 bhp) View specs of the Toyota Estima (2006-2010)	
Curb Weight	1,710 kg	?
Features	Powerful 2.4L DOHC 16V VVT-I Engine, 7 Speed Super CVT Auto Transmission, Dual Power Sliding Doors, Keyless Entry Push Start/Stop, 8 Seaters MPV	
Accessories	18" S/Rims, Premium Luxurious Leather Seats, DVD Player With Reverse Camera, Fog Lamps, Aero Bodykit, Roof Mount LCD Monitor, Full Walnut Interior.	
Description	100% Loan Available, Upon Approval, 100% Accident Free. Beautiful Pearl White Paintwork. Facelifted Rear Lamps! Guaranteed No Repairs Needed. Flexible Bank And In House Loan Available At Low Interest Rate. 6 Months Pre-Owned Car Warranty Will Be Provided. Trade In Welcome. Kindly Contact Our Friendly Sales Advisor For Viewing.	
COE	\$51,850	?
OMV	\$29,370	?
ARF	\$32,307	?
Dereg Value	\$45,571 as of today (change)	?
No. of Owners	3	?



Location Map

Seller Information

Company	Creative Auto » dealer's pricelist » 144 vehs sold 136 vehs available	
Address	61 Ubi Avenue 2 #04-03/18/19 Search cars nearby this location	
Location	Automobile Megamart	
Contact Person(s)	Vix Teo	9799760
	Alex Tan	9755688
	Terence Leow	9029089

Compare



Toyota Estima

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼

Advanced Search

Home » Used Cars » Corsica Trading » Toyota Estima 2.4A Aeris (COE till 11/2027)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

Leasing
YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE



6769 7117 8720 5000 8720 8000

Toyota Estima 2.4A Aeris (COE till 11/2027)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$62,800**Depreciation** \$7,240 /yr**Reg Date** 06-Nov-2007
(8yrs 8mths COE left)**Manufactured** 2007**Mileage** -**Transmission** Auto**Engine Cap** 2,362 cc**Road Tax** \$1,966 /yr**Power** 125.0 kW (167 bhp)
View specs of the Toyota Estima (2006-2010)**Curb Weight** 1,770 kg**Features** -**Accessories** -**Description** Low Mileage, 7 Seaters Mpv, Nice Paint Work And Excellent Condition, Power Sliding Door, Keyless Entry/Start Stop, Leather Seat, Sport Rim, Reverse Camera, Rear Air Condition Blower, Bank Or In House Loan Available.**COE** \$50,168**OMV** \$27,719**ARF** \$30,491**Dereg Value** \$43,529 as of today (change)**No. of Owners** 4**Type of Veh** MPV**Category** COE Car**Availability** Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 01-Mar-2019 | Last Updated on: 02-Mar-2019

Tags: Toyota Estima, toyota estima, 2007 Toyota Estima, 2007 toyota estima, Toyota, Estima, estima, Used Toyota



Seller Information

Company	Corsica Trading	
	» dealer's pricelist	
	» 18 vehs sold 9 vehs available	
Address	1 Bukit Batok Crescent #02-61	
	Search cars nearby this location	
Location	WCEGA Plaza	
Office No	67775005	
Contact Person(s)	Woo Kok Wah	9008666
	Kelvin Goh	9678666

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Compare

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW

Toyota Estima

Price Range ▾

Depreciation ▾

> 10 year(s) ▾

Vehicle Type ▾



Advanced
Search

Home » Used Cars » A4 Car Motor » Toyota Estima 2.4A (COE till 05/2027)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Toyota Estima 2.4A (COE till 05/2027)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$62,688	
Depreciation	\$7,620 /yr	?
Reg Date	24-May-2007 (8yrs 2mths 18days COE left)	
Manufactured	2007	?
Mileage	132,496 km (11.2k /yr)	
Transmission	Auto	
Engine Cap	2,362 cc	
Road Tax	\$1,966 /yr	?
Power	125.0 kW (167 bhp) View specs of the Toyota Estima (2006-2010)	
Curb Weight	1,750 kg	?
Features	Powerful 2.4 Litre DOHC VTI Engine, 7 Speed Super CVT Auto Transmission, Dual Power Sliding Doors, Keyless Entry.	
Accessories	Sports Rims, Leather Seats, DVD Player, Reverse Sensors And Camera, Fog Lamps, New Paintwork, New Leather Seats.	
Description	100% Loan Available. Highest Offer For All Trade In! Insurance Can Pay By 12 Months Installment (No Cards Needed). 6 Months Warranty For Engine And Gearbox. Flexible Loan! Fast Approval! Call Us Now!	
COE	\$52,491	?
OMV	\$29,632	?
ARF	\$32,596	?
Dereg Value	\$43,158 as of today (change)	?
No. of Owners	3	?
Type of Veh	MPV	
Category	COE Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 05-Mar-2019 | Last Updated on: 05-Mar-2019



Location Map

Seller Information

Company	A4 Car Motor » dealer's pricelist » 16 vehs sold 9 vehs available	
Address	210 Turf Club Road Lot A40 Search cars nearby this location	
Location	Car Mall @ The Grandstand	
Office No	90508080	
Contact Person(s)	Max	9050808
	WEI	9485669
	David	8233019

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car.

Compare

TP / INCOME
SURVEYOR COPY.



GST Reg No. M901721111

Reporting Centre
Workshop
Spray-painting

5 Soon Lee Street, #01-60 Pioneer Point, Singapore 627607
5 Soon Lee Street, #01-62 Pioneer Point, Singapore 627607
1 Soon Lee Street, #06-41 Pioneer Centre, Singapore 627605

Office: 6331 0707 Fax: 6186 2438 Email: info@chengauto.com Cheng Auto Bodyworks Singapore



DATE: 5/3/2019

Handwritten signature and date:
7/3/19

REPAIR DETAILS			
REFERENCE			
Vehicle Reg No.	: SMA668P		
Make & Model	: TOYOTA	ESTIMA AERAS 2.4 A	
Chassis No.	: ACR500038190		
Engine No.	: 2AZF037461		
Manufactured Year	: 2007		
Labour	: REPAIRER'S		
TP Vehicle Reg No.	: SLQ199D		
DOA & Location	: 01/03/2019	AYE AFTER CLEMENTI AVE 6 EXIT	
Our Ref	: SMA668P	/ ANG SIEW KIAT	

Handwritten notes:
Steve (LKK) w/L perjudic
8322 8813
5/3/19 1.45 pm
L/S
11 8 days

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	TAILGATE / DD		\$ 1,566.60
2	1	TAILGATE HINGE LH X NN		\$ 61.95
3	1	TAILGATE HINGE RH X NN		\$ 61.95
4	1	TAILGATE W/STRIPE / TN		\$ 373.80
5	1	TAILGATE LOCK / BT		\$ 410.55
6	1	TAILGATE LOCK CATCH X NN		\$ 26.25
7	1	TAILGATE LOCK SENSOR ?		\$ 131.25
8	1	TAILGATE OUTER GARNISH ?		\$ 206.85
9	1	TAILGATE LOGO / NEC		\$ 59.85
10	1	TAILGATE REFLECTOR CENTRE X NN		\$ 185.85
11	1	TAILGATE REFLECTOR LH ?		\$ 299.25
12	1	TAILGATE REFLECTOR RH X NN		\$ 299.25
13	1	TAILGATE DAMPER LH X NN		\$ 227.85
14	1	TAILGATE DAMPER RH X NN		\$ 227.85
15	1	TAILGATE INNER TRIM BOARD / GR		\$ 490.35
16	1	TAILGATE INNER TOP GARNISH X NN		\$ 246.75
17	1	TAILGATE INNER SIDE GARNISH LH / GR		\$ 110.25
18	1	TAILGATE INNER SIDE GARNISH RH X NN		\$ 173.25
19	1	TAILGATE WIPER MOTOR X NN		\$ 708.75
20	1	REAR W/SCREEN WITH MOULDING X ?		\$ 2,043.26
21	1	TAILLAMP LH ?		\$ 309.75
22	1	TAILLAMP CLIP LH ?		\$ 5.25
23	1	TAILLAMP RH X NN		\$ 309.75
24	1	TAILLAMP PANEL LH X R		\$ 278.25
25	1	TAILLAMP CLIPS RH X NN		\$ 5.25
26	1	REAR BUMPER / GR		\$ 573.30
27	1	REAR BUMPER BRACKET LH / GR		\$ 40.95
28	1	REAR BUMPER BRACKET RH / GR		\$ 40.95
29	1	REAR BUMPER SIDE RETAINER LONG LH X NN		\$ 89.25
30	1	REAR BUMPER SIDE RETAINER SHORT LH X NN		\$ 40.95
31	1	REAR BUMPER SIDE RETAINER LONG RH X NN		\$ 89.25
32	1	REAR BUMPER SIDE RETAINER SHORT RH X NN		\$ 40.95
33	1	REAR BUMPER REFLECTOR LH / GR		\$ 51.45
34	1	REAR BUMPER REFLECTOR RH X NN		\$ 51.45

35	1	REAR BUMPER TOW COVER LH	X NN	\$	24.15
36	1	REAR END PANEL INNER	/ DD	\$	341.25
37	1	REAR END PANEL OUTER	/ DD	\$	694.05
38	1	REAR END PANEL TOP GARNISH	/ CR4	\$	282.45
39	1	SPARE WHEEL PANEL	?	\$	819.00
40	1	SPARE WHEEL PANEL TOP BOARD	X NIII	\$	1,338.75
41	1	SPARE WHEEL PANEL GARNISH	/ CR4	\$	183.75
42	1	SPARE WHEEL PANEL LINING	X NN	\$	173.25
43	1	REAR END PANEL BRACKET LH	X BT	\$	36.75
44	1	REAR END PANEL BRACKET RH	X BT	\$	36.75
45	1	REAR LH FENDER INNER LOWER GARNISH	V NAI	\$	185.85
46	1	REAR RH FENDER INNER LOWER GARNISH	V NN	\$	185.85
47	1	REAR LH FENDER INNER LOWER GARNISH TOOLS COVER	X NN	\$	310.80
48	1	REAR LH FENDER	X R	\$	886.20
49	1	REAR WIRE HARNESS	X NN	\$	206.85
				Sub-Total (\$\$)	\$ 15,544.16
				SAAA List Item Discount 25% (\$\$)	\$ 3,886.04
				Sub-Total (\$\$)	\$ 11,658.12

LABOUR

No.	Description	Price
1	LABOUR	\$ 2,000.00 1900
2	SPRAYPAINTING	\$ 2,000.00 1400
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 150.00 30
4	REPLACE REAR WINDSCREEN	\$ 150.00 100
5	REMOVE + REFIT TAILGATE TOP GARNISH FACILITATE REPAIR	\$ 200.00 50 200 50
6	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	\$ 300.00 200
7	ANTI-RUST CORROSION	\$ 300.00 20
8	REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, LINING, GARNISH AND UPHOLSTERY TO FACILITATE REPAIRS	\$ 500.00 9
9	REMOVE * REFIT REAR EXHAUST SYSTEM TO ASSIST REPAIR	\$ 200.00 X
10	REPLACE REAR REVERSE SENSOR + CHECK FUNCTION	\$ 60.00 10
11	REPLACE TAILGATE SPOILER	\$ 150.00 30
12	REMOVE & REFIT REAR UNDERCARRIAGE TO ASSIST REPAIR	\$ 400.00 ?
13	TO DO UP WHEEL ALIGNMENT	\$ 180.00 X
Total Labour (\$\$)		\$ 6,590.00

MISCELLANEOUS ITEMS

No.	Description	Price
1	REAR W/SCREEN SEALANT	\$ 80.00 50
2	REAR W/SCREEN SOLAR FILM - ask for previous instal invoice	\$ 280.00 100
3	TAILGATE OUTER GARNISH CLIPS 1 SET	\$ 50.00 10
4	TAILGATE IN-CAR REAR VIEW CAMERA	\$ 300.00 X
5	TAILGATE REAR GARNISH REVERSE CAMERA	\$ 250.00 X
6	REAR BUMPER REVERSE CAMERA	\$ 250.00 X
7	REAR BUMPER REVERSE SENSOR	\$ 250.00 100
8	REAR BUMPER CLIPS 1 SET	\$ 100.00 130
9	TAILGATE CENTRE SPOILER	\$ 400.00 200 X NN
10	TAILGATE INNER TRIM BOARD CLIPS 1 SET	\$ 100.00 10
11	TAILGATE INNER TOP GARNISH CLIPS 1 SET	\$ 50.00 X

12	TAILGATE INNER SIDE GARNISH LH CLIPS 1 SET	\$	50.00	/10
13	TAILGATE INNER SIDE GARNISH RH CLIPS 1 SET	\$	50.00	/10
14	REAR END PANEL TOP GARNISH CLIPS 1 SET	\$	50.00	/10
15	SPARE WHEEL GARNISH CLIPS 1 SET	\$	50.00	/10
16	SPARE WHEEL PANEL LINING CLIPS 1 SET	\$	100.00	X
17	REAR LH FENDER INNER LOWER GARNISH CLIPS 1 SET	\$	100.00	X
18	REAR RH FENDER INNER LOWER GARNISH CLIPS 1 SET	\$	100.00	X
19	REAR END PANEL TOP GARNISH CHROME PLATE	\$	250.00	/150
20	REAR END PANEL SEALANT	\$	80.00	/30
21	SPARE WHEEL PANEL SEALANT	\$	80.00	/30
22	SPARE WHEEL PANEL INSULATION	\$	250.00	?
23	REAR NO. PLATE	\$	180.00	X
Total Miscellaneous Items (S\$)		\$	3,450.00	

Total Parts (S\$)	\$	11,658.12
Total Labour (S\$)	\$	6,590.00
Total Miscellaneous (S\$)	\$	3,450.00
Total (S\$)	\$	21,698.12
GST 7% (S\$)	\$	1,518.87
Grand Total (S\$)	\$	23,216.99

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DATE: 5/3/2019

REPAIR DETAILS	
REFERENCE	
Vehicle Reg No.	: SMA668P
Make & Model	: TOYOTA ESTIMA AERAS 2.4 A
Chassis No.	: ACR500038190
Engine No.	: 2AZF037461
Manufactured Year	: 2007
Labour	: REPAIRER'S
TP Vehicle Reg No.	: SLQ199D
DOA & Location	: 01/03/2019 AYE AFTER CLEMENTI AVE 6 EXIT
Our Ref	: SMA668P / ANG SIEOW KIAT

✓ Steve (CLKK) w/L peroxide
8327 8813 5/3/19 1.45 pm
L/S
11 & days

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	TAILGATE ✓		\$ 1,566.60 ✓
2	1	TAILGATE HINGE LH ✓		\$ 61.95 X
3	1	TAILGATE HINGE RH ✓		\$ 61.95 X
4	1	TAILGATE W/STRIPE ✓		\$ 373.80 ✓
5	1	TAILGATE LOCK ✓		\$ 410.55 ✓
6	1	TAILGATE LOCK CATCH ✓		\$ 26.25 X
7	1	TAILGATE LOCK SENSOR ✓ (At bumper)		\$ 131.25 ✓
8	1	TAILGATE OUTER GARNISH ✓		\$ 206.85 ✓
9	1	TAILGATE LOGO ✓		\$ 59.85 ✓
10	1	TAILGATE REFLECTOR CENTRE ✓		\$ 185.85 X
11	1	TAILGATE REFLECTOR LH ✓		\$ 299.25 ✓
12	1	TAILGATE REFLECTOR RH ✓		\$ 299.25 X
13	1	TAILGATE DAMPER LH ✓		\$ 227.85 X
14	1	TAILGATE DAMPER RH ✓		\$ 227.85 X
15	1	TAILGATE INNER TRIM BOARD ✓		\$ 490.35 ✓
16	1	TAILGATE INNER TOP GARNISH ✓		\$ 246.75 X
17	1	TAILGATE INNER SIDE GARNISH LH ✓		\$ 110.25 ✓
18	1	TAILGATE INNER SIDE GARNISH RH ✓		\$ 173.25 X
19	1	TAILGATE WIPER MOTOR ✓		\$ 708.75 X
20	1	REAR W/SCREEN WITH MOULDING ✓ ?		\$ 2,043.26 X
21	1	TAILLAMP LH ✓		\$ 309.75 ✓
22	1	TAILLAMP CLIP LH ✓		\$ 5.25 X
23	1	TAILLAMP RH ✓		\$ 309.75 X
24	1	TAILLAMP PANEL LH ✓ R		\$ 278.25 X
25	1	TAILLAMP CLIPS RH ✓		\$ 5.25 X
26	1	REAR BUMPER ✓		\$ 573.30 ✓
27	1	REAR BUMPER BRACKET LH ✓		\$ 40.95 ✓
28	1	REAR BUMPER BRACKET RH ✓		\$ 40.95 ✓
29	1	REAR BUMPER SIDE RETAINER LONG LH ✓		\$ 89.25 X
30	1	REAR BUMPER SIDE RETAINER SHORT LH ✓		\$ 40.95 X
31	1	REAR BUMPER SIDE RETAINER LONG RH ✓		\$ 89.25 X
32	1	REAR BUMPER SIDE RETAINER SHORT RH ✓		\$ 40.95 X
33	1	REAR BUMPER REFLECTOR LH ✓		\$ 51.45 ✓
34	1	REAR BUMPER REFLECTOR RH ✓		\$ 51.45 X

35	1	REAR BUMPER TOW COVER LH X	\$	24.15 X
36	1	REAR END PANEL INNER X	\$	341.25 X
37	1	REAR END PANEL OUTER /	\$	694.05 /
38	1	REAR END PANEL TOP GARNISH /	\$	282.45 /
39	1	SPARE WHEEL PANEL X 9 R	\$	819.00 X
40	1	SPARE WHEEL PANEL TOP BOARD X	\$	1,338.75 X
41	1	SPARE WHEEL PANEL GARNISH /	\$	183.75 /
42	1	SPARE WHEEL PANEL LINING X	\$	173.25 X
43	1	REAR END PANEL BRACKET LH X /	\$	36.75 /
44	1	REAR END PANEL BRACKET RH X /	\$	36.75 /
45	1	REAR LH FENDER INNER LOWER GARNISH X	\$	185.85 X
46	1	REAR RH FENDER INNER LOWER GARNISH X	\$	185.85 X
47	1	REAR LH FENDER INNER LOWER GARNISH TOOLS COVER X	\$	310.80 X
48	1	REAR LH FENDER X R	\$	886.20 X
49	1	REAR WIRE HARNESS X	\$	206.85 X

Sub-Total (\$\$) \$ 15,544.16

SAAA List Item Discount 25% (\$\$) \$ 3,886.04

Sub-Total (\$\$) \$ 11,658.12

LABOUR

No.	Description	Price	
1	LABOUR	\$ 2,000.00	1400
2	SPRAYPAINTING	\$ 2,000.00	1700
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 150.00	1400 1400
4	REPLACE REAR WINDSCREEN	\$ 150.00	30
5	REMOVE + REFIT TAILGATE TOP GARNISH FACILITATE REPAIR	\$ 200.00	100
6	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	\$ 300.00	200 200
7	ANTI-RUST CORROSION	\$ 300.00	20
8	REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, LINING, GARNISH AND UPHOLSTERY TO FACILITATE REPAIRS 200	\$ 500.00	200 200
9	REMOVE + REFIT REAR EXHAUST SYSTEM TO ASSIST REPAIR	\$ 200.00	X
10	REPLACE REAR REVERSE SENSOR + CHECK FUNCTION	\$ 60.00	120
11	REPLACE TAILGATE SPOILER	\$ 150.00	300
12	REMOVE & REFIT REAR UNDERCARRIAGE TO ASSIST REPAIR	\$ 400.00	200 X
13	TO DO UP WHEEL ALIGNMENT	\$ 180.00	X

Total Labour (\$\$) \$ 6,590.00

MISCELLANEOUS ITEMS

No.	Description	Price	
1	REAR W/SCREEN SEALANT	\$ 80.00	/
2	REAR W/SCREEN SOLAR FILM	\$ 280.00	100
3	TAILGATE OUTER GARNISH CLIPS 1 SET	\$ 50.00	30
4	TAILGATE IN-CAR REAR VIEW CAMERA	\$ 300.00	X
5	TAILGATE REAR GARNISH REVERSE CAMERA	\$ 250.00	X
6	REAR BUMPER REVERSE CAMERA	\$ 250.00	X
7	REAR BUMPER REVERSE SENSOR	\$ 250.00	200
8	REAR BUMPER CLIPS 1 SET	\$ 100.00	130
9	TAILGATE CENTRE SPOILER	\$ 400.00	200 X
10	TAILGATE INNER TRIM BOARD CLIPS 1 SET	\$ 100.00	120
11	TAILGATE INNER TOP GARNISH CLIPS 1 SET	\$ 50.00	X

12	TAILGATE INNER SIDE GARNISH LH CLIPS 1 SET	\$	50.00 / 10
13	TAILGATE INNER SIDE GARNISH RH CLIPS 1 SET	\$	50.00 / 10
14	REAR END PANEL TOP GARNISH CLIPS 1 SET	\$	50.00 / 10
15	SPARE WHEEL GARNISH CLIPS 1 SET	\$	50.00 / 10
16	SPARE WHEEL PANEL LINING CLIPS 1 SET	\$	100.00 10 / 10
17	REAR LH FENDER INNER LOWER GARNISH CLIPS 1 SET	\$	100.00 10 / 10
18	REAR RH FENDER INNER LOWER GARNISH CLIPS 1 SET	\$	100.00 10 / 10
19	REAR END PANEL TOP GARNISH CHROME PLATE	\$	250.00 / 150
20	REAR END PANEL SEALANT	\$	80.00 / 30
21	SPARE WHEEL PANEL SEALANT	\$	80.00 / 30
22	SPARE WHEEL PANEL INSULATION	\$	250.00 2 X
23	REAR NO. PLATE	\$	180.00 X

Total Miscellaneous Items (S\$) \$ 3,450.00

Total Parts (S\$)	\$	11,658.12
Total Labour (S\$)	\$	6,590.00
Total Miscellaneous (S\$)	\$	3,450.00
Total (S\$)	\$	21,698.12
GST 7% (S\$)	\$	1,518.87
Grand Total (S\$)	\$	23,216.99

DATE: 5/3/2019

REPAIR DETAILS	
REFERENCE	
Vehicle Reg No.	SMA668P
Make & Model	TOYOTA ESTIMA AERAS 2.4 A
Chassis No.	ACR500038190
Engine No.	2AZF037461
Manufactured Year	2007
Labour	REPAIRER'S
TP Vehicle Reg No.	SLQ199D
DOA & Location	01/03/2019 AYE AFTER CLEMENTI AVE 6 EXIT
Our Ref	SMA668P / ANG SIEW KIAT

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	TAILGATE ✓		\$ 1,566.60 ✓
2	1	TAILGATE HINGE LH ✓		\$ 61.95 ✓
3	1	TAILGATE HINGE RH ✓		\$ 61.95 ✓
4	1	TAILGATE W/STRIPE ✓		\$ 373.80 ✓
5	1	TAILGATE LOCK ✓		\$ 410.55 ✓
6	1	TAILGATE LOCK CATCH ✓		\$ 26.25 ✓
7	1	TAILGATE LOCK SENSOR ✓		\$ 131.25 ✓
8	1	TAILGATE OUTER GARNISH ✓		\$ 206.85 ✓
9	1	TAILGATE LOGO ✓		\$ 59.85 ✓
10	1	TAILGATE REFLECTOR CENTRE ✓		\$ 185.85 ✓
11	1	TAILGATE REFLECTOR LH ✓		\$ 299.25 ✓
12	1	TAILGATE REFLECTOR RH ✓		\$ 299.25 ✓
13	1	TAILGATE DAMPER LH ✓		\$ 227.85 ✓
14	1	TAILGATE DAMPER RH ✓		\$ 227.85 ✓
15	1	TAILGATE INNER TRIM BOARD ✓		\$ 490.35 ✓
16	1	TAILGATE INNER TOP GARNISH ✓		\$ 246.75 ✓
17	1	TAILGATE INNER SIDE GARNISH LH ✓		\$ 110.25 ✓
18	1	TAILGATE INNER SIDE GARNISH RH ✓		\$ 173.25 ✓
19	1	TAILGATE WIPER MOTOR ✓		\$ 708.75 ✓
20	1	REAR W/SCREEN WITH MOULDING ✓		\$ 2,043.26 ✓
21	1	TAILLAMP LH ✓		\$ 309.75 ✓
22	1	TAILLAMP CLIP LH ✓		\$ 5.25 ✓
23	1	TAILLAMP RH ✓		\$ 309.75 ✓
24	1	TAILLAMP PANEL LH ✓		\$ 278.25 ✓
25	1	TAILLAMP CLIPS RH ✓		\$ 5.25 ✓
26	1	REAR BUMPER ✓		\$ 573.30 ✓
27	1	REAR BUMPER BRACKET LH ✓		\$ 40.95 ✓
28	1	REAR BUMPER BRACKET RH ✓		\$ 40.95 ✓
29	1	REAR BUMPER SIDE RETAINER LONG LH ✓		\$ 89.25 ✓
30	1	REAR BUMPER SIDE RETAINER SHORT LH ✓		\$ 40.95 ✓
31	1	REAR BUMPER SIDE RETAINER LONG RH ✓		\$ 89.25 ✓
32	1	REAR BUMPER SIDE RETAINER SHORT RH ✓		\$ 40.95 ✓
33	1	REAR BUMPER REFLECTOR LH ✓		\$ 51.45 ✓
34	1	REAR BUMPER REFLECTOR RH ✓		\$ 51.45 ✓

35	1	REAR BUMPER TOW COVER LH X	NAI	\$	24.15 X
36	1	REAR END PANEL INNER X	NAI	\$	241.25 X
37	1	REAR END PANEL OUTER /	DO	\$	694.05 /
38	1	REAR END PANEL TOP GARNISH /	CR4	\$	282.45 /
39	1	SPARE WHEEL PANEL X R		\$	819.00 X
40	1	SPARE WHEEL PANEL TOP BOARD X	NAI	\$	1,338.75 X
41	1	SPARE WHEEL PANEL GARNISH /	CR4	\$	183.75 /
42	1	SPARE WHEEL PANEL LINING X	NAI	\$	173.25 X
43	1	REAR END PANEL BRACKET LH X	BT	\$	36.75 /
44	1	REAR END PANEL BRACKET RH X	BT	\$	36.75 /
45	1	REAR LH FENDER INNER LOWER GARNISH X	NAI	\$	185.85 X
46	1	REAR RH FENDER INNER LOWER GARNISH X	NAI	\$	185.85 X
47	1	REAR LH FENDER INNER LOWER GARNISH TOOLS COVER X	NAI	\$	310.80 X
48	1	REAR LH FENDER X R		\$	886.20 X
49	1	REAR WIRE HARNESS X	NAI	\$	206.85 X

Sub-Total (S\$) \$ 15,544.16

SAAA List Item Discount 25% (S\$) \$ 3,886.04

Sub-Total (S\$) \$ 11,658.12

5898.90
- 25%
4,424.17

LABOUR

No.	Description	Price
1	LABOUR	1400
2	SPRAYPAINTING	\$ 2,000.00 1900
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 2,000.00 1400 1400
4	REPLACE REAR WINDSCREEN	\$ 150.00 30
5	REMOVE + REFIT TAILGATE TOP GARNISH FACILITATE REPAIR	\$ 150.00 100
6	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	\$ 200.00 80 200 50
7	ANTI-RUST CORROSION	\$ 300.00 30
8	REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, LINING, GARNISH AND UPHOLSTERY TO FACILITATE REPAIRS	\$ 300.00 30
9	REMOVE + REFIT REAR EXHAUST SYSTEM TO ASSIST REPAIR	\$ 500.00 200 200
10	REPLACE REAR REVERSE SENSOR + CHECK FUNCTION	\$ 200.00 X
11	REPLACE TAILGATE SPOILER	\$ 60.00 10
12	REMOVE & REFIT REAR UNDERCARRIAGE TO ASSIST REPAIR	\$ 150.00 X 30
13	TO DO UP WHEEL ALIGNMENT	\$ 400.00 X 2 X
		\$ 180.00 X
Total Labour (S\$)		\$ 6,590.00 3270

MISCELLANEOUS ITEMS

No.	Description	Price
1	REAR W/SCREEN SEALANT	\$ 80.00 /
2	REAR W/SCREEN SOLAR FILM	\$ 280.00 / 100
3	TAILGATE OUTER GARNISH CLIPS 1 SET	\$ 50.00 / 30
4	TAILGATE IN-CAR REAR VIEW CAMERA	\$ 300.00 X
5	TAILGATE REAR GARNISH REVERSE CAMERA	\$ 250.00 X
6	REAR BUMPER REVERSE CAMERA	\$ 250.00 X
7	REAR BUMPER REVERSE SENSOR	\$ 250.00 / 100
8	REAR BUMPER CLIPS 1 SET	\$ 100.00 / 30
9	TAILGATE CENTRE SPOILER	\$ 400.00 X 300
10	TAILGATE INNER TRIM BOARD CLIPS 1 SET	\$ 100.00 / 20
11	TAILGATE INNER TOP GARNISH CLIPS 1 SET	\$ 50.00 X

12	TAILGATE INNER SIDE GARNISH LH CLIPS 1 SET	MEC	\$	50.00 / 10
13	TAILGATE INNER SIDE GARNISH RH CLIPS 1 SET	MEC	\$	50.00 / 10
14	REAR END PANEL TOP GARNISH CLIPS 1 SET	MEC	\$	50.00 / 10
15	SPARE WHEEL GARNISH CLIPS 1 SET	MEC	\$	50.00 / 10
16	SPARE WHEEL PANEL LINING CLIPS 1 SET	MEC	\$	100.00 / 10
17	REAR LH FENDER INNER LOWER GARNISH CLIPS 1 SET	MEC	\$	100.00 / 10
18	REAR RH FENDER INNER LOWER GARNISH CLIPS 1 SET	MEC	\$	100.00 / 10
19	REAR END PANEL TOP GARNISH CHROME PLATE	DD	\$	250.00 / 150
20	REAR END PANEL SEALANT	MEC	\$	80.00 / 30
21	SPARE WHEEL PANEL SEALANT	MEC	\$	30.00 / 30
22	SPARE WHEEL PANEL INSULATION	NAI	\$	250.00 / 2
23	REAR NO. PLATE	NAI	\$	180.00 X

Total Miscellaneous Items (\$\$) \$ 3,450.00

949

Total Parts (\$\$)	\$	11,658.12
Total Labour (\$\$)	\$	6,590.00
Total Miscellaneous (\$\$)	\$	3,450.00
Total (\$\$)	\$	21,698.12
GST 7% (\$\$)	\$	1,518.87
Grand Total (\$\$)	\$	23,216.99

21,833.12

8634.17

8634.17

Supp + 135

8769.17

L/5 - 7,015.33
= 7,000

ESTIMATES OF SUPPLEMENTARY PARTS

No.	Qty	Description	Part No.	Price
1	1	REAR GLASS MOULDING	AFC	\$ 180.00
Sub-Total (\$)				\$ 180.00
SAAA List Item Discount 25% (\$)				\$ 45.00
Sub-Total (\$)				\$ 135.00

Steve Chen (LKK Auto)

From: CLAIMS@CHENGAUTO.COM
Sent: Tuesday, April 09, 2019 4:59 PM
To: Steve Chen (LKK Auto)
Subject: RE: SMA668P Finalize

Dear Mr Steve,

We refer to your offer of \$7,000 lump sum before GST and 11 repair days. We accept your offer.

Thanks & Best Regards,
Claims Department
Murugesan



CHENG AUTO BODYWORKS

HP: 8666 7775 | Office-Tel: 6631 0707 | Fax: 6316 2431

Reporting Centre

Address: 5 Soon Lee Street #01-60 Pioneer Point, Singapore 627607
Email: claims@chengauto.com

Workshop

Address: 5 Soon Lee Street #01-62 Pioneer Point, Singapore 627607
Email: cab@chengauto.com

Spraypainting

Address: 1 Soon Lee Street #06-41 Pioneer Centre, Singapore 627605
Email: cab@chengauto.com

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Monday, 18 March, 2019 9:40 AM
To: CLAIMS@CHENGAUTO.COM
Subject: SMA668P Finalize

Dear Sir,

Kindly refer the above vehicle for finalize \$7,000 lump sum. 11 days.

Kindly check and confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: CS/INC19004122/Evd3s2

Date: 10-04-2019



ATTN: RAJESWARY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 199D	Veh. Inspected	SMA 668P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1034327-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	05/03/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ESTIMA	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	ACR500038190	Colour	BLACK
Odometer	221896 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50R18	BRIDGESTONE	7 mm
L/H Front Tyre	225/50R18	BRIDGESTONE	7 mm
R/H Rear Tyre	225/50R18	BRIDGESTONE	7 mm
L/H Rear Tyre	225/50R18	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/03/2019	Inspect Date / Time	05/03/2019 (01:23 PM)
Survey held at	5 SOON LEE #01-62		
Repairer	CHENG AUTO BODYWORKS		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 668P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DENTED	1,566.60	1,566.60
1	TAILGATE HINGE LH	NOT NECESSARY	61.95	-
1	TAILGATE HINGE RH	NOT NECESSARY	61.95	-
1	TAILGATE W/STRIPE	TORN	373.80	373.80
1	TAILGATE LOCK	BENT	410.55	410.55
1	TAILGATE LOCK CATCH	NOT NECESSARY	26.25	-
1	TAILGATE LOCK SENSOR (AT BUMPER)	SHORTED	131.25	131.25
1	TAILGATE OUTER GARNISH	BROKEN	206.85	206.85
1	TAILGATE LOGO	NECESSARY	59.85	59.85
1	TAILGATE REFLECTOR CENTRE	NOT NECESSARY	185.85	-
1	TAILGATE REFLECTOR LH	BROKEN	299.25	299.25
1	TAILGATE REFLECTOR RH	NOT NECESSARY	299.25	-
1	TAILGATE DAMPER LH	NOT NECESSARY	227.85	-
1	TAILGATE DAMPER RH	NOT NECESSARY	227.85	-
1	TAILGATE INNER TRIM BOARD	BROKEN	490.35	490.35
1	TAILGATE INNER TOP GARNISH	NOT NECESSARY	246.75	-
1	TAILGATE INNER SIDE GARNISH LH	BROKEN	110.25	110.25
1	TAILGATE INNER SIDE GARNISH RH	NOT NECESSARY	173.25	-
1	TAILGATE WIPER MOTOR	NOT NECESSARY	708.75	-
1	REAR W/SCREEN WITH MOULDING	NOT NECESSARY	2,043.26	-
1	TAILLAMP LH	BROKEN	309.75	309.75
1	TAILLAMP CLIP LH	NOT NECESSARY	5.25	-
1	TAILLAMP LH	NOT NECESSARY	309.75	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	278.25	-
1	TAILLAMP CLIPS LH	NOT NECESSARY	5.25	-
1	REAR BUMPER	DENTED	573.30	573.30
1	REAR BUMPER BRACKET LH	BROKEN	40.95	40.95
1	REAR BUMPER BRACKET RH	BROKEN	40.95	40.95
1	REAR BUMPER SIDE RETAINER LONG LH	NOT NECESSARY	89.25	-
1	REAR BUMPER SIDE RETAINER SHORT LH	NOT NECESSARY	40.95	-

Report Ref No. CS/INC19004122/Evd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SIDE RETAINER LONG RH	NOT NECESSARY	89.25	-
1	REAR BUMPER SIDE RETAINER SHORT RH	NOT NECESSARY	40.95	-
1	REAR BUMPER REFLECTOR LH	BROKEN	51.45	51.45
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	51.45	-
1	REAR BUMPER TOW COVER LH	NOT NECESSARY	24.15	-
1	REAR BUMPER PANEL INNER	NO SUCH PARTS	341.25	-
1	REAR END PANEL OUTER	DENTED	694.05	694.05
1	REAR END PANEL TOP GARNISH	CRUSHED	282.45	282.45
1	SPARE WHEEL PANEL	TO REPAIR SEE LABOUR	819.00	-
1	SPARE WHEEL PANEL TOP BOARD	NOT NECESSARY	1,338.75	-
1	SPARE WHEEL PANEL GARNISH	CRUSHED	183.75	183.75
1	SPARE WHEEL PANEL LINING	NOT NECESSARY	173.25	-
1	REAR END PANEL BRACKET LH	BENT	36.75	36.75
1	REAR END PANEL BRACKET RH	BENT	36.75	36.75
1	REAR LH FENDER INNER LOWER GARNISH	NOT NECESSARY	185.85	-
1	REAR RH FENDER INNER LOWER GARNISH	NOT NECESSARY	185.85	-
1	REAR LH FENDER INNER LOWER GARNISH TOOLS COVER	NOT NECESSARY	310.80	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	886.20	-
1	REAR WIRE HARNESS	NOT NECESSARY	206.85	-
1	REAR GLASS MOULDING (ADDITIONAL)	NECESSARY	180.00	180.00
	LESS 25% DISCOUNT		-3,931.04	-1,519.72
			11,793.12	4,559.18
	SPECIAL NETT ITEMS			
1	REAR W/SCREEN SEALANT (SN)	NECESSARY	80.00	80.00
1	REAR W/SCREEN SOLAR TRIM (SN)	NECESSARY	280.00	100.00
1	SET TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	TAILGATE IN-CAR REAR VIEW CAMERA (SN)	NOT NECESSARY	300.00	-
1	TAILGATE REAR GARNISH REVERSE CAMERA (SN)	NOT NECESSARY	250.00	-
1	REAR BUMPER REVERSE CAMERA (SN)	NOT NECESSARY	250.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	BROKEN	250.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	100.00	30.00

Report Ref No. CS/INC19004122/Evd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE CENTRE SPOILER (SN)	BROKEN	400.00	200.00
1	SET TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	100.00	20.00
1	SET TAILGATE INNER TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET TAILGATE INNER SIDE GARNISH CLIPS (SN)	NECESSARY	50.00	10.00
1	SET TAILGATE INNER SIDE GARNISH RH CLIPS (SN)	NECESSARY	50.00	10.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	10.00
1	SET SPARE WHEEL GARNISH CLIPS (SN)	NECESSARY	50.00	10.00
1	SET SPARE WHEEL PANEL LINING CLIPS (SN)	NECESSARY	100.00	10.00
1	SET REAR LH FENDER INNER LOWER GARNISH CLIPS (SN)	NECESSARY	100.00	10.00
1	SET REAR RH FENDER INNER LOWER GARNISH CLIPS (SN)	NECESSARY	100.00	10.00
1	REAR END PANEL TOP GARNISH CHROME PLATE (SN)	DENTED	250.00	150.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	30.00
1	SPARE WHEEL PANEL SEALANT (SN)	NECESSARY	80.00	30.00
1	SPARE WHEEL PANEL INSULATION (SN)	NOT NECESSARY	250.00	-
1	REAR NO. PLATE (SN)	NOT NECESSARY	180.00	-
			3,450.00	940.00
	LABOUR			
	LABOUR. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL LH, SPARE WHEEL PANEL AND REAR LH FENDER.		2,000.00	1,400.00
	SPRAY PAINTING.		2,000.00	1,400.00
	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING.		150.00	30.00
	REPLACE REAR WINDSCREEN.		150.00	100.00
	REMOVE + REFIT TAILGATE TOP GARNISH FACILITATE REPAIR.		200.00	20.00
	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE.		300.00	50.00
	ANTI-RUST CORROSION.		300.00	20.00
	REMOVE AND REINSTALL, CUSHIONS, SEATS, BACKREST, LINING, GARNISH AND UPHOLSTERY TO FACILITATE REPAIRS.		500.00	200.00
	REMOVE & REFIT REAR EXHAUST SYSTEM TO ASSIST REPAIR.	NOT NECESSARY	200.00	-

Report Ref No. CS/INC19004122/Evd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACE REAR REVERSE SENSOR + CHECK FUNCTION.		60.00	20.00
	REPLACE TAILGATE SPOILER.		150.00	30.00
	REMOVE & REFIT REAR UNDERCARRIAGE TO ASSIST REPAIR.	NOT NECESSARY	400.00	-
	TO DO UP WHEEL ALIGNMENT.	NOT NECESSARY	180.00	-
			6,590.00	3,270.00
GRAND TOTAL			21,833.12	8,769.18
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				7,000.00

Report Ref No. CS/INC19004122/Evd3s2

CHEN TSUE YEE

Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.