

ASS. REC. BY:

REF: CS/CT/19004128/Bsd302

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person);

Boon Leng

of

China Tai Ping

Date/Time:

6/3/2019 10:28am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 1235Y

Insured:

PH 2861 L

at Workshop m/s

CAS Barage Pte Ltd

Tel:

of

Kaki Bukit

Ave 6

#02-27

Policy No:

Claim No:

SNW19D201064

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

1	3	19
---	---	----

CA / REV / REP. / REV 24 HRS

6/3/19

H.O.D. Endorsement:

Date/Time: _____

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKA 1235Y-X

PH 2861 L-X

REF:

AXA

ASSIGNMENT

From: Date: 6/3/19

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SKA 12354

at Workshop m/s CAS Garage Pte Ltd

of 1 Kaki Bukit Ave 6 #02-22

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKA 12354 Yr Regn: 21/1/2011

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI TUCSON C.C. 159 1998

Colour: GREY A/C Insured / Std / NI / NA

Sp. Reading: 93466 T/Radio: Insured / Std / NI / NA

Eng/No: G4KDA11026207

C/No: KMHJ4818MBU114600

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/60/17

R: 225/60/17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 1/3/19 D.O.I. 6/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 6,000 - 7,500

Lm

RECEIVED 04 JUN 2019

PIS see my remarks

31/05/19 Confirmed HS \$6,250/- @ 6 days with LTG.

(\$ 7,909.68 Red - 56%)

MV 23,000/-

HS 6,250/-

PV 20,670/-

NV 2,330/-

TCLM 31/5/19

Date/Time, File Pass to?



: Prel. Report

04/06/19

1) Typ. 24



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$) 6,250/- HS

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

TOTAL

220

220

Nivitha (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Wednesday, 6 March 2019 12:47 PM
To: assignments
Subject: FW: ACCIDENT INVOLVING SKA1235Y &PH2861L AT UPPER SERANGOON VIEW / our re: SNM19D201064

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

mm Cum
(nt)

From: Allan Goh <allangoh.cas@gmail.com>
Sent: Wednesday, 6 March 2019 10:28 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: casgaragesg@gmail.com; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: ACCIDENT INVOLVING SKA1235Y &PH2861L AT UPPER SERANGOON VIEW / our re: SNM19D201064

Hi Boon Sen,

Please help to arrange for PRI at the soonest .

The vehicle is in our workshop since Monday.

Regards,
Allan Goh
CAS Garage Pte. Ltd.
No.1 Kaki Bukit Ave 6
#02-22
Singapore 417883
UEN: 201828067M
Tel: 6484 2220
Mobile: 8782 7171

On Tue, Mar 5, 2019 at 5:03 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sir,

We pri.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Allan Goh [<mailto:allangoh.cas@gmail.com>]

Sent: Tuesday, 5 March, 2019 4:57 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: casgaragesg@gmail.com

Subject: Re: ACCIDENT INVOLVING SKA1235Y &PH2861L AT UPPER SERANGOON VIEW

Hi Boon Seng,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0422A
Vehicle Details	
Vehicle No.:	SKA1235Y
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Mar 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	LM TUCSON 2.0L AUTO ABS D/AB S/R
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	G4KDAU026207
Chassis No.:	KMHJU81BMBU114690
Maximum Power Output:	122.0 kW (163 bhp)
Open Market Value:	\$17,601.00
Original Registration Date:	21 Jan 2011
First Registration Date:	21 Jan 2011
Transfer Count:	0
Actual ARF Paid:	\$17,601.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jan 2021
PARF Rebate Amount:	\$9,680.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jan 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$58,910.00
COE Rebate Amount:	\$10,990.00
Total Rebate Amount:	\$20,670.00

The information contained herein is correct as at 08 Mar 2019

OK

COE left 1yr 10 months

MV 23,000/2

PV 20,670/2

NV 2,330/2

Shirley Hiew (LKK Auto)

From: Allan Goh <allangoh.cas@gmail.com>
Sent: Tuesday, 4 June 2019 11:43 AM
To: Shirley Hiew (LKK Auto)
Cc: TG Lim (LKK Auto); casgaragesg@gmail.com; Nicole Chong
Subject: Re: ACCIDENT INVOLVING SKA1235Y &PH2861L AT UPPER SERANGOON VIEW / our re: SNM19D201064

Dear Shirley,

We will accept the finalized amount of \$6250 for the final repair cost.

Thank you

Regards,
Allan Goh
CAS Garage Pte. Ltd.
No.1 Kaki Bukit Ave 6
#02-22
Singapore 417883
UEN: 201828067M
Tel: 6484 2220
Mobile: 8782 7171

On Tue, Jun 4, 2019 at 11:41 AM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Allan,

According to our surveyor Mr. Lim, please re-confirm final fig \$ 6,250.00 (lump sum) @ 6 days of repairs.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Allan Goh [<mailto:allangoh.cas@gmail.com>]
Sent: Monday, 3 June 2019 5:27 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; teowguan@lkkauto.com

Cc: casgaragesg@gmail.com; Nicole Chong <nicolechong.cas@gmail.com>

Subject: Re: ACCIDENT INVOLVING SKA1235Y &PH2861L AT UPPER SERANGOON VIEW / our re: SNM19D201064

Dear Mr Lim,

There are a few items which are damaged but not ticked:

The silencer box

Silencer box mounting

Rear Floor panel

Rear Floor panel top board

Based on my calculation Lumpsum repair cost is \$6839.

Kindly agree the finalized amount at \$6800 , and to close the case.

Thank you.

Regards,

Allan Goh

CAS Garage Pte. Ltd.

No.1 Kaki Bukit Ave 6

#02-22

Singapore 417883

UEN: 201828067M

Tel: 6484 2220

Mobile: 8782 7171

On Mon, Jun 3, 2019 at 4:22 PM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Allan,

Please confirm final fig \$ 6,050.00 (lump sum) @ 6 days of repairs.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	01/03/2019 17:15
Date Of Accident	01/03/2019 14:35
Exact Location Of Accident	UPPER SERANGOON VIEW
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKA1235Y
Insured/Policyholder	
Name Of Registered Owner	ALICE YEO PUAY KOON
NRIC No	S1790422A
Email Address	ALIZANG@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96603258
Alternative Phone No	OFFICE-96603258
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	TUCSON-1.6 GLS TURBO (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1241895
Cover Note Number	
Driver	
Name of Driver	ANG HOCK LYE
NRIC No	S1762059B
Date Of Birth	04/01/1966
Occupation	INDOOR
Date Of Driving Pass	31/01/1985
Driving Experience	34 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96603258
Fax Number	
Contact Number	
EMail Address	ALIZANG@SINGNET.COM.SG

Address	BLK 272A SENGKANG CENTRAL #12-303 SINGAPORE
Postcode	541272
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ALICE YEO PUAY KOON GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PH2861L
Vehicle Make/Model/Colour	EXCURSION BUS
Details Of Properties	
Vehicle Category	BUS
Name of Driver	ABDUL LATIFF BIN HASSAN
NRIC/Passport Number	S1584756E
Contact Number	81223294
Address	APT BLK 620HOUGANG AVE 8 #07-278 SINGAPORE
Postcode	530620
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers or the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application of interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claim;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes";
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers (agents) including their lawyers/law firms, which may be situated outside of Singapore for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile my history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud (regulators, law enforcement and government agencies as reasonably required for the purposes stated);
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 1/3/2019


Driver's Signature
(If driver is not the policyholder)
Date & Time: 1/3/2019


Reporting Centre Personnel's Signature
Name: _____

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Upper Serangoon Road. My car was stationary stopping at the traffic light. An excursion bus no PH2861L came from behind and hit directly onto the rear of my car SKA1235Y.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

1/3/2019 17:20pm 1/3/2019 17:20pm

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: CHINA TAIPING INSURANCE(SINGAPORE) PTE LTD

3, ANSON ROAD, #16-00, SPRINGLEAF TOWER

Address: S(079909)

Telephone: 63896111

Fax: 62221033

Email: e-claims@sg.cntaiping.com

Make/ Model : HYUNDAI TUCSON

Date: 05.03.2019

Chassis No : KMHJU81BMBU114690

Vehicle No: SKA1235Y

Date/Time of Accident : 01.03.2019/1435

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCO	FINAL PRICE \$
1	TAIL GATE	1	\$ 1,451.50	20%	\$ 1,161.20
2	TAIL GATE DASMPS	2	\$ 223.60	20%	\$ 178.88
3	TAIL GATE INNER POCKET	1	\$ 65.30	20%	\$ 52.24
4	TAIL GATE LOCK CATCH	1	\$ 45.60	20%	\$ 36.48
5	TAIL GATE INNER LOCK	1	\$ 158.20	20%	\$ 126.56
6	TAIL GATE INNER TRIM	1	\$ 408.90	20%	\$ 327.12
7	TAIL GATE REFLECTOR	2	\$ 490.60	20%	\$ 392.48
8	TAIL GATE SMART KEY ANTENNA	1	\$ 223.80	20%	\$ 179.04
9	TAIL GATE LOGO	1	\$ 60.50	20%	\$ 48.40
10	TAIL GATE "HYUNDAI" EMBLEM	1	\$ 55.60	20%	\$ 44.48
11	TAIL GATE "TUCSON" EMBLEM	1	\$ 52.60	20%	\$ 42.08
12	TAIL GATE WEATHERSTRIP	1	\$ 236.90	20%	\$ 189.52
13	REAR NUMBER PLATE LAMP	2	\$ 105.40	20%	\$ 84.32
14	REAR BUMPER TOP	1	\$ 523.10	20%	\$ 418.48
15	REAR BUMPER BOTTOM	1	\$ 432.20	20%	\$ 345.76
16	REAR BUMPER SIDE RETAINER	2	\$ 128.60	20%	\$ 102.88
17	REAR BUMPER REFLECTOR	2	\$ 150.80	20%	\$ 120.64
18	REAR BUMPER REINFORCEMENT	1	\$ 386.50	20%	\$ 309.20
19	REAR BUMPER SPONGE	1	\$ 145.30	20%	\$ 116.24
20	END PANEL	1	\$ 823.60	20%	\$ 658.88
21	END PANEL TOP GARNISH	1	\$ 135.70	20%	\$ 108.56
22	REAR TAIL LAMP	2	\$ 1,056.80	20%	\$ 845.44
23	REAR TAIL LAMP PANEL	2	\$ 523.60	20%	\$ 418.88
24	REAR SILENCER BOX	1	\$ 603.10	20%	\$ 482.48
25	REAR SILENCER BOX MOUNTING	2	\$ 126.50	20%	\$ 101.20
26	REAR FLOOR PANEL	1	\$ 688.90	20%	\$ 551.12
27	REAR FLOOR PANEL TOP BOARD	1	\$ 321.40	20%	\$ 257.12

Total List Price Cost**\$ 7,699.68**

SPECIAL NETT ITEM	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING	1SET	\$ 50.00		\$ 50.00
2	REAR WINDSCREEN GLASS SEALANT	2	\$ 80.00		\$ 60.00 80.00
3	REAR TAILGATE LED STRIP	1	\$ 250.00		\$ 250.00
4	TAILGATE STOPPER	2	\$ 60.00		\$ 60.00
5	REAR BUMPER CLIPS	1 SET	\$ 30.00		\$ 30.00
6	END PANEL SEALANT	2	\$ 80.00		\$ 60.00 80.00
7	REAR END PANEL TOP GARNISH CLIPS	1 SET	\$ 30.00		\$ 30.00

8	REVERSE SENSOR	1 SET	\$ 280.00	\$ 280.00	200.00 ✓
9	REVERSE CAMERA	1 SET	\$ 300.00	\$ 300.00	NNX
Total Special Nett Items				\$ 1,160.00	

Labour Works/ Panel Beating Related Works					
Job Scope				Quotation	
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGNE ALL PARTS				\$ 2,000.00	
				1000.00	
Spray Painting					
Job Scope				Quotation	
TO RESPRAY AFFECTED AREAS				\$ 1,600.00	
				700.00	
Others Cost (Accident Repair Related Expenses)					
Job Scope				Quotation	
TO REMOVE & REFIX REAR WINDSCREEN				\$ 120.00	150.00
TO TUFFCOAT AFFECTED AREA				\$ 60.00	200.00
TO APPLY UNDERCOATING ON REPAIRED & REPLACED PANELS				\$ 60.00	300.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY				\$ 100.00	150.00
REAR CHASSIS ALIGNMENT				\$ 120.00	NNX
TO REMOVE/ REFIT WIRING CHECKS				\$ 50.00	120.00
TO CONDUCT WATER LEAKAGE TEST				\$ 150.00	NNX
TO REMOVE/ REPLACE REAR SILENCER BOX				\$ 80.00	120.00
TO REMOVE/ REFIT/REPLACE REVERSE SENSORS				\$ 60.00	120.00
TO REMOVE/REFIT/ REPLACE REVERSE CAMERA				\$ 60.00	120.00
TO REMOVE/REMOVE/ REPLACE TAILGATE MECHANISM				\$ 60.00	150.00
Total Others Cost				\$ 1,700.00	
GRAND TOTAL				\$ 14,159.68	

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax: +65 6509 9501

? photo
 Lump sum repair
 Days of repair 6
 Terim lui, 9761577 97361577
 taowguan@lkkauto.com

**CAS GARAGE PTE LTD**

(Reg No. 201838067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATEInsurance Company: CHINA TAIPING INSURANCE(SINGAPORE) PTE LTD
3, ANSON ROAD, #16-00, SPRINGLEAF TOWER

Address: S(079909)

Telephone: 63896111

Fax: 62221033

Email: e-claims@sg.cntaiping.com

Make/ Model : HYUNDAI TUCSON

Date: 05.03.2019

Chassis No : KMHJU81BMBU114690

Vehicle No: SKA1235Y

Date/Time of Accident : 01.03.2019/1435

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCO	FINAL PRICE \$
1	TAIL GATE	1	\$ 1,451.50	20%	\$ 1,161.20
2	TAIL GATE DASH PERS	2	\$ 223.60	20%	\$ 178.88
3	TAIL GATE INNER POCKET	1	\$ 65.30	20%	\$ 52.24
4	TAIL GATE LOCK CATCH	1	\$ 45.60	20%	\$ 36.48
5	TAIL GATE INNER LOCK	1	\$ 158.20	20%	\$ 126.56
6	TAIL GATE INNER TRIM	1	\$ 408.90	20%	\$ 327.12
7	TAIL GATE REFLECTOR	1	\$ 245.30	20%	\$ 196.24
8	TAIL GATE SMART KEY ANTENNA	1	\$ 223.80	20%	\$ 179.04
9	TAIL GATE LOGO	1	\$ 60.50	20%	\$ 48.40
10	TAIL GATE "HYUNDAI" EMBLEM	1	\$ 55.60	20%	\$ 44.48
11	TAIL GATE "TUCSON" EMBLEM	1	\$ 52.60	20%	\$ 42.08
12	TAIL GATE WEATHERSTRIP	1	\$ 111.00	20%	\$ 88.80
13	REAR NUMBER PLATE LAMP	2	\$ 105.40	20%	\$ 84.32
14	REAR BUMPER TOP	1	\$ 523.10	20%	\$ 418.48
15	REAR BUMPER BOTTOM	1	\$ 298.60	20%	\$ 238.88
16	REAR BUMPER SIDE RETAINER	2	\$ 109.00	20%	\$ 87.20
17	REAR BUMPER REFLECTOR	2	\$ 150.80	20%	\$ 120.64
18	REAR BUMPER REINFORCEMENT	1	\$ 294.80	20%	\$ 235.84
19	REAR BUMPER SPONGE	1	\$ 145.30	20%	\$ 116.24
20	END PANEL	1	\$ 823.60	20%	\$ 658.88
21	END PANEL TOP GARNISH	1	\$ 135.70	20%	\$ 108.56
22	REAR TAIL LAMP	2	\$ 1,056.80	20%	\$ 845.44
23	REAR TAIL LAMP PANEL	2	\$ 523.60	20%	\$ 418.88
24	REAR SILENCER BOX	1	\$ 603.10	20%	\$ 482.48
25	REAR SILENCER BOX MOUNTING	2	\$ 126.50	20%	\$ 101.20
26	REAR FLOOR PANEL	1	\$ 688.90	20%	\$ 551.12
27	REAR FLOOR PANEL TOP BOARD	1	\$ 321.40	20%	\$ 257.12
Total List Price Cost					\$ 7,699.68

SPECIAL NETT ITEM	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING	1 SET	\$ 50.00		\$ 50.00
2	REAR WINDSCREEN GLASS SEALANT	2	\$ 80.00		\$ 80.00
3	REAR TAILGATE LED STRIP	1	\$ 250.00		\$ 250.00
4	TAILGATE STOPPER	2	\$ 60.00		\$ 60.00
5	REAR BUMPER CLIPS	1 SET	\$ 30.00		\$ 30.00
6	END PANEL SEALANT	2	\$ 80.00		\$ 80.00
7	REAR END PANEL TOP GARNISH CLIPS	1 SET	\$ 30.00		\$ 30.00

8	REVERSE SENSOR	1 SET	\$ 280.00	\$ 280.00	200.00 ✓
9	REVERSE CAMERA	1 SET	\$ 300.00	\$ 300.00	DM
Total Special Nett Items				\$ 1,160.00	NNX

Labour Works/ Panel Beating Related Works					570.00
Job Scope				Quotation	
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGN ALL PARTS				\$ 2,000.00	
Spray Painting					1000.00
Job Scope				Quotation	800.00
TO RESPRAY AFFECTED AREAS				\$ 1,600.00	
Others Cost (Accident Repair Related Expenses)					900/2 700.00
Job Scope				Quotation	
TO REMOVE & REFIX REAR WINDSCREEN				\$ 120.00	150.00
TO TUFFCOAT AFFECTED AREA				\$ 60.00	200.00
TO APPLY UNDERCOATING ON REPAIRED & REPLACED PANELS				\$ 60.00	300.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY				\$ 100.00	150.00
REAR CHASSIS ALIGNMENT				\$ 120.00	NNX
TO REMOVE/ REFIT WIRING CHECKS				\$ 50.00	120.00
TO CONDUCT WATER LEAKAGE TEST				\$ 150.00	NNX
TO REMOVE/ REPLACE REAR SILENCER BOX				\$ 80.00	120.00
TO REMOVE/ REFIT/REPLACE REVERSE SENSORS				\$ 60.00	120.00
TO REMOVE/REFIT/ REPLACE REVERSE CAMERA				\$ 60.00	120.00
TO REMOVE/REMOVE/ REPLACE TAILGATE MECHANISM				\$ 60.00	150.00
Total Others Cost				\$ 1,700.00	
GRAND TOTAL				\$ 14,159.68	

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax: +65 6509 9501

[Signature]
 12/3/19

Parts 5044.08
 SN 570.00
 labour 2210.00
 7824.08
 @20% 1564.82
 6,259.26

Resurvey 7/3/19
 1440 hrs

Terim lui

Lump sum repair

Days of repair 6

4/3 6,250/2

Terim lui, 9761577 97361577

taowguan@lkkauto.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2019		06 Mar 2019 15:54 Edit Adj Rpt	S\$6,250.00 Edit Estimates	S\$6,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ALICE YEO PUAY KOON, ID: S1790422A								
Vehicle Reg. No.:	SKA1235Y	Date of Loss:	01/03/2019 14:00 - :59 [97 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201064C02	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	PH2861L	Policy No. (Claimant):	VPA/P1241895						
		Excess:	S\$0.00						
Repairer:	Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 15/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKA1235Y (SNM19D201064C02)
[PH2861L]
TP
ALICE YEO PUAY KOON
Mar 1 2019 2:00PM
[-]
Cas Garage Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Komoco Motors Pte Ltd (Bukit Merah)								Thumbnail	Print	
1	01/03/19 17:30	Accident Statement								Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Komoco Motors Pte Ltd (Bukit Merah)								Thumbnail	Print	
1	01/03/19 17:28	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
2	01/03/19 17:28	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
3	01/03/19 17:28	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
4	01/03/19 17:28	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
5	01/03/19 17:28	Driving License [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
2	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
3	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
4	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
5	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
6	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
7	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
8	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
9	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
10	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
11	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
12	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
13	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
14	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
15	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
16	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
17	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
18	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
19	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
20	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
21	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
22	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
23	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
24	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
25	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	
26	03/06/19 11:22	General View								Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Komoco Motors Pte Ltd (Bukit Merah)	Thumbnail	Print
27	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
28	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
29	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
30	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
31	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
32	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
33	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
34	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
35	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
36	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
38	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/06/19 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	03/06/19 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Komoco Motors Pte Ltd (Bukit Merah)		Thumbnail	Print
No	Finalized On	Komoco Motors Pte Ltd (Bukit Merah)		Thumbnail	Print
1	01/03/19 17:27	Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	01/03/19 17:27	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/03/19 15:55	PRI CONTACT		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Komoco Motors Pte Ltd (Bukit Merah)		Thumbnail	Print
1	01/03/19 17:30	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Komoco Motors Pte Ltd (Bukit Merah)		Thumbnail	Print
1	01/03/19 17:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	01/03/19 17:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	01/03/19 17:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	01/03/19 17:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	01/03/19 17:28	Driving License		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Komoco Motors Pte Ltd (Bukit Merah)		Thumbnail	Print
1	01/03/19 17:27	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	01/03/19 17:27	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19004128/BSD3E2

Date: 28/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No : SKA1235Y

Insured Vehicle No :

PH2861L

Date of Loss: 01/03/2019

Nature of Claim:

TP

Claim No:

SNM19D201064C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA1235Y

Make & Model: HYUNDAI TUCSON, 1.6 GLS TURBO (A)

Engine No: G4KDAU026207

Reg. Date: 21/01/2011 (Man. Year: 2010)

Chassis No: KMHJU81BMBU114690

Colour: Grey

Odometer: 93466 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size: 225/60 R17

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,859.68	5,614.08	3,245.60	36.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,300.00	2,210.00	3,090.00	58.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,159.68	7,824.08	6,335.60	44.74
Approved Total (Overridden) (S\$)		6,250.00		
Nett Amount (S\$)	14,159.68	6,250.00	7,909.68	55.86

INSPECTION

Date of Assignment: 06/03/2019

Date Inspected: 06/03/2019 Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22 Autobay
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2019)	
Parts: M1-SUV	HYUNDAI TUCSON 1.6 GLS TURBO (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKA1235Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,451.50 FL	*1,451.50 FL
2	2		*TAIL GATE DASMPERS	Not Necessary	223.60 FL	*- FL
3	1		*TAIL GATE INNER POCKET	Not Necessary	65.30 FL	*- FL
4	1		*TAIL GATE LOCK CATCH	Not Necessary	45.60 FL	*- FL
5	1		*TAIL GATE INNER LOCK	Bent	158.20 FL	*158.20 FL
6	1		*TAIL GATE INNER TRIM	Broken	408.90 FL	*408.90 FL
7	1		*TAIL GATE REFLECTOR	O/S Broken	490.60 FL	*245.30 FL
8	1		*TAIL GATE SMART KEY ANTENNA	Bent	223.80 FL	*223.80 FL
9	1		*TAIL GATE LOGO	Necessary	60.50 FL	*60.50 FL
10	1		*TAIL GATE HYUNDAI EMBLEM	Necessary	55.60 FL	*55.60 FL
11	1		*TAIL GATE TUCSON EMBLEM	Necessary	52.60 FL	*52.60 FL
12	1		*TAIL GATE WEATHERSTRIP	Cut	236.90 FL	*111.00 FL
13	2		*REAR NUMBER PLATE LAMP	Not Necessary	105.40 FL	*- FL
14	1		*REAR BUMPER TOP	Cracked	523.10 FL	*523.10 FL
15	1		*REAR BUMPER BOTTOM	Cracked	432.20 FL	*298.60 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	128.60 FL	*109.00 FL
17	2		*REAR BUMPER REFLECTOR	Broken	150.80 FL	*150.80 FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	386.50 FL	*294.80 FL
19	1		*REAR BUMPER SPONGE	Broken	145.30 FL	*145.30 FL
20	1		*END PANEL	Dented	823.60 FL	*823.60 FL
21	1		*END PANEL TOP GARNISH	Dislodged	135.70 FL	*135.70 FL
22	2		*REAR TAILLAMP	Crumpled	1,056.80 FL	*1,056.80 FL
23	2		*REAR TAIL LAMP PANEL	Not Necessary	523.60 FL	*- FL
24	1		*REAR SILENCER BOX	Not Necessary	603.10 FL	*- FL
25	2		*REAR SILENCER BOX MOUNTING	Not Necessary	126.50 FL	*- FL
26	1		*REAR FLOOR PANEL	Not Necessary	688.90 FL	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	321.40 FL	*- FL
28	1		*SET REAR NUMBER PLATE WITH CASING	Bent	50.00 FS	*40.00 FS
29	2		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
30	1		*REAR TAILGATE LED STRIP	Shorted	250.00 FS	*150.00 FS
31	2		*TAILGATE STOPPER	Not Necessary	60.00 FS	*- FS
32	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
33	2		*END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
34	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
35	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
36	1		*SET REVERSE CAMERA	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **10,784.60** **6,875.10**
- List Item Discount on L Items 20.00/20.00% (\$\$) **1,924.92** **1,261.02**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	8,859.68	5,614.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	New	2,000.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	1,600.00	900.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TUFFCOAT AFFECTED AREA	New	200.00	60.00
5	TO APPLY UNDERCOATING ON REPAIRED & REPLACED PANELS	New	300.00	60.00
6	TO REMOVE / REFIT INTERIOR UPHOLSTERY	New	150.00	100.00
7	REAR CHASSIS ALIGNMENT	New	120.00	0.00
8	TO REMOVE / REFIT WIRING CHECKS	New	120.00	50.00
9	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
10	TO REMOVE / REPLACE REAR SILENCER BOX	New	120.00	0.00
11	TO REMOVE / REFIT / REPLACE REVERSE SENSORS	New	120.00	60.00
12	TO REMOVE / REFIT / REPLACE REVERSE CAMERA	New	120.00	0.00
13	TO REMOVE / REPLACE TAILGATE MECHANISM	New	150.00	60.00
Gross Labour Cost (\$\$)			5,300.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >