

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 20 Mar 2019

Preliminary Advice

Vehicle No	: SKE5659K	Accident Date	: 28/02/2019
Make	: MERCEDES-BENZ C180K	Policy No.	: DMPSCN1309111805
Assignment Date	: 06/03/2019	Excess	: S\$0.00
Date of Inspection	: 20/03/2019	Est. Duration of Repair	: 5 days
Inspection At	: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,202.13
Revised Amount	:S\$	3,618.13
Check Items (Estimated)	:S\$	456.00
Total	:S\$	4,074.13

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	41,000.00
COE / PARF Rebate	:S\$	25,907.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,093.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :