


Hsiao Tony



MBM WHEELPOWER PTE LTD

Your Ref: GBC7891J

Our Ref: SKT7823K

To: AXA

CC

Fax

Date: 6/3/2019
 From: Danny
 Fax: 64525333
 Contact: 93288668
 Make / Model: TOYOTA WISH 1.8X A
 Chassis No.: ZGE206020287
 Engine No.: 2ZR1516339
 Year of Make: 2016
 Accident Date: 4 March 2019

ESTIMATE FOR VEHICLE NO.: SKT7823K

DESCRIPTION	QTY	List Price
REAR WINDSCREEN MOULDING	NEC ✓ 1	\$ 158.00 210.00
TAIL GATE	DDV ✓ 1	\$ 1468.10 1,819.00
TAIL GATE HINGE LH	NNX 1	\$ -103.00
TAIL GATE HINGE RH	NNX 1	\$ -103.00
TAIL GATE WEATHERSTRIP	CUT ✓ 1	\$ 403.00
TAIL GATE LOCK	? BR ✓ 1	\$ 431.00
TAIL GATE STRIKER	? NN 1	\$ 75.00
TAIL GATE STAY LH	1	\$ -283.00
TAIL GATE STAY RH	1	\$ -283.00
TAIL GATE INNER TRIM BOARD	? DIS ✓ 1	\$ 420.00 420.00
TAIL GATE INNER TRIM BOARD CLIPS	NEC ✓ 10	\$ 30.00 60.00
TAIL GATE INNER DOOR PULL HANDLE	NNX 1	\$ 79.00
REAR BUMPER	DDV ✓ 1	\$ 1189.00 1,435.00
REAR BUMPER CLIPS	NEC ✓ 10	\$ 30.00 -60.00
REAR BUMPER RH SIDE RETAINER	1	\$ 69.30 76.00
REAR BUMPER LH SIDE RETAINER	1	\$ 69.30 76.00
REAR BUMPER LH SUPPORT	? BT ✓ 1	\$ 74.50 114.00
REAR BUMPER RH SUPPORT	? BT ✓ 1	\$ 74.50 114.00
REAR BUMPER LH REFLECTOR	? BR ✓ 1	\$ 85.00
REAR BUMPER RH REFLECTOR	? BR ✓ 1	\$ 85.00
END PANEL	? DD ✓ 1	\$ 655.00
END PANEL TOP GARNISH	? BR ✓ 1	\$ 327.00
END PANEL TOP GARNISH CLIPS	NEC? ✓ 10	\$ 30.00 -60.00
Total:	\$	5516.98 7,356.00
LESS 25%	\$	1390.48 + 112.39 (1,839.00)
Parts Total:	\$	4447.52 5,517.00

4171.43

SPECIAL NETT

BODY SEALANT	?	1	\$ NECV	60.00	-80.00
WINDSCREEN SEALANT		1	\$ NECV	60.00	-80.00
REVERSE SENSOR	CUT ✓	1 SET	\$	200.00	400.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	600.00	1,200.00
TO REMOVE AND RE-FIT REAR WINDSCREEN	\$	100.00	150.00
TO DISMANTLE & TRANSFER TAIL GATE FITTINGS & MECHANISM TO NEW TAILGATE / FACILITATE REPAIR	\$	NX	-80.00
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$		-100.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	100.00	150.00
TO REMOVE & REPLACE BUMPER SENSORS	\$	✓	40.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	50.00 ✓	80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	600.00	1,000.00
Total:	\$		8,877.00
7% GST:	\$		621.39
Grand Total:	\$		9,498.39

Repair day 4

? photo

Termin lin

97361577

28/3/19

1115 hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


Parts	4449.52	5200.66
SN	320.00	320.00
Labour	1450.00	1450.00
	6213.52	6970.66
@20%	1243.70	1394.13
	4775.62	5576.53

4/5 4900/2
5550/2

Mbm wheelpower pte ltd
160 SIN MING DRIVE
#06-02
SIN MING AUTOCITY
162628888 164525333

Company Registration Number : 200204110W

MBM WHEELPOWER PTE LTD



Your Ref: GBC7891J

Our Ref: SKT7823K

To: AXA

CC

Fax

Steve 29/3/19

Date: 28/3/2019
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: TOYOTA WISH 1.8X A
Chassis No.: ZGE206020287
Engine No.: 2ZR1516339
Year of Make: 2016
Accident Date: 4 March 2019

SUPPLEMENTARY ESTIMATE FOR VEHICLE NO. : SKT7823K

DESCRIPTION

TAIL GATE LAMP RH *✓ CPA*
TAIL GATE LAMP LH *✓ BR*
REAR RH FENDER INNER GARNISH TRIM *✓ BR*
REAR ANTENNA ASSY *✓ BR*
REAR REINFORCEMENT BRACKET RH *✓ BT*

QTY		List Price	
1	\$	291.60	352.00
1	\$	291.60	352.00
1	\$	425.10	560.00
1	\$		182.00
1	\$		162.00
Total:		\$ 1372.30	1,608.00
LESS 25%		\$ 243.08	(402.00)
Parts Total:		\$ 1029.23	1,206.00

\$1206

Mbm wheelpower pte ltd
160 SIN MING DRIVE
#06-02
SIN MING AUTOCITY
t62628888 f64525333
Company Registration Number : 200204110W