

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5107H**AAD1903-009***Not Authorized*
11/2/2013 \$1850/

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5107H

VF1ABL15AUC276178

RENAULT

LATITUDE

28.2.2019

AXA

27/12/2013

PART**LIST**

- | | |
|----|--------------------------------|
| 1 | 1 BUMPER COVER REAR |
| 2 | 1 BUMPER LOWER REAR |
| 3 | 1 BUMPER BRACKET CTR REAR |
| 4 | 1 BUMEP R BRACKET SIDE RH REAR |
| 5 | 1 BUMEP R RETAINER RH REAR |
| 6 | 1 BUMPER REFLECTOR RH |
| 7 | 1 BUMEP R BRACKET SIDE LH REAR |
| 8 | 1 BUMEP R RETAINER LH REAR |
| 9 | 1 BUMPER REFLECTOR LH |
| 10 | 1 BUMPER BEAM REAR |
| 11 | 1 BUMPER BEAM BRACKET LH REAR |
| 12 | 1 BUMPER BEAM BRACKET RH REAR |
| 13 | 1 BOOT REAR |
| 14 | 1 BOOT FINISHER |
| 15 | 1 BOOT WHEATERSTRIP |
| 16 | 1 BOOT REFLECTOR LAMP LH |
| 17 | 1 BOOT REFLECTOR LAMP RH |
| 18 | 1 BOOT BADGE 'RENAULT' |
| 19 | 1 BOOT BADGE |
| 20 | 1 BOOT STRUT LH |
| 21 | 1 BOOT STRUT RH |
| 22 | 1 BOOT HINGE LH |
| 23 | 1 BOOT HINGE RH |
| 24 | 1 BOOT INNER TRIM |
| 25 | 1 BOOT SWITCH |
| 26 | 1 BOOT LOCK |
| 27 | 1 BOOT LOCK CATCH |
| 28 | 2 LICENCE PLATE LAMP |
| 29 | 2 BOOT RUBBER PLUG |

\$	<i>Bul/Ad</i>	1,108.46	✓
\$	<i>cm</i>	768.84	✓
\$	<i>sn</i>	113.47	✓
\$	<i>sn</i>	135.97	
\$	<i>sn</i>	44.99	
\$	<i>sn</i>	43.61	
\$	<i>sn</i>	135.97	
\$	<i>sn</i>	44.99	
\$	<i>sn</i>	43.61	
\$	<i>n</i>	777.52	
\$	<i>n</i>	225.95	
\$	<i>n</i>	225.95	
\$	<i>n</i>	2,872.68	
\$	<i>sn</i>	470.06	
\$	<i>sn</i>	323.05	
\$	<i>sn</i>	493.35	
\$	<i>sn</i>	493.35	
\$	<i>na</i>	225.36	
\$	<i>na</i>	225.36	
\$	<i>sn</i>	276.08	
\$	<i>sn</i>	276.08	
\$	<i>n</i>	367.84	
\$	<i>n</i>	367.84	
\$	<i>sn</i>	586.45	
\$	<i>sn</i>	168.13	
\$	<i>n</i>	202.67	
\$	<i>R</i>	74.40	
\$	<i>sn</i>	50.52	
\$	<i>sn</i>	221.81	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5107H**AAD1903-009**

30	1 FENDER PANEL REAR LH	\$	N	3,299.13	}
31	1 WHEELARCH REAR LH	\$	Sn	543.47	
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	
33	1 WHEEL HOUSING PANEL REAR LH	\$	N	4,682.09	
34	1 TAILLAMP LH	\$	Sn	552.55	
35	1 TAILLAMP PANEL LH	\$	N	986.70	
36	1 TAILLAMP RH	\$	Sn	552.55	
37	1 TAILLAMP PANEL RH	\$	N	986.70	
38	1 OUTER PANEL REAR (End Panel)	\$	N	1,471.77	
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	2,189.88	
41	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	
42	1 EXHAUST REAR	\$	N	7,489.05	
43	1 EXHAUST CAP REAR	\$	N	230.49	
44	1 FENDER PANEL REAR RH	\$	N	3,299.13	
45	1 WHEELARCH REAR RH	\$	Sn	543.47	
46	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
47	1 WHEEL HOUSING PANEL REAR RH	\$	N	4,682.09	

TOTAL	\$	45,233.12
10%	\$	4,523.31
	\$	40,709.81

Special Nett

1	1SET PARKING AID	\$	Sn	700.00	X
2	1SET REAR BUMPER CLIP	\$	ne	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	ne	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	ne	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	nn	17.82	X
11	1SET BOOT FINISHER CLIP	\$	nn	24.20	X
12	1 REAR BOOT ADVERTISEMENT STICKER	\$	nn	80.00	X
13	1 REAR BOOT ADVERTISEMENT STICKER	\$	nn	80.00	X

Trans-cab Auto Services Pte Ltd**AAD1903-009**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5107H

14	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	}	X
15	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00		
16	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
18	1 TAILLAMP CLIP RH	\$	na	5.00		
19	1 TAILLAMP CLIP LH	\$	na	5.00		
20	2 REAR WINDSCREEN SELANT	\$	na	80.00		
21	1 WINDSCREEN MOULDING	\$	na	100.00		
22	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
23	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na	385.00		
24	1 SPARE TYRE	\$	na	330.00		

TOTAL \$ 2,280.02**TOTAL PARTS \$ 42,989.83****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00 X
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1903-009**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5107H

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>↪</i> 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>↪</i> 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>↪</i> 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>↪</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>↪</i> 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>↪</i> 380.00	X

TOTAL \$ 14,340.00**Over All Total \$ 57,329.83****(LUMP SUM)****Repair Days****~~20 DAYS~~***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: