



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 5th March 2018

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Raffles Way #07-16
AIG Building
Singapore 078120

Dear Sirs

Re: Cost of repair to Kian Lou Duke - FBJ7544A

1 pc of Front signal	LH	RR	18	\$15.00 /
" Handle bar	BT			225.00 /
" Rear absorber swing arm	BT			490.00 /
" Rear spoke rim	- BT			550.00 /
" Rear Explorer box	- CUT			550.00 /
" Side stand	/ BT			15.00 /
" Rear box bracket (Explorer)	-			250.00 /
" Mirror	LH / CUT			120.00 /
" Clutch lever	/ BT			45.00 /
				<u>2,400.00</u>
				240.00
				<u>2,160.00</u>

Less 10%

Nett

Alignment fork
Transport

75.00 50%

250.00 100%

2,485.00

Yours faithfully,
SOUTHERN MOTOR

Steve (LKK) with Principal

83228813

6/3/19 3.00pm

Steve.chm@lkkauto.com

3 chgs L/S

Rey ATL Spry

Tel 6493000
Fax 64153720