PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

5-Mar-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1387 L

				\$	362.61 XR
1 pc	Tailgate lower garnish			\$	27.80 Na 29.40 Na 29.40
1 pc	Emblem I30				20.40
1 pc	Emblem CRDI			\$	29.40 Mrs
1 pc	Emblem Hyundai		\$	811.11 / CRY	
1 pc	Rear bumper			\$	811.11
1 pc	Rear bumper sponge		\$	79.20 ?	
1 pc	Rear bumper reinforcement		\$	815.64 ?	
1 pc	Rear bumper reinforcement centre		\$	79.20 ?	
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20		\$	104.40 ?	
2 pcs	Rear bumper n/s @ o/s reflector @ \$107.50		\$	215.00 X SV C	
2 pcs				\$	2,553.76
		Less	20%	\$	510.75
		LKK Auto Consultants hence notify	7	\$	2,043.01
S/NETT		the Repairer of the following:			
	Rear bumper clips	 To recurvey before/after spray painting 		\$	48.00 /NEL
1 set		To display damaged part(s) during resurvey Parts prices are subject to confirmation		\$	280.00 ?
1 set	Reverse sensor	 Third party survey is on a "Without Prejudice" basis 		\$	100.00 NEC
1 set	Tailgate stickers	 No illegal modification(s) is allowed 		\$	28 00 × NN
1 set	Tailgate lower garnish clips	 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 			30.00 / CRK
	Rear Number Plate			4	50.00 × NN
	Sundry	Acknowledged by Repairer	-1	\$	
	To dismontle and replace reve	Signature:		\$	80.00 30
To dismantle and replace reverse sensor and test system					
	To labour charge for dismantle and renew the accident				
	damaged parts. Including to knock-out, straighten, repair, reshape of the tailgate, end panel, etc		\$	900.00 360	
	To putty and spray painting on the rear bumper, tailgate, tailgate		\$	800.00 360	
	lower garnish, end panel			φ	000.00
				\$	120.00 50
	To apply rustproofing on the repaired and replaced panels				
			Γotal	\$	4,449.01
	AND REPAIR COSTS ARE SUBJECTED TO GST				
	(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)		N	JA2	LKK
	THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE			513/19 1630	
			1311	2 2-101	
				Pl	e 3 DAYS
	CH			+ BCK	- ITEMS (401)
				0	ECK ITEMS PHOTOS
	34				UNI