	ASSIGNME	004147/Atd3n2 Special Instruction:
	From (Person): The Swell Clong of Fire	3t Capital Date/Time: 6/3/19
	Estimated Cost:	Bill to:
	To Inspect Vehicle No: SHA-HOOD	Insured: SHA37576
	at Workshop m/s Prem'ium	Tel:
	of 55 Upi Ave 1	
	Policy No: 0-1909 2580 MFSH	Claim No:
	Sum Insured:	Excess:
	Make of Veh: (Client's Record)	D.O.A.
-	CA / REV / REP. / REV 24 HRS \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	H.O.D. Endorsement: Vehicle IN / OHT
	Date/Time Action/Instruction () Estimate	
	8/3/19/010:36am- Revised via	emai pre li aduje
	Part my Part \$9964.	20 CRED. 4234.80 !29%)
	1 days	

Preli. Report:

Final Report:

50

Photos

Others

TOTAL



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D/191538

Date: 8/3/2019

Our Ref: CS/FCI19004147/Atd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGA 7700D

Please be informed that we had conducted the inspection of the abovementioned vehicle 6/3/2019 at the premises of M/s Premium have the following to report: -

Workshop Estimate Amount	: S\$	11,799.00
Revised Estimate Amount	: S\$	8,159.00
"Check" Items Amount	: S\$	2,381.00
Market Value	: <u>S\$</u>	
LTA Reimbursement Value	: <u>S\$</u>	
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the Rear n/s portion.

nearside fro

Comments/ Present Status:

Damages Consistent.

Yours faithfully Adrian Automotive Assessor

Job Sheet (/C	laimWS/Surveyor/JobSheet/2	249127) 🚣 PR	Documents 🚇 Close 🗶		
		American Sparrers, process	PRI Header Details	8	3
Claim No	D19001538MFSH	Policy No	D-19092580MFSH	Claimant S.No & Name	1 & PREMIUN
Workshop Name	PREMIUM AUTOMOBILES PTE LTD (Contact Person : MASTURA)	Survey Location & Contact Details	55 UBI ROAD 1 Mobile: 67689828 , Phon EmailId: MASTURA@PREM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE	ADMIT LIABIL	ITY QUANTUM
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA3757E	TP Vehicle No	SGA7700D
PRI Recieved Date	cieved 04-03-2019 03:46:48 PM Appointed 06-03-2019 05:30:59 PM		Surveyor Accept Date	07-06-2019	
			Survey Report Upload		
Surveyor Inspection Date *:	100	Surveyor Report Date	07-06-2019	Upload Survey Report *:	Choose File
			Vehicle Particulars		
Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			
Multiple D	ocuments Upload				
		Upload Multipl	e Documents		
File Nar	ne			Action	
Surveyor .	Job Remarks				
1				Save	

* X

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Thursday, 6 June 2019 3:26 PM

To:

Boo seng yak; Adrian Ling (LKKAuto); CS A Team; Admin A; Carrine Leong;

jiayee.yap@premiumauto.com.sg; Chang Chee Sing

Subject:

RE: FINAL REVISION - SGA7700D- TP FIRSTCAP - SURVEYED 6 MAR 19

Dear Mr Boo,

confirm repair cost of \$9964.20 @ 4 days of repairs.

Please submit your relevant documents to First Capital directly.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Monday, 6 May 2019 4:04 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang

Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SGA7700D- TP FIRSTCAP - SURVEYED 6 MAR 19

hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$9964.20 @ 4 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Friday, 8 March 2019 10:36 AM

To:

'CWS Motor Claims'

Cc:

'Joanne Yong Lai fong'; assignments

Subject:

RE: PRI REQUEST : FC REF: SHA4417E. (D19001516MFSH) & TP REF: SHA9556D.

(SGA7700D) ACCIDENT ON 28-02-2019

Attachments:

PRELI ADVISED SGS 7700D.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGA 7700D

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)

From: Admin-D (LKKAuto)

Sent: Friday, 8 March 2019 9:51 AM

To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Subject: FW: PRI REQUEST: FC REF: SHA4417E. (D19001516MFSH) & TP REF: SHA9556D. (SGA7700D) ACCIDENT ON

28-02-2019

Dear Sir/Madam,

Thank you for your assignment

Shiau Chan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 7 March 2019 12:19 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: Joanne Yong Lai fong < Joanneyong@msfirstcapital.com.sg >; CWS Motor Claims

<cwsmotorclaims@msfirstcapital.com.sg>

Subject: Re: PRI REQUEST: FC REF: SHA4417E. (D19001516MFSH) & TP REF: SHA9556D. (SGA7700D) ACCIDENT ON

28-02-2019

Nivitha (LKK Auto)

From:

Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>

Sent:

Wednesday, 6 March 2019 3:28 PM

To:

'assignments@lkkauto.com'

Cc:

May Chua Hui Chin

Subject:

NEW SURVEY ASSIGNMNENT - OUR REF: D19/1538 - IV VEH: SHA3757E

VEH: SGA7700D DOA 01/03/2019

Attachments:

SGA 7700 D - 01032019 GIA ADDENDUM.PDF; FW: ACCIDENT INVOLVING SGA

7700 D AND YOUR INSURED SHA3757E DATED ON 01/... (59.1 KB)

Importance:

High

Dear Sirs

Survey assignment for your handling urgent as per attached.

Thanks and Regards,

SK Teo

Motor Claims Dept

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID: 6507 3848 | Fax No.: 6507 3849 |

A Member of MISSEAD INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Jaime Tay

Sent: Friday, March 01, 2019 5:47 PM

To: Teo Swee Keong < Teo Swee Keong @msfirstcapital.com.sg>

Subject: FW: spam>ACCIDENT INVOLVING SGA 7700 D AND YOUR INSURED SHA3757E DATED ON 01/03/2019

Dear SK,

Survey - SHA3757E - CTPL (reported)

Thank you.

With regards,

Jaime Tay

Motor Claims Department

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | ►: 6507 3848 | ➡: 6507 3849 | Company Regn. No. 195000106C

A Member of MISSAN INSURANCE GROUP



Change of email address

jaimetay@msfirstcapital.com.sg

Personal Data Protection Act 2012 ("PDPA").

Under the POPA, there are various requirements that regulate the processing of your personal data. Pleasers of to www.first-insurance.com.sa for details of PDPA Personal Data Collection Statement.

Confidentially Natice! This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: ILPROCESSCENTRE //ICICILOMBARD/HYD <ilprocesscentre@icicilombard.com>

Sent: Friday, 1 March, 2019 5:33 PM

To: Motor Claims < Motor Claims@msfirstcapital.com.sg>

Subject: FW: spam>ACCIDENT INVOLVING SGA 7700 D AND YOUR INSURED SHA3757E DATED ON 01/03/2019

From: Mastura [mailto:mastura@premiumauto.com.sg]

Sent: Friday, March 01, 2019 2:57 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; 'Claims' <claims@premiumauto.com.sg> Subject: spam>ACCIDENT INVOLVING SGA 7700 D AND YOUR INSURED SHA3757E DATED ON 01/03/2019

Dear all,

Kindly assist in the liability clearance for the above mentioned case. We propose for 100% direct settlement in our clients favour.

We herein attached the GIA report for direct settlement for your reference.

We will forward you the estimate once is available.

Do take note, kindly arrange the survey on 06/03/2019, Wednesday, 2 PM.

Best Regards.

Mastura

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. mastura a premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p.

Email Disclaimer

any attachment, is confidential and may also be privileged.

have the word it in error, please notify as immediately by reply citial and then delete this message from your system.

and the same it for any purpose, or disclose its contents or any attachment to any other person. Thank you

"Please note that this email, including any attachments, is intended solely for the individual (s) or entity (ies) to whom they are addressed and may contain information that is private, confidential and privileged. In case you are not the intended recipient, request you to notify the sender by reply mail and delete this email, including any copies or attachments from your system. Any unauthorized dissemination, disclosure and/or use of the contents of this communication to anyone is strictly prohibited and punishable by law.

Opinions, conclusions and statements of intent expressed in this e-mail are of the sender and ICICI Lombard General Insurance Company Limited (Company) does not accept liability for the views expressed in this email unless confirmed by an authorized representative of the Company independently of this communication or for the consequences of any viruses that may be transmitted with this email."



REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$9416340D



LECK KAI SEN

楷 陆

CHINESE Date of birth 21-04-1994

SINGAPORE

394.16340D

REPUBLIC OF SHIGHPURE DRIVING LICENCE Lectron Number \$9416340D LECK KAISEN Birth Date: 21 Apr 1994 Issue Date: 06 Nov 2017

4839166



MRIC No. S9416340D

27-02-2012

100 LORONG M TELOK KURAU #01-07 SINGAPORE 425403

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Motor cars without clutch pedals (Auto) with unladen 06 Nov 2017 weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight =< 2500kg

NP 428A

Licence No:S9416340D





AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore) (65) 6880 4888 (International)

(65) 6880 4740

☑ customer.care@axa.com.sg

www.axa.com.sg

account number

00953

-Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960-Road Transport Act. 1987 (Malaysia) -Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name

LECK TIN HENG

Certificate of Insurance

Certificate number

GA439373 / 1

Cover

Comprehensive

Chassis number Engine number

WAUZZZ4H0EN012352 CRE002487

Plan name

Flexi 50%

NCD applicable Vehicle registration number

SGA7700D

Period of Insurance

from 26/01/2019 to 25/01/2020 (both dates inclusive)

Finance loan company

Persons or classes of persons entitled to drive*

(a) The Policyholder

(b) Any Named Driver as stated in the Policy:

1. LECK KALJIN

2. LECK KALSEN

(c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Basic Own Damage Excess

Windscreen Excess

SGD 600.00

SGD 100.00

An Additional Excess is applicable as follows:

- 1. S\$500 for unnamed Authorised Driver
- 2, S\$500 for declared Young and Inexperienced Driver
- 3. S\$5,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium

Additional clauses & endorsements to your policy

Additional Clause 1

IT IS HEREBY NOTED THAT THE FOLLOWING NAMED DRIVER IS ADDED INTO THE POLICY:

DRIVER TYPE: ADDITIONAL DRIVER DRIVER NAME: VINCENT NG HWEI YERN MALAYSIA NRIC: 760719145967 DATE OF BIRTH: 19/07/1976 DRIVING EXPERIENCE: 10 YEAR(S) GENDER/MARITAL STATUS: MALE/SINGLE

RELATIONSHIP: SON

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/TP/0278/2019/GW

Date : 2-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No: SHA 3757 E

First Capital Insurance Ltd

36 Robinson Road # 16-01 City House Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Mr. Leck Tin Heng

Address : 100 Telok Kurau Lor M

#01-07

Singapore 425403 HP +6591912037

Telephone : HP +6591912037
Type of Claim : Third party Claims
Policy No. : GA439373/1
Vehicle No : SGA 7700 D

Model Code : Audi A8 L D4 3.0 TFSI QU

 Model / Year
 : Mar-15

 Engine No
 : CRE 002487

Chassis No : WAUZZZ4H0EN012352

Mileage : Date In : Liability : - Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 1-Mar-19

Place of Accident : Still Rd Junction Towards PIE Near Mosque

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following: To resurvey defore latter spray cainting • To it splay damaged part(s) during resurvey

· Partir chicos are subject to confirmation

• No dega modification(s) is allowed

Acknowledged by Repairer

Signature:

Date:

Third party survey is on a "Without Prejudice" basis

· Supplementary demiss) must be resurveyed and is subject to final approval from insurance Company

we Anthorsed, 03 Duys

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGA 7700 D

S/n	Nature of Jobs		Estimated Charges
1	To remove and transfer rear parking and rear lid kick sensor assy. Check function.	S/N	\$ 360.00
2	To dismantle and renew front bumper assy.Inspect lhs rear fender for damages. Re-organise rear crash management components. Reinstall all parts removed.		\$ 1,200.00 800
3	To respray rear bumper and lower spoiler.		\$ 1,500,00 1200
4	To carry out diagnostic check.	S/N	\$192.00
	TOTAL LABOUR CHARGES	:	\$ 3,252.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGA 7700 D

		Damaged Parts & Prices		
S/N	Parts Description		S/Nett Remark	
	a a			
1	REAR BUMPER De la d	\$	3,342.00	
2	REAR BUMPER SPOILER Read	\$	614.00 613 50	
3	REAR BUMPER TRIM STRIPS-LH/RH	\$	284.00 - 142 · [4]	
4	REAR BUMPER TRIM STRIPS-CENTER Conce	\$	√828.00 / B2A.5	
5	REAR BUMPER CLOSING ELEMENT-LH	\$	V171.00 8 170.5	0
6	EXHAUST TAIL PIPE TRIM	\$	517.00 \$ 516 50	
7	REAR BUMPER SECURING STRIP	\$	143.00 - 143	
8	REAR BUMPER FIXING PARTS Nec	\$	131.00 ≺	
9	REAR SENSOR NOT 2	\$	462.00 ? ×	
10	REAR SENSOR SEAL RING NOTNEC	\$	5.00 7	
11	REAR BUMPER GUIDE SECTION-LH	\$	21.00 20.90	
12	REAR BUMPER GUIDE SECTION-LH OUTER	\$	30.00 🖈	
13	REAR BUMPER CARRIER THE ME	\$	1,370.00	
14	REAR BUMPER BRACKET-OUTER 3 Not New	\$	44.00 ·x	
15	REAR VENT TRIM	\$	85.00×	
16	SUNDRIES NEU	\$	500.00 ? 36.80	
	TOTAL SPARE PARTS	\$	8,547.00	
	TOTAL LABOUR CHARGES :	\$	3,252.00	
	GRAND TOTAL :	\$	11,799.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

First Capital Insurance Ltd 36 Robinson Road # 16-01 City House Singapore 068877 Attn: Motor Claims Dept

Tel: 6854 3909 Fax: 6507 3849

Estimate No.

Date Service Advisor

Pages Regn No

Model No

PA/TP/0278/2019/GW

28-Mar-19 CHANG

1 of 1 SGA 7700 D

AUDI ABL D4 3.0 TFSI QU

Quantity	Description	Unit Price	Amount
	To repair LHS tail panel panel. 400 To respray LHS tail lamp panel and LHS rear fender.	s 600.00 s 1,800.00	400 -
	GRAND TOTAL :	\$ 2,400.00	

For Premium Automobiles Pte Ltd

Adain ()

Authorised Signature

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

Accident Repairs

Workshop

Ubi Road 1

Contact No

6366 2323 6841 1183

Fax No Reference

PA/TP/0278/2019/GW

Date

2-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No: SHA 3757 E

First Capital Insurance Ltd

36 Robinson Road # 16-01 City House Singapore 068877

We take 4 days with added repairs ib 6 May 19

Attn: Motor Claims Dept Tel:6854 3909 Fax: 6507 3849

Owner's Name

Mr. Leck Tin Heng

Address

100 Telok Kurau Lor M

Singapore 425403

Telephone

HP +6591912037

Type of Claim

Third party Claims

Policy No.

GA439373/1

Vehicle No

SGA 7700 D

Model Code

Audi A8 L D4 3.0 TFSI QU

Model / Year

Mar-15

CRE 002487

Engine No

Chassis No

WAUZZZ4H0EN012352

Mileage

Date In

Liability

Excess Cost

Estimated By

Johnny Boo / Allan Wu

Accident Date

Place of Accident

Still Rd Junction Towards PIE Near Mosque

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGA 7700 D

S/n	Nature of Jobs		Estimated Charges	
1	To remove and transfer rear parking and rear lid kick sensor assy. Check function.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper assy.Inspect Ihs rear fender for damages. Re-organise rear crash management components. Reinstall all parts removed.		\$ 1,200.00	\$ 800.00
3	To respray rear bumper and lower spoiler.		\$ 1,500.00	\$ 1,200.00
3A	Added labour charges - see attached		\$2,400.00	\$ 1,600.00
4	To carry out diagnostic check.	S/N	\$192.00	\$ 192.00
	TOTAL LABOUR CHARGES	i:	\$ 5,652.00	\$ 4,152.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGA 7700 D

				Damaged Part	Parts & Prices		
S/N	Parts Description			S/Nett	Remark		
1	REAR BUMPER		\$	3,342.00	\$	3,342.00	
2	REAR BUMPER SPOILER		S	614.00	\$	613.50	
3	REAR BUMPER TRIM STRIPS-LH/RH	2	\$	284.00	\$	141.50	
4	REAR BUMPER TRIM STRIPS-CENTER		\$	828.00	\$	827.50	
5	REAR BUMPER CLOSING ELEMENT-LH		\$	171.00	\$	170.50	
6	EXHAUST TAIL PIPE TRIM		\$	517.00	\$	516.50	
7	REAR BUMPER SECURING STRIP		\$	143.00	\$	143.00	
8	REAR BUMPER FIXING PARTS		\$	131.00			
9	REAR SENSOR	2	\$	462.00			
10	REAR SENSOR SEAL RING		\$	5.00			
11	REAR BUMPER GUIDE SECTION-LH		\$	21.00	\$	20.90	
12	REAR BUMPER GUIDE SECTION-LH OUTER		\$	30.00			
13	REAR BUMPER CARRIER		\$	1,370.00			
14	REAR BUMPER BRACKET-OUTER		\$	44.00			
15	REAR VENT TRIM		\$	85.00			
16	SUNDRIES		\$	500.00	\$	36.80	
	TOTAL SPARE PARTS	:	\$	8,547.00	\$	5,812.20	
	TOTAL LABOUR CHARGES		\$	5,652.00	\$	4,152.00	
	GRAND TOTAL	*	\$	14,199.00	\$	9,964.20	
			_		-		

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

PA/TP/0278/2019/GW Estimate No. First Capital Insurance Ltd 28-Mar-19 Date 36 Robinson Road CHANG Service Advisor # 16-01 City House 1 of 1 Pages Singapore 068877 SGA 7700 D Regn No Attn: Motor Claims Dept AUDI A8L D4 3.0 TFSI QU Model No Tel: 6854 3909 Fax: 6507 3849

Quantity	Description	ı	Init Price		Amount
Labours 1 2	To repair LHS tail panel panel. To respray LHS tail lamp panel and LHS rear fender.	\$	600.00 1,800.00	s	400.00
	GRAND TOTAL :	\$	2,400.00	\$	1,600.00

For Premium Automobiles Pte Ltd

Authorised Signature

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Tres		Affiliated to Federation Interna	tionale Des Experts En Automo	
AS FII	RST CAPITAL IN	SURANCE LTD	Ref : CS/FCI1900414	7/Atd3n2
16 RO	BINSON ROAD	NGAPORE 068877	Date: 11-06-2019 Code: FCI2	
		Policy Particula	rs :- THIRD PARTY CLAIR	M
_	Insured Veh.	SHA 3757E	Veh. Inspected	SGA 7700D
	Policy No.	D-19092580MFSH	Coverage (\$)	0.00
	Claim No.	D19001538MFSH	Excess (\$)	0.00
	Assign From	TEO SWEE KEONG	Assign Date	06/03/2019
2.		Vehicle Pa	articulars & Condition	
	Make & Model	AUDI A8	c.c	2995
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WAUZZZ4H0EN012352	Colour	BLACK
	Odometer	74497	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	255/45 R19	PIRELLI	6 mm
	L/H Front Tyre	255/45 R19	PIRELLI	6 mm
	R/H Rear Tyre	255/45 R19	PIRELLI	6 mm
	L/H Rear Tyre	255/45 R19	PIRELLI	6 mm
4.		10000000	iption of Damages	
	THE VEHICLE SU	ISTAINED DAMAGES AT THE	REAR N/S PORTION.	
	DAMAGES SEE D	DETAILS.		
5.		Ger	neral Information	WHEN EXPLANABLE
	Accident Date	01/03/2019	Inspection Date	06/03/2019
	Survey held at	PREMIUM AUTOMOBILES	PTE LTD	
		55 UBI ROAD 1 . SINGAPORE 408699		
5a.			Remarks	
	DITTLE INCOFCE	NSISTENT TO ACCIDENT RE ION WAS CONDUCTED ON A ICE TO YOUR INSTRUCTION	IS, WE HAVE NOT AUTHOR	ASIS. ISED REPAIRS.
5b.		10000000	nate Days of Repair	
	ESTIMATED NO	RMAL PERIOD FOR REPAIR:	4 Working Da	ays



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 7700D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1000	REPLACEMENT OF PARTS			
-1	REAR BUMPER (SN)	DEFORMED	3,342.00	3,342.00
	REAR BUMPER SPOILER (SN)	DEFORMED	614.00	613.50
	REAR BUMPER TRIM STRIPS-LH/RH (SN)	N/S CUT	284.00	141.50
	REAR BUMPER TRIM STRIPS-CENTER (SN)	CRACKED	828.00	827.50
	REAR BUMPER CLOSING ELEMENT-LH (SN)	DAMAGED	171.00	170.50
	EXHAUST TAIL PIPE TRIM (SN)	CUT	517.00	516.50
	REAR BUMPER SECURING STRIP (SN)	NECESSARY	143.00	143.00
	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	131.00	-
	REAR SENSOR (SN)	NOT NECESSARY	462.00	-
100	REAR SENSOR SEAL RING (SN)	NOT NECESSARY	5.00)
1	REAR BUMPER GUIDE SECTION-LH (SN)	NECESSARY	21.00	20.90
1	REAR BUMPER GUIDE SECTION-LH OUTER (SN)	NOT NECESSARY	30.00	
	REAR BUMPER CARRIER (SN)	NOT NECESSARY	1,370.00	
	REAR BUMPER BRACKET-OUTER (SN)	NOT NECESSARY	44.00	
	REAR VENT TRIM (SN)	NOT NECESSARY	85.00	
	SUNDRIES (SN)	NECESSARY	500.00	36.80
	SUNDRIES (SIV)		8,547.00	5,812.20
	LABOUR			
	TO REPAIR LHS TAIL PANEL PANEL (ADDITIONAL).		600.0	
	TO RESPRAY LHS TAIL LAMP PANEL AND LHS REAR FENDER.(ADDITIONAL).		1,800.0	
	TO REMOVE AND TRANSFER REAR PARKING AND REAR LID KICK SENSOR ASSY. CHECK FUNCTION.		360.0	0 360.0
	TO DISMANTLE AND RENEW FRONT BUMPER ASSY.INSPECT LHS REAR FENDER FOR DAMAGES.RE- ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.		1,200.0	0 800.0
	TO RESPRAY REAR BUMPER AND LOWER SPOILER.		1,500.0	
8	TO CARRY OUT DIAGNOSTIC CHECK.		192.0	
			5,652.0	4,152.0
	GRAND TOTAL		14,199.0	9,964.2

Report Ref No. CS/FCI19004147/Atd3n2



Page No.: 2 of 2

RECOMMENDED COST OF REPAIRS 9,964.20

Report Ref No. CS/FCI19004147/Atd3n2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.