



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM)

#04-04 Singapore 757047

Tel: 65 6493 1924

Fax: 65 6493 1928

VEHICLE REPAIR ESTIMATE

Insurance Company: FWD INSURANCE

Address: 6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

Telephone: 6820 8888

Fax:

Email: motorclaims.sg@fwd.com

Make/ Model : Fiat Bravo

Date: 04-03-19

Chassis No : ZFA19800004330490

Vehicle No: SKD 6650 H

Date/Time of Accident : 04-03-19 13:25

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	Rear bumper	1	\$ 945.00	10%	\$ 850.50
2	Rear bumper reinforcement	1	\$ 456.00	10%	\$ 410.40
3	Rear bumper lower cover	1	\$ 315.00	10%	\$ 283.50
4	Rear bumper side retainer	2	\$ 85.00	10%	\$ 76.50
5	Rear bumper centre bracket	1	\$ 145.00	10%	\$ 130.50
6	Rear number plate lamp	1	\$ 56.00	10%	\$ 50.40
7	Rear reverse lamp	1	\$ 224.00	10%	\$ 201.60
8	Rear reflector lamp	1	\$ 133.00	10%	\$ 119.70
9	Rear towing cover	1	\$ 28.00	10%	\$ 25.20
10	Rear left fender	1	\$ 1,550.00	10%	\$ 1,395.00
11	Rear left inner quarter panel	1	\$ 250.00	10%	\$ 225.00
12	Rear left fender air duct	1	\$ 185.00	10%	\$ 166.50
13	Rear end panel	1	\$ 672.00	10%	\$ 604.80
14	Rear end panel top garnish	1	\$ 180.00	10%	\$ 162.00
15	Rear end corner panel left	1	\$ 392.00	10%	\$ 352.80
16	Tailgate lock	1	\$ 137.20	10%	\$ 123.48
17	Tailgate hinge	1	\$ 84.00	10%	\$ 75.60
18	Tail lamp lower bracket LH	1	\$ 154.00	10%	\$ 138.60
19	Tail Lamp LH	1	\$ 252.00	10%	\$ 226.80
Total Spare Parts Cost					\$ 5,618.88

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
20	Rear bumper lower cover clips	10	\$ 60.00		\$ 60.00
21	Rear end panel top garnish clips	6	\$ 30.00		\$ 30.00
Total Special Items Cost					\$ 90.00

Labour Works/ Panel Beating Related Works		
Job Scope		Quotation
TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS		\$ 1,600.00
		1200.00
Spray Painting		
Job Scope		Quotation
TO RESPRAY AFFECTED AREAS		\$ 1,000.00
		600.00
Others Cost (Accident Repair Related Expenses)		
Job Scope		Quotation
TOWING		
TO REMOVE & REFIX REAR WINDSCREEN		
TO TUFFCOAT AFFECTED AREA		
TO REPLACE FRONT WINDSCREEN		120.00 \$ 250.00
TO REPLACE ENGINE MOUNTING/ GEAR BOX MOUNTING		
TO REMOVE/ REPLACE AIRCON CONDENSOR, VACUUM, TOP UP AIRCON GAS COMPUTERIZED		
TO REMOVE/ REFIT/ REPLACE DASHBOARD		
TO REMOVE/ REFIT INTERIOR UPHOLSTERY		
TO REMOVE/ REPLACE FRONT UNDERCARRIAGE		60.00 \$ 120.00
TO REMOVE/ REFIT WIRING CHECKS		
TO REMOVE/REFIT/ ADJUST BRAKE FOUR WHEELS		50.00 \$ 60.00
TO REMOVE/ REPLACE REAR SILENCER BOX		
TO REMOVE/ REPLACE REVERSE SENSORS		
TO RESET ALL AIRBAG NECESSARY SYSTEM		
TO REMOVE & REPLACE ALL NECESSARY AIR BAG		
TO REMOVE AND REPLACE ROOF-TOP LINNING		
TO REMOVE AND REPLACE TAIL GATE MECHANISM		
Total Others Cost		
GRAND TOTAL		\$ 430.00
		\$ 8,738.88

TGim 6/mar/19
1330 hr

CARZ AUTO SERVICES PTE LTD

Person Incharge: Wilson (Ah Yong)
Job Title: Workshop Supervisor
Direct Contact: +65 8363 3059
Email: jeslyn@carzauto.com.sg

? photo
Lump sum repair
Days of repair 6 days