

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : EQ INSURANCE COMPANY LTD

5 Maxwell Road #17-00

Tower Block MND Complex

singapore 069110

TEL: 6223 9433

FAX: 6224 3903

ATTN: Motor Claim Department

Your Ref No: 19/EQ/TP-042 (03)

Claim Type: Third Party

Accident Date: 28/02/2019

TP Veh Reg No: SMD3297R

Estimate No: EST0004678

Date: 05 Mar 2019

Policy No: CN035306

Veh Reg No: **SMG5987D**

Make/Model: BMW 523i

Chasis No: WBAFP32010C546466

Engine No: 04637570N52B25AF

Reg. Date: 16/11/2010

Estimate Repair Cost to Vehicle No :SMG5987D

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Parts			
1 REAR BUMPER	1 PC	1,375.00	✓
2 REAR BUMPER RETAINER RH	1 PC	165.00	X
3 REAR BUMPER CLIP	10 PC	22.00	✓
4 REAR SPORT RIM RH	1 PC	1,155.00	X
		2,717.00	2,717.00
Labour			
5 WHEEL ALIGNMENT	1 UNIT	60.00	✓
6 LABOUR CHARGE	1 UNIT	300.00	✓
7 SPRAY PAINTING	1 UNIT	400.00	320
		760.00	760.00
Total			S\$ 3,477.00
Add GST @ 7%			243.39
Total Amount Payable			S\$ 3,720.39

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SEVEN HUNDRED TWENTY AND CENTS THIRTY NINE ONLY

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorised
h/bk
h/s
2dy.
11/3/19
thru photo After Rep