

ASS. REC. BY:

REF: CS/CTI 19004157 | A sd307 Special Instruction:

SURVAYOR

ASSIGNMENT (Office)From (Person): Boon Sen (Merimen) of CTI Date/Time: 6/3/19

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 84655 Insured: GBA 4983Hat Workshop m/s Abwin Tel: 6713 9417of 8 Kaki Bukit Ave 4 #107-48

Policy No: \_\_\_\_\_ Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 27/2/19  
(Client's Record)CA / REV / REP. / REV 24 HRS wp 7/3/19 H.O.D. Endorsement: \_\_\_\_\_Date/Time: 6/3/19 @ 5:15pm Person Contacted: Linda Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
<u>09/04/19</u>	<u>@ 17:08 p.m. Confirmed with Linda, Vehicle Tow to other repairer workshop repair. Vehicle has not repaired</u>

REF:

CTI

ASSIGNMENT

From: Date: 7/3/2019

Veh No: SLT8465S Yr/Regn: 2010 / Augst - 1

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: SLT 8465S

Make: Nissan Teana C.C. 2496

at Workshop m/s: ABWIN  
of: 8 Kaki Bukit Ave 4

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 161016 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

C/No: JN1BBUJ3220002403

Policy No:

Gen. Cond: Good / Fair / Poor / Burnt

Claims No:

Steering: In order / Jammed / Leaked / Burnt or

Sum Insured:

Excess:

Brake: In order / Jammed / Leaked / Burnt or

(Client's Record)

Modi: Nil / R/Rim / STD A/Rim or

Make of Veh:

Tyre Size: F: 225/50R17

(Policy Condition)

R: 225/50R17

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent?: Yes or No

R/Bal. 06 mm

R/Bal. 06 mm

GIA / PR Seen: Consistent?: Yes or No

L/Bal. 06 mm

L/Bal. 06 mm

Est. Repairs: days Res.: Yes or No

D.O.A. D.O.I. 07/03/19

Lum Sum: % 3 Val: Yes or No

Survey held at: Abwin.

CA / REV / REP. / 24 HRS

LWP

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s.

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/4/19 TP China.  
duke with Adrian, repair days = 10 days.

MV: 27K  
PV: 22.8K  
Nett: 4.2K

RECEIVED 15 APR 2019

Date/Time, File Pass to?

: Preli. Report  
: Final Report

Days Of Repair: 10

Resurvey No. of Trip: /

Survey Fee:

1) 15/04/19  
Typist

2)

Add Fee:  Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Transportation

Other

Report Format: Preli

Lump Sum / I.B.A. (\$)

220
220

## Catherine Chong (LKK Auto)

---

**From:** Catherine Chong (LKK Auto) <admin-d@lkkauto.com>  
**Sent:** Wednesday, 6 March, 2019 5:14 PM  
**To:** 'Chong Boon Sen'  
**Cc:** 'sur@lkkauto.com'  
**Subject:** RE: SLT84655 Against GBA4983H Date of accident : 27/02/2019

Dear Boon Sen,

Thank you for your assignment.

Best Regards,

Veron Chen | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen [mailto:[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)]  
**Sent:** Wednesday, 6 March, 2019 4:53 PM  
**To:** Linda Liao <[lindaliao@abwin.com.sg](mailto:lindaliao@abwin.com.sg)>  
**Cc:** Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Subject:** RE: SLT84655 Against GBA4983H Date of accident : 27/02/2019

Without Prejudice

Dear Sir,

We pri.

Dear LKK,

Pls pri.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Linda Liao [mailto:lindaliao@abwin.com.sg]  
**Sent:** Wednesday, 6 March, 2019 4:38 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** RE: SLT8465S Against GBA4983H Date of accident : 27/02/2019

Dear Mr chong


We conduct MARCUS CHUA survey before repair.

Thank you

**Best regards,**

**Linda Liao**  
Claims Executive  
DID +65 6713 9417  
HP: +65 9751 9596

**Abwin Service Pte Ltd**



No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875  
T +65 6713 9400 | F +65 6713 9415

**From:** Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]  
**Sent:** Wednesday, 6 March, 2019 4:26 PM  
**To:** Linda Liao <lindaliao@abwin.com.sg>  
**Subject:** RE: SLT8465S Against GBA4983H Date of accident : 27/02/2019


**WITHOUT PREJUDICE**

Dear Mr Sim,

We refer to your email of 06.03.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO



No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875  
T +65 6713 9400 | F +65 6713 9415

**From:** Linda Liao  
**Sent:** Tuesday, 5 March, 2019 11:41 AM  
**To:** 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>  
**Subject:** Re: SLT8465S Against GBA4983H Date of accident : 27/02/2019

Dear Motor Claim Dept

Please arrange survey before repair as soon as possible,


Please advise the liability as soon as possible.

Thank you

Best regards,

Linda Liao  
Claims Executive  
DID +65 6713 9417  
HP: +65 9751 9596

Abwin Service Pte Ltd



No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875  
T +65 6713 9400 | F +65 6713 9415

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	27/02/2019 17:12
Date Of Accident	27/02/2019 14:40
Exact Location Of Accident	KAKI BUKIT AVE 4
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT8465S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ROADPULSE
Co Reg No	53347175C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-84880363

#### Vehicle Particulars

Manufacturer	NISSAN
Model	TEANA-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

#### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106096507
Cover Note Number	

#### Driver

Name of Driver	OOI CHEE SIONG
NRIC No	F4514576W
Date Of Birth	31/07/1980
Occupation	INDOOR
Date Of Driving Pass	23/11/2009
Driving Experience	9 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84880363
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address	BLK 329 #17-98 TAH CHING ROAD
Postcode	610329
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer to attachment.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA4983H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
  
 \_\_\_\_\_  
 Policyholder's Signature  
 Date & Time:

  
 \_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 \_\_\_\_\_  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

SKETCH PLAN



A: SLT84655

B: GBA4983H


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/02/2019 at around 1440hrs, I was driving SLT84655 going to Vicom to pay roadtax. At the intersection, there was a jam due to the traffic lights. As I was turning in slowly (due to the fact that one heavy vehicle was blocking my view) I am watching for incoming traffic. When I saw that it is clear, I move forward and stop to double check that the outer lane was clear of traffic. As I move slowly out to get a view, the other party GBA4983H was speeding down the lane. I was already stationary when I was hit by vehicle B, resulting my car to end up in a parallel position aligned to the ~~road~~ lane

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*Signature*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Accident Photo



Accident Photo



LINDA LIAO  
 ABWIN SERVICE PTE LTD  
 DID: 67139417  
 Fax: 67139415  
 HP: 97519596

Date : 05/03/2019  
 TP Vehicle No. : GBA-4983-H  
 To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 Attn : Motor Claim Department

Owner : ROADPULSE  
 NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Certificate No. : 5106096507  
 Vehicle No. : SLT-8465-S  
 Make & Model : NISSAN TEANA 2.5 CVT ABS D/AB HID 2WD 4DR

Accident Date: 27/02/2019

JN18BUJ32Z0002403

## ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

### List Item

1	BONNET Distorted	\$1,150.00	✓
1	BONNET LOCK	\$165.80	✓
1	BONNET LOCK CATCH New	\$150.00	x
1	BONNET GRILLE Cracked	\$350.00	✓
1	BONNET CHROME MOULDING New	\$450.00	+
1	BONNET LOGO	\$95.00	✓
1	FRONT NUMBER PLATE HOLDER New	\$120.00	x
1	FRONT BUMPER Distorted	\$780.00	✓
1	FRONT BUMPER RETAINER RH	\$165.00	—
1	FRONT BUMPER RETAINER LH	\$165.00	✓
10	FRONT BUMPER CLIPS	\$50.00	30
1	FRONT BUMPER FOG LAMP GARNISH LH Distorted	\$95.00	—
1	FRONT BUMPER FOG LAMP GARNISH RH New	\$95.00	x
2	FRONT BUMPER TOWING COVER Missing	\$220.00	53
1	FRONT BUMPER CHROME MOULDING RH New	\$185.00	+
1	FRONT BUMPER CHROME MOULDING LH Cracked	\$185.00	—
1	RH HEADLAMP Cracked	\$2,850.60	288
1	LH HEADLAMP Smashed	\$2,850.60	288
1	RH HEADLAMP PANEL Repair	\$480.60	x
1	LH HEADLAMP PANEL Distorted	\$480.60	✓
1	RH FRONT DOOR Repair	\$2,100.00	+
1	LH FRONT DOOR New	\$2,100.00	x
1	RH FRONT FENDER Buckled	\$1,956.00	755
1	RH FRONT FENDER INNER PANEL Repair	\$350.60	x
1	RH FRONT FENDER OUTER PANEL Repair	\$350.60	x
1	RH FRONT FENDER INNER SHIELD New	\$195.60	x
10	RH FRONT FENDER INNER SHIELD CLIPS New	\$50.00	x
1	LH FRONT FENDER Distorted	\$1,956.00	755
1	LH FRONT FENDER INNER PANEL Distorted	\$350.60	✓

LINDA LIAO  
 ABWIN SERVICE PTE LTD  
 DID: 67139417  
 Fax: 67139415  
 HP: 97519596

Date : 05/03/2019  
 TP Vehicle No. : GBA-4983-H  
 To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 Attn : Motor Claim Department

Owner : ROADPULSE  
 NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No. : 5106096507  
 Vehicle No. : SLT-8465-S  
 Make & Model : NISSAN TEANA 2.5 CVT ABS D/AB HID 2WD 4DR

Accident Date: 27/02/2019

## ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
1	LH FRONT FENDER INNER SHIELD <i>Rehd</i>	\$195.60	✓
10	LH FRONT FENDER INNER SHIELD CLIPS <i>m</i>	\$50.00	✓
1	LH FRONT FENDER OUTER PANEL <i>Rehd</i>	\$215.00	✓
2	HORN <i>seen</i>	\$571.20	X
1	FRONT SUPPORT PANEL <i>Distorted</i>	<del>\$2,158.60</del>	✓ 753.
1	FRONT SUPPORT PANEL TOP GARNISH <i>seen</i>	\$450.60	+
10	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>m</i>	\$50.00	X
1	RADIATOR <i>But</i>	\$850.60	✓
1	RADIATOR FAN COWLING <i>Rehd</i>	\$250.60	✓ 125
1	RADIATOR FAN BLADE <i>Rehd</i>	\$250.60	✓ 55
1	RADIATOR FAN MOTOR <i>Rehd</i>	\$350.60	✓
1	AIR CON CONDENSER <i>But</i>	\$1,250.60	✓
1	AIR CON CONDENSER COWLING <i>Rehd</i>	\$250.60	✓ 125
1	AIR CON FAN MOTOR <i>Rehd</i>	\$250.60	✓
1	AIR CON FAN BLADE <i>Rehd</i>	\$250.60	✓ 55
	<b>Sub Total</b>	<i>14227</i> \$27,888.40	
	<b>Discount 10% on Parts</b>	<i>12804.30</i> (\$2,788.84)	
		\$25,099.56	

### Special Nett

1	FRONT NUMBER PLATE & CASING <i>Rehd</i>	<i>65</i> \$65.00	✓
	<b>Sub Total</b>	\$65.00	

### Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$2,500.00	✓ 1500
TO SPRAY PAINT ON AFFECTED AREAS	\$2,500.00	✓ 1000
TO CHECK LIGHTING AND FOCUS HEADLAMP	\$250.00	✓ 30
TO VACCUM AND TOP AIR CON GAS	\$250.00	✓ 60
TO CHECK AND CONDUCT UNDERCARRIAGE SYSTEM	\$350.00	X
TO APPLY TUFF KOTE ON AFFECTED AREA.	\$180.00	X
TO CONDUCT CHASSIS ALIGNMENT	\$350.00	X

Date : 05/03/2019  
 TP Vehicle No. : GBA-4983-H  
 To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 Attn : Motor Claim Department

LINDA LIAO  
 ABWIN SERVICE PTE LTD  
 DID: 67139417  
 Fax: 67139415  
 HP: 97519596

Owner : ROADPULSE  
 NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Certificate No. : 5106096507  
 Vehicle No. : SLT-8465-S  
 Make & Model : NISSAN TEANA 2.5 CVT ABS D/AB HID 2WD 4DR

Accident Date: 27/02/2019

### ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	\$350.00	X
	TO CHECK, RESET & DIAGNOS ENGINE MANAGEMENT WARNING LIGHT	\$350.00	X
	TO CONDUCT RADIATOR PRESSURE TEST	<del>\$250.00</del>	60
	TO TRANSFER AND REFIX FRONT WINDSCREEN FIXTURE	\$150.00	X 2650
	<b>Sub Total</b>	<b>\$7,480.00</b>	

**Sub Total** \$32,644.56  
**GST 7%** \$2,285.12  
**Total** \$34,929.68

total: 15519.3  
 4/5: 12.41K.  
 (Nett Value: )

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Apr 2019		10 Apr 2019 10:25 <a href="#">Edit Adj Rpt</a>	<b>S\$12,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$12,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>ROADPULSE</b> , Co. Reg. No.: 53347175C								
Vehicle Reg. No.:	<b>SLT8465S</b>	Date of Loss:	27/02/2019 14:00 - :59 [102 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D201009C02</b>	Policy/Cover Note No.:	DMCVSN30334018044						
Vehicle Reg. No. (Insured):	<b>GBA4983H</b>	Policy No. (Claimant):	5106096507						
		Excess:	S\$0.00						
Repairer:	<b>Abwin Service Pte Ltd (HQ)</b> No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2, 415875 Kaki Bukit - Tel: 6713 9400								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 22/04/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SLT8465S (SNM19D201009C02)  
 [GBA4983H]  
 TP  
 ROADPULSE  
 Feb 27 2019 2:00PM  
 [-]  
 Abwin Service Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <input type="button" value="View in Browser"/>		
<b>Assessment Reports</b>									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Abwin Service Pte Ltd (HQ)			Thumbnail	Print					
1	01/03/19 09:43	<b>Accident Statement</b>				Load HTM					
<b>Photos/Images</b>									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Abwin Service Pte Ltd (HQ)			Thumbnail	Print					
1	27/02/19 17:29	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>			
2	27/02/19 17:29	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>			
3	27/02/19 17:29	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>			
4	27/02/19 17:29	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>			
5	27/02/19 17:29	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>			
6	27/02/19 17:29	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>			
7	27/02/19 17:29	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>			
8	27/02/19 17:29	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print					
1	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
2	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
3	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
4	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
5	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
6	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
7	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
8	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
9	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
10	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
11	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
12	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
13	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
14	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
15	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
16	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
17	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
18	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
19	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
20	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
21	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			
22	12/04/19 15:33	<b>General View</b>				Load JPG		<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Abwin Service Pte Ltd (HQ)	Thumbnail	Print
23	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
24	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
25	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
26	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
27	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
28	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
29	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
30	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
31	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
32	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
33	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
34	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
35	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
36	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
37	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
38	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
39	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
40	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
41	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
42	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
43	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
44	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
45	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
46	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
47	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
48	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
49	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
50	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
51	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
52	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
53	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
54	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
55	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
56	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
57	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
58	12/04/19 15:33	General View		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/04/19 10:26	PRI CONTACT		<input type="checkbox"/>
No	Finalized On	Abwin Service Pte Ltd (HQ)	Thumbnail	Print
1	01/03/19 09:42	Sketch Plan [Linked Accident Report Documents]		<input type="checkbox"/>

### Linked Accident Report Documents

View 

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Abwin Service Pte Ltd (HQ)	Thumbnail	Print
1	01/03/19 09:43	Accident Statement		<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Abwin Service Pte Ltd (HQ)		Thumbnail	Print
No	Finalized On	Abwin Service Pte Ltd (HQ)		Thumbnail	Print
1	27/02/19 17:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	27/02/19 17:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	27/02/19 17:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	27/02/19 17:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	27/02/19 17:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	27/02/19 17:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	27/02/19 17:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	27/02/19 17:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Abwin Service Pte Ltd (HQ)		Thumbnail	Print
1	01/03/19 09:42	Sketch Plan		Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI19004157/ASD3E2  
**Date:** 09/05/2019

#### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30334018044
Claimant Vehicle No :	SLT8465S	Insured Vehicle No :	GBA4983H
Date of Loss:	27/02/2019	Nature of Claim:	TP
		Claim No:	SNM19D201009C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT8465S	Engine No:	HIDDEN
Make & Model:	NISSAN TEANA, 2.5 (A)	Chassis No:	JN1BBUJ32Z0002403
Reg. Date:	01/08/2010 (Man. Year: 2010)	Odometer:	161016 km
Colour:	White		
Engine Capacity:	2496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,164.56	12,869.30	12,295.26	48.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,480.00	2,650.00	4,830.00	64.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>32,644.56</b>	<b>15,519.30</b>	<b>17,125.26</b>	<b>52.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>12,400.00</b>		
(S\$)	32,644.56	12,400.00	20,244.56	62.02
+ GST 7.00/7.00% (S\$)	2,285.12	868.00	1,417.12	62.02
<b>Nett Amount (S\$)</b>	<b>34,929.68</b>	<b>13,268.00</b>	<b>21,661.68</b>	<b>62.02</b>

#### INSPECTION

Date of Assignment:	10/04/2019	
Date Inspected:	07/03/2019 Inspected At:	Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875

Estimated Period of Repair: 10.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2019)
<b>Parts:</b> 143	NISSAN TEANA 2.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLT8465S)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Distorted	1,150.00 FL	*1,150.00 FL
2	1		*BONNET LOCK	Damaged	165.80 FL	*165.80 FL
3	1		*BONNET LOCK CATCH	Not Necessary	150.00 FL	*- FL
4	1		*BONNET GRILLE	Cracked	350.00 FL	*350.00 FL
5	1		*BONNET CHROME MOULDING	Not Necessary	450.00 FL	*- FL
6	1		*BONNET LOGO	Necessary	95.00 FL	*95.00 FL
7	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	120.00 FL	*- FL
8	1		*FRONT BUMPER	Distorted	780.00 FL	*780.00 FL
9	1		*FRONT BUMPER RETAINER RH	Necessary	165.00 FL	*165.00 FL
10	1		*FRONT BUMPER RETAINER LH	Necessary	165.00 FL	*165.00 FL
11	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
12	1		*FRONT BUMPER FOG LAMP GARNISH LH	Distorted	95.00 FL	*95.00 FL
13	1		*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	95.00 FL	*- FL
14	2		*FRONT BUMPER TOWING COVER	Missing	220.00 FL	*53.00 FL
15	1		*FRONT BUMPER CHROME MOULDING RH	Not Necessary	185.00 FL	*- FL
16	1		*FRONT BUMPER CHROME MOULDING LH	Cracked	185.00 FL	*185.00 FL
17	1		*RH HEADLAMP	Cracked	2,850.60 FL	*2,188.00 FL
18	1		*LH HEADLAMP	Smashed	2,850.60 FL	*2,188.00 FL
19	1		*RH HEADLAMP PANEL	Repair	480.60 FL	*- FL
20	1		*LH HEADLAMP PANEL	Distorted	480.60 FL	*480.60 FL
21	1		*RH FRONT DOOR	Repair	2,100.00 FL	*- FL
22	1		*LH FRONT DOOR	Not Necessary	2,100.00 FL	*- FL
23	1		*RH FRONT FENDER	Buckled	1,956.00 FL	*755.00 FL
24	1		*RH FRONT FENDER INNER PANEL	Repair	350.60 FL	*- FL
25	1		*RH FRONT FENDER OUTER PANEL	Repair	350.60 FL	*- FL
26	1		*RH FRONT FENDER INNER SHIELD	Not Necessary	195.60 FL	*- FL
27	10		*RH FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FL	*- FL
28	1		*LH FRONT FENDER	Distorted	1,956.00 FL	*755.00 FL
29	1		*LH FRONT FENDER INNER PANEL	Distorted	350.60 FL	*350.60 FL
30	1		*LH FRONT FENDER INNER SHIELD	Deformed	195.60 FL	*195.60 FL
31	10		*LH FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FL	*50.00 FL
32	1		*LH FRONT FENDER OUTER PANEL	Distorted	215.00 FL	*215.00 FL
33	2		*HORN	Not Necessary	571.20 FL	*- FL
34	1		*FRONT SUPPORT PANEL	Bent	2,158.60 FL	*753.00 FL
35	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	450.60 FL	*- FL
36	10		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FL	*- FL
37	1		*RADIATOR	Bent	850.60 FL	*850.60 FL
38	1		*RADIATOR FAN COWLING	Damaged	250.60 FL	*125.00 FL
39	1		*RADIATOR FAN BLADE	Damaged	250.60 FL	*55.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*RADIATOR FAN MOTOR	Damaged	350.60 FL	*350.60 FL
41	1		*AIR CON CONDENSER	Bent	1,250.60 FL	*1,250.60 FL
42	1		*AIR CON CONDENSER COWLING	Damaged	250.60 FL	*125.00 FL
43	1		*AIR CON FAN MOTOR	Damaged	250.60 FL	*250.60 FL
44	1		*AIR CON FAN BLADE	Damaged	250.60 FL	*55.00 FL
45	1		*FRONT NUMBER PLATE & CASING	Damaged	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>27,953.40</b>	<b>14,292.00</b>
- List Item Discount on L Items 10.00/10.00% (S\$)	2,788.84	1,422.70
<b>Total Parts (S\$)</b>	<b>25,164.56</b>	<b>12,869.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	2,500.00	1,500.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	2,500.00	1,000.00
3	TO CHECK LIGHTING AND FOCUS HEADLAMP	New	250.00	30.00
4	TO VACUUM AND TOP AIR CON GAS	New	250.00	60.00
5	TO CHECK AND CONDUCT UNDERCARRIAGE SYSTEM	New	350.00	0.00
6	TO APPLY TUFF KOTE ON AFFECTED AREA	New	180.00	0.00
7	TO CONDUCT CHASSIS ALIGNMENT	New	350.00	0.00
8	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	350.00	0.00
9	TO CHECK, RESET & DIAGNOS ENGINE MANAGEMENT WARNING LIGHT	New	350.00	0.00
10	TO CONDUCT RADIATOR PRESSURE TEST	New	250.00	60.00
11	TO TRANSFER AND REFIX FRONT WINDSCREEN FIXTURE	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>7,480.00</b>	<b>2,650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >