



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Lynette Tan Su Ling (Lynette Chen Suling) 526 Miltonia Close #05-17 Singapore 768107  Contact No	Cust No/Name	KCV06334/Ms Lynette Tan Su Ling (Lynette)
	Reg No/Reg Date	SKH3335S / 04/10/201
	Date In/Mileage	/ 0
	Chassis No	JMYXTGF3WJZ000325
	Engine No	4B12TP2671
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E04)
	Colour/Trim	DO1 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KCV06334	CRDVCH	05/03/2019/ 17:00		265 / AndreChow	37003		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PORTION ON REAR BUMPER, REAR TAILGATE, REPAIR REAR END PANEL							1650 2750.00
E PNT88000 TRANSFER TAILGATE TRIM, MECHANISM AND ELECTRONICS TO FACILITATE REPAIR							160 550.00
E PNT88000 REMOVE AND INSTALL TAILGATE GLASS							240.00
E PNT88000 REMOVE AND INSTALL REVERSE SENSOR							60 150.00
E PNT98000 RESPRAY REAR BUMPER, REAR TAILGATE, REAR END PANEL							1260 1680.00
M SUNDRY SUPPLY C&C LOGO							40.00
M SUNDRY SUPPLY REAR WINDSCREEN SEALANT							80.00
M SUNDRY SUPPLY BODY SEALANT							40 80.00
M SUNDRY SUPPLY ANTI CORROSION							160.00
M SUNDRY SUPPLY REVERSE SENSORS							NA 220.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							60 100.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							200.00
M FACE,RR BUMPER DE				1.00	873.00	00.00	873.00
M REINFORCEMENT,RR BUMPER,LH ?				1.00	78.00	00.00	78.00
M REINFORCEMENT,RR BUMPER,RH ?				1.00	78.00	00.00	78.00
M BRKT,R/BMPR FACE SIDE,RH NA				1.00	12.00	00.00	12.00
M BRKT,R/BMPR FACE SIDE,LH NA				1.00	12.00	00.00	12.00
M EXTENSION,RR BUMPER DE				1.00	230.00	00.00	230.00
M PANEL ASSY,TAILGATE NA				1.00	924.00	00.00	924.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Lynette Tan Su Ling (Lynette Chen Suling) 526 Miltonia Close #05-17 Singapore 768107  Contact No	Cust No/Name	KCV06334/Ms Lynette Tan Su Ling (Lynette)
	Reg No/Reg Date	SKH3335S / 04/10/201
	Date In/Mileage	/ 0
	Chassis No	JMYXTGF3WJZ000325
	Engine No	4B12TP2671
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E04)
	Colour/Trim	D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KCV06334	CRDVCH	05/03/2019/ 17:00		265 / AndreChow	37003		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	GARNISH, TAILGATE	X		1.00	489.00	00.00	489.00
M	DAM, TAILGATE, UPR	nee /		1.00	12.00	00.00	12.00
P	DAM, TAILGATE SIDE	nee /		2.00	27.00	00.00	54.00
P	STOPPER, WINDSHIELD GLASS	nee /		2.00	3.00	00.00	6.00
M	DAM, TAILGATE, LWR	nee /		1.00	41.00	00.00	41.00
M	REFLECTOR, TAIL LAMP, LH	X		1.00	99.00	00.00	99.00
M	REFLECTOR, TAIL LAMP, RH	?		1.00	94.00	00.00	94.00
M	DECAL, 4WD	nee /		1.00	18.00	00.00	18.00
M	MARK, OUTLANDER	nee /		1.00	94.00	00.00	94.00

# Estimate

SURVEYOR NAME: Rome - Hp 90010068SURVEYOR SIGNATURE: [Signature]DATE: 12/03/19 @ 1130REMARKS: 7 days

Reserving before paint

Confirm &amp; accepted by

	Nett	9,364.00
7% GST on	9364.00	655.48
<b>Total Payable</b>		<b>10,019.48</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.