

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0286/2019/KN ✓
Date : 6-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Jespico Ang Chern Yih
Address : Blk 154 Lorong 2 Toa Payoh
#28-612
Singapore 310154
Telephone : 94558967
Type of Claim : Third Party Claims
Policy No. : 1900016653
Vehicle No : **SLH 8118 H** ✓
Model Code : Q5 SPORTS 2.0 TFSI
Model / Year : 25/2/2019
Engine No : DAX 051201
Chassis No : WAUZZZF1K2028747
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Mar-19
Place of Accident : 75E LOEVEN ROAD CARPARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLH 8118 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid	S/N \$ 480.00	✓
2	To dismantle and renew front bumper assy and LHS headlight. Re-organize front crash management components. Reinstall all parts removed.	\$ 1,400.00	700
3	To respray front bumper assy, front bumper spoiler and both front wheel arch covers.	\$ 2,200.00	1100 700 wheel Arch: 200x2 = 400
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,272.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLH 8118 H**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Red</i>	\$ 2,364.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 244.00	+
3	FRONT BUMPER SECURING STRIP <i>new</i>	\$ 34.00	+
4	BUMPER CLOSING ELEMENT - LH <i>new</i>	\$ 101.00	+
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	\$ 129.00	+
6	FRONT SPOILER <i>new</i>	\$ 685.00	+
7	UNDERRUN BAR <i>new</i>	\$ 431.00	+
8	CLOSING ELEMENT	\$ 156.00	+
9	RADIATOR GRILLE <i>Red</i>	\$ 3,258.00	✓
10	QUATTRO' INSCRIPTION <i>new</i>	\$ 87.00	✓
11	STRIKER PLATE <i>new</i>	\$ 222.00	+
12	AIR GUIDE GRILLE <i>new</i>	\$ 519.00	+
13	END CAP <i>new</i>	\$ 83.00	+
14	FOAM FILLER PIECE <i>new</i>	\$ 259.00	+
15	FRONT BUMPER CARRIER <i>new</i>	\$ 831.00	+
16	FRONT BUMPER COVER	\$ 116.00	+
17	GUIDE SECTION - LH <i>new</i>	\$ 34.00	+
18	FRONT PARKING SENSOR - INNER <i>new</i>	\$ 231.00	+
19	FRONT PARKING SENSOR - OUTER <i>new</i>	\$ 231.00	+
20	PARKING SENSOR SEAL RING	4 \$ 12.00	+

SUB TOTAL SPARE PARTS: **\$ 10,027.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLH 8118 H**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	MOUNTING FOR MAIN BEAM HEADLIGHT <i>new</i>	\$ 107.00	*
22	LED HEADLIGHT - LH <i>new</i>	\$ 7,227.00	*
23	LIFT CYLINDER - LH <i>new</i>	\$ 128.00	*
24	CAUTION' SIGN <i>new</i>	\$ 13.00	*
25	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 18.00	*
26	WHEEL COVER - LH <i>new</i>	\$ 577.00	✓
27	WHEEL COVER - RH <i>new</i>	\$ 577.00	✓
28	CLIP	\$ 124.00	?
29	FRONT NUMBER PLATE <i>new</i>	\$ 25.00	✓
30	SUNDRIES	\$ 500.00	?
TOTAL SPARE PARTS		\$ 19,323.00	
TOTAL LABOUR CHARGES		\$ 4,272.00	
GRAND TOTAL		\$ 23,595.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L
Surveyed Date : 13/03/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 83 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant