

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 6/3/2010
VEHICLE NO: SJY7702L
MODEL: MAZDA 3 HB
YEAR: 2009
ACCIDENT DATE: 4/3/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

S/NET

RH SIDE SKIRT *repair*

1

\$ 653.10

TOTAL: \$ 653.10

LABOUR

LABOUR FOR FACILITATE REPAIR

TO RESPRAY AFFECTED AREAS -FRONT BUMPER

TO RESPRAY AFFECTED AREAS - RH FRONT FENDER

TO RESPRAY AFFECTED AREAS - RH FRONT DOOR

TO RESPRAY AFFECTED AREAS - RH REAR DOOR

TO RESPRAY AFFECTED AREAS - RH SIDE SKIRT

TO RESPRAY AFFECTED AREAS - RH REAR FENDER

TO CHECK AND RECONNECT ALL NECESSARY WIRING

TO REMOVE AND REFIT RH FRONT DOOR COMPONENT FOR FACILITATE REPAIR

TO REMOVE AND REFIT RH FRONT UNDERCARRIAGE

TO ROTATE AND BALANCE RH FRONT RIM

WHEEL ALIGNMENT

SUNDARIES

RUST PROOFING

PRICE

\$ 500 1,200.00

\$ 200 300.00

\$ 200 300.00

\$ 200 300.00

\$ 200 300.00

\$ 100 300.00

\$ 200 300.00

\$ X 100.00

\$ X 150.00

\$ 100 350.00

\$ 50 100.00

\$ 60 100.00

\$ X 80.00

\$ 60 100.00

TOTAL: \$ 3,980.00

TOTAL: \$ 9,236.54

7% GST: \$ 646.56

\$ 9,883.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Stamp

Rasul

Hp 90010068

7 days

4/3

12/03/19 @ 1010

Resy after repair

NOTE: Require wheel alignment copy

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 6/3/2010
VEHICLE NO: SJY7702L
MODEL: MAZDA 3 HB
YEAR: 2009
ACCIDENT DATE: 4/3/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
FRONT BUMPER <i>repair</i>	1	\$ 779.60
FRONT BUMPER CLIPS <i>sc-</i>	10	\$ 30.00
RH FRONT BUMPER RETAINER <i>X</i>	1	\$ 76.30
RH FRONT FENDER <i>repair</i>	1	\$ 345.20
RH FRONT FENDER INNER SHIELD <i>X</i>	1	\$ 213.10
RH FRONT FENDER INNER SHIELD CLIPS <i>X</i>	10	\$ 30.00
RH FRONT DOOR <i>repair</i>	1	\$ 998.50
RH FRONT DOOR BLACK TAPE (COMPLETE) <i>X</i>	1	\$ 98.50
RH REAR DOOR <i>repair</i>	1	REPAIR
RH REAR FENDER <i>repair</i>	1	REPAIR
RH FRONT RIM <i>sc-</i>	1	\$ 785.10 <i>\$/n 300</i>
RH FRONT ABSORBER <i>X</i>	1	\$ 497.40
RH FRONT KNUCKLE ARM <i>?</i>	1	\$ 466.30
RH FRONT LOWER ARM <i>?</i>	1	\$ 365.30
RH FRONT WHEEL HUB <i>?</i>	1	\$ 377.60
RH FRONT WHEEL HUB BEARING <i>?</i>	1	\$ 295.60
RH FRONT TIE ROD <i>X</i>	1	\$ 196.40
RH FRONT STABILIZER LINK <i>X</i>	1	\$ 199.40

TOTAL: \$ 5,754.30
DISCOUNT 20%: \$ 1,150.86
\$ 4,603.44