

曉企美

Win Auto Enterprise
Blk 1033 Eunos Ave 5A #01-31
Singapore 409703
HP No: +65 9745 8981
Fax No: +65 6842 5778

TPEW

Xiao Tony

MNTBBA B 1720015824

9 6893-735

Adm

Estimated Quotation Vehicle No: SKZ9458L

Quantity	Items	Amount SGD\$ (Nett)	Remarks
1 Pc	Front Door Ventid	\$973.80	✓
1 Pc	Front Door Top Moulding	\$158.00	+
1 Pc	Front Door Lower Moulding	\$148.00	✓
1 Pc	Front Door Lock Inner Rubber	\$180.30	-
1 Pc	Front Door Lock	\$297.20	✓
1 Pc	Rooftop Moulding	\$238.50	x.
1 Pc	Rooftop Moulding Clip	\$21.00	+
1 Pc	Front Door Outer Handle	\$169.00	x.
1 Pc	Rear Door Dislute	\$987.40	✓
1 Pc	Rear Door Hing Top Bent	\$78.10	✓
1 Pc	Rear Door Hing Lower Bent	\$78.10	✓
1 Pc	Rear Door Centre Stopper	\$79.50	x.
1 Pc	Rear Door Outer Rubber	\$191.20	✓
1 Pc	Rear Door Inner Rubber	\$187.30	-
1 Pc	Rear Door Lower Rubber	\$68.10	+
1 Pc	Rear Door Window Glass Shutter	\$780.00	Special Nett
1 Pc	Rear Door Lock	\$267.20	✓
1 Pc	Rear Door Cut Board	\$822.50	✓
1 Pc	Rear Door Window Glass Motor	\$553.20	✓

Win Auto Enterprise

Blk 1033 Eunos Ave 5A #01-31

Singapore 409703

HP No: +65 9745 8981

Fax No: +65 6842 5778

1 Pc	Rear Door Glass Window Gear <i>Repl</i>	\$213.80	<i>e</i>
1 Pc	Rear Door Moulding Top <i>Repl</i>	\$187.00	<i>✓</i>
1 Pc	Rear Door Moulding Lower <i>Repl</i>	\$155.00	<i>✓</i>
1 Pc	Rear Door Outer Handle <i>Repl</i>	\$178.00	<i>✓</i>
1 Pc	Rear Door Inner Handle <i>Repl</i>	\$190.10	<i>x</i>
2Pcs	Rear Door Handle Cable <i>Repl</i>	\$130.60	<i>x</i>
1 Pc	Rear Door Pillar Sticker <i>Repl</i>	\$68.10	<i>✓</i>
1 Pc	Rear Centre Pillar <i>Repl</i>	\$1,575.70	<i>x</i>
1 Pc	Rear Centre Pillar Garnish <i>Repl</i>	\$325.10	<i>+</i>
1 Pc	Rear Pillar Step Garnish <i>Repl</i>	\$235.00	<i>✓</i>
1 Pc	Rear Bumper <i>Torn</i>	\$786.20	<i>✓</i>
1 Pc	Rear Bumper Side Bracket <i>Repl</i>	\$120.10	<i>✓</i>
1 Pc	Rear Shock Absorber <i>Repl</i>	\$217.70	Special Nett
1 Pc	Rear Knuckle Arm <i>Repl</i>	\$1,368.90	Special Nett
1 Set	Rear Wheel Bearing <i>Repl</i>	\$210.10	<i>x</i>
2 Pcs	Front and Rear Window Glass Sun X <i>Repl</i>	\$220.00	<i>180</i>
	Total Amount	\$12,459.80	

*Repl RH wheel rim 600
600(SW)*

*7480 20
6732 18 S.N. 500*

Win Auto Enterprise
 Blk 1033 Eunos Ave 5A #01-31
 Singapore 409703
 HP No: +65 9745 8981
 Fax No: +65 6842 5778

Labour Charges	Amount SGD\$
Spray Painting	\$1,900.00 1400
Knocking and Welding	\$1,500.00 1200
Remove Cushion	\$180.00 80
Remove and Fix Petrol Tank	\$180.00 x
Remove Rooftop Cushion	\$150.00 120
Spray Undercoating	\$250.00 60
Remove Undercarriage	\$250.00 x
4 wheels alignment	\$150.00 80
Remove and Fix Rear Triangle Glass	\$180.00 x
Remove and Fix Rear Windscreen	\$280.00 x
Remove and Fix Front Windscreen	\$280.00 120 3140
1 Set of Windscreen Gum	\$100.00 50
1 Set of Windscreen Seal	\$180.00 x
Checking of Wiring	\$150.00 30
Total Amount	\$5,730.00

LKK Auto Consultants will notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

831C

Adrian Lij
 L/s 05/03/19.

102y

total 1037218
 L/s 831C