

SOF964H.

Hyundai Elantra.

KMH D841CMJ4744695

TP ALG.  
Asher

Rear Bumper <sup>Rehnd</sup>

495.40 ✓

Rear Bumper Clips <sup>m</sup>

30 ✓

Rear Bumper Side Holder x 02

<sup>new</sup>

26 x 2 = 52 x

Rear Bumper Side Reflector LH. <sup>14</sup>

<sup>new</sup>

38 x

Reverse Sensor

<sup>new</sup>

280 (SN) x

525.40

420.32

Panel Beating

~~300~~ 200

Spray Painting

~~300~~ 200

Wiring

~~50~~ 30

380.

To remove reverse sensor ~~100~~ 50

total: 800.32

L/S: 650

02000

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

|    |                                               |   |             |                            |
|----|-----------------------------------------------|---|-------------|----------------------------|
| 20 | AIR CONDENSOR                                 | 1 | \$ 1,495.00 | \$ 1,495.00                |
| 21 | RADIATOR                                      | 1 | \$ 1,795.00 | \$ 1,795.00                |
| 22 | RADIATOR FAN COWLING                          | 1 | \$ 422.00   | \$ 422.00                  |
| 23 | RADIATOR FAN MOTOR                            | 1 | \$ 589.00   | \$ 589.00                  |
| 24 | RADIATOR FAN BLADE                            | 1 | \$ 170.00   | \$ 170.00                  |
| 25 | BOOT LID <i>Distorted</i>                     | 1 | \$ 1,850.00 | \$ 1,850.00                |
| 26 | BOOT LID LOGO <i>3/4</i>                      | 1 | \$ 59.00    | \$ 59.00                   |
| 27 | BOOT LID EMBLEM '528'                         | 1 | \$ 62.00    | \$ 62.00                   |
| 28 | BOOT LID TOP LOCK <i>Byd</i>                  | 1 | \$ 350.00   | \$ 350.00                  |
| 29 | BOOT LID LOWER CATCH <i>3/4</i>               | 1 | \$ 92.00    | \$ 92.00                   |
| 30 | BOOT LID REFLECTOR <i>crack</i>               | 2 | \$ 520.00   | \$ 1,040.00                |
| 31 | BOOT LID HINGE <i>3/4</i>                     | 2 | \$ 75.00    | \$ 150.00                  |
| 32 | BOOT LID WEATHERSTRIP <i>at</i>               | 1 | \$ 288.90   | \$ 288.90                  |
| 33 | REAR BUMPER <i>Distorted</i>                  | 1 | \$ 1,650.00 | \$ 1,650.00                |
| 34 | REAR BUMPER REFLECTOR                         | 2 | \$ 45.60    | \$ 91.20                   |
| 35 | REAR BUMPER TOW HOOK COVER <i>crack</i>       | 1 | \$ 52.00    | \$ 52.00                   |
| 36 | REAR BUMPER SENSOR <i>3 pieces dyd</i>        | 4 | \$ 261.00   | \$ <del>1,044.00</del> 783 |
| 37 | REAR BUMPER SENSOR HOLDER <i>3 pieces dyd</i> | 4 | \$ 19.75    | \$ <del>79.00</del> 59.25  |
| 38 | REAR BUMPER SENSOR WIRE HARNESS               | 1 | \$ 499.00   | \$ 499.00                  |
| 39 | REAR BUMPER CORNER BRACKET (PLASTIC)          | 2 | \$ 96.75    | \$ 193.50                  |
| 40 | REAR BUMPER BOTTOM GARNISH                    | 1 | \$ 798.60   | \$ 798.60                  |
| 41 | REAR BUMPER BOTTOM GARNISH (SIDE)             | 1 | \$ 214.85   | \$ 214.85                  |
| 42 | REAR BUMPER SIDE RETAINER <i>me</i>           | 2 | \$ 99.80    | \$ 199.60                  |
| 43 | REAR BUMPER BEAM                              | 1 | \$ 179.45   | \$ 179.45                  |
| 44 | REAR BUMPER REINFORCEMENT                     | 1 | \$ 490.95   | \$ 490.95                  |
| 45 | REAR BUMPER REINFORCEMENT BRACKET             | 2 | \$ 149.75   | \$ 299.50                  |
| 46 | TAIL LAMP <i>crack</i>                        | 2 | \$ 630.00   | \$ 1,260.00                |
| 47 | TAIL LAMP BRACKET                             | 2 | \$ 87.80    | \$ 175.60                  |
| 48 | REAR FENDER <i>Repair</i>                     | 2 | \$ 1,405.00 | \$ 2,810.00                |
| 49 | REAR FENDER COWLING RH                        | 2 | \$ 183.25   | \$ 366.50                  |
| 50 | REAR FENDER INNER TRIM                        | 2 | \$ 379.15   | \$ 758.30                  |
| 51 | REAR WINDSCREEN MOULDING                      | 1 | \$ 222.30   | \$ 222.30                  |
| 52 | REAR END PANEL <i>Distorted</i>               | 1 | \$ 920.00   | \$ 920.00                  |
| 53 | REAR END PANEL TOP GARNISH <i>Distorted</i>   | 1 | \$ 390.00   | \$ 390.00                  |
| 54 | REAR FLOOR PANEL                              | 1 | \$ 1,735.50 | \$ 1,735.50                |
| 55 | REAR FLOOR TOP BOARD <i>seal</i>              | 1 | \$ 397.65   | \$ 397.65                  |
| 56 | REAR SPONGE (TOOLS TRAY)                      | 1 | \$ 186.25   | \$ 186.25                  |
| 57 | REAR SPONGE (TOOLS TRAY COVER)                | 1 | \$ 216.55   | \$ 216.55                  |
| 58 | REAR EXHAUST PIPE                             | 1 | \$ 1,600.00 | \$ 1,600.00                |