

URGENT

C/03/2009

ASS. REC. BY:

REF C83/III/19061060/Btd35²

Special Instruction:

Surveyor: Mr Jim

ASSIGNMENT (Office)

04/03/19 @ 5.58pm

From (Person): ^{in person} Gabriel Wee

of III

Date/Time: 1

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKM 2117K

Insured:

SHA 2935P

at Workshop in/s

~~Modern Automotive~~

Tel:

82728575 / 90210057

of

BLK 3023A Ubi Road 1 # 01-64

*Repairer at: Prestige Motor

Policy No:

MCOM0015

Claim No:

MCT19010436

Sum Insured:

Excess:

6768442

Make of Veh:

D.O.A

16/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 12:06pm @ 17/1/2019

Person Contacted:

Chong

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKM 2117K - X
	SHA 2935P - C83/III/15015543/Ybdl DOA: 10/9/15
	Dismantle: 18/1/2019 2.20pm
	After repair: 24/1/2019 2.24pm
	SKM 2117K C84/LPC19001091/T1f63 DOA: 16/1/19

lump sum \$6650 (Red 5850: 46.8%)

7 days

File pass to typist.

in. into
8/3/2019

RECEIVED 08 MAR 2019

REF: INDIA

ASSIGNMENT

From:

Date: 17/1/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKM 2117K

at Workshop with: MODERN AUTOMOTIVE

of BLK5023A UBI Rd 1, 01-64

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKM 2117K

Yr Regn: 5/2 / 2014

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ

cc: 1595

Colour: WHITE

A/C: Insured / Std / NI / NA

Sp. Reading: 27532

T/Radio: Insured / Std / NI / NA

Eng No: 27071830260331

Ch No: WDD1760432J175509

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ STD / ☐ STD A/Rim or

Tyre Size: F: 225/45R17

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 16/1/19

D.O.I: 17/1/19

Survey held at: MODERN AUTO

Des. of Damages: ☒ Fnt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV 73,000/2

PV 49,580/2

NV 22,420/2

Team Luv
21/1/2019

Date/Time, File Pass to?



: Proli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

Transportation

) S + RS: \$

) Photos

) Other:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format: PRC

Lump Sum / I.B.I: (\$

TOTAL

Nivitha (LKK Auto)

From: Stanley Lai <stanley.lai@iii.com.sg>
Sent: Monday, 4 March 2019 5:58 PM
To: 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Manivel Priyadarshini; Mekavathanan Sarangapani
Subject: RE: MCT19010436

Dear Sir/Mdm,

Rights granted in Merimen for the above LOD. Kindly proceed with the paper survey.

TP Veh No. : **SKM2117K**

Warmest regards,

Stanley Lai

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

S&P 'A-' rated Company



From: Mekavathanan Sarangapani

Sent: Friday, 1 March, 2019 1:24 PM

To: Stanley Lai <stanley.lai@iii.com.sg>

Cc: Gabriel Wee <Gabriel@iii.com.sg>; Manivel Priyadarshini <manivel@iii.com.sg>

Subject: FW: MCT19010436

Send LOD to LKK to do paper survey please .

Best Regards,

Mekavathanan

HOD

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6105 Fax: 6224 4174



From: Mekavathanan Sarangapani

Sent: Friday, March 01, 2019 1:22 PM

To: Manivel Priyadarshini <manivel@iii.com.sg>; Gabriel Wee <Gabriel@iii.com.sg>; Hsiao Tong (chewht@lkkauto.com) <chewht@lkkauto.com>; Olivia Lau (olivialau@lkkauto.com) <olivialau@lkkauto.com>

Cc: Stanley Lai <stanley.lai@iii.com.sg>

Subject: RE: MCT19010436

LOD is given as Prestige Motor Pte Ltd - 191 Tg. Katong Road S 436993

LKK team may want to clarify this ?

Main	28 Jan 2019	17 Jan 2019 00:00	17:58 S\$0.00 (S\$139.10)	Pending for Offer Cancel Case
------	-------------	-------------------	---------------------------	----------------------------------

Main	Offer Processing	Claim Details	Adjuster's Details
------	------------------	---------------	--------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]			
Insured:	-, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	SKM2117K	Date of Loss:	16/01/2019 00:00 - :5 [59 Months and 11 Da
Claim Type:	TP / MCT19010436	Policy/Cover Note No.:	MC00015
Vehicle Reg. No. (Insured):	SHA2935P	Policy No. (Claimant):	
		Excess:	
Repairer:	Modem Automotive Pte Ltd (HQ) PROFILE BLK 3023A UBI ROAD 1 #01-61, 408717 Ubi - Tel: 6741		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final R		

CLAIM REGISTERED			
Cim. No (Cim Reg Date)	MCT19010436 (22/02/2019)	Intimation (Notify Date)	From T
Registration Type	[Manually registered]	Claim Status	OPEN
Incurred TP			
S\$	0.00		
Subfolder	SubCode	Reg. No / Claimant	Person-in-Charge
TP BI		SHB6389JPAX / JOANNE NG	Priya
TP		SKM2117K / -	Priya

ASSOCIATED MAIL RECEIVED	
• LKK_HQ (11/02/2019): Alert: Final Report (SKM2117K)	

Best Regards,

Mekavathanan

HOD

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6105 Fax: 6224 4174



From: Mekavathanan Sarangapani
Sent: Friday, March 01, 2019 1:19 PM
To: Manivel Priyadarshini <manivel@iii.com.sg>; Gabriel Wee <Gabriel@iii.com.sg>
Cc: Stanley Lai <stanley.lai@iii.com.sg>
Subject: FW: MCT19010436

Please write write to ARC and copy GIA - ARC use lawyers

LOd from Cathering Lim LLC

Meka

Modern Automotive Pte Ltd	HQ	Blk 3023A Ubi Road 1	#01-61 & #01-58	408717
Modern Automotive Pte Ltd	HQ	Blk 3023A Ubi Road 1	#01-61 & #01-58	408717

Best Regards,

Mekavathanan
HOD
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street, #04/#05 IOB Building, Singapore 049711
DID: 6347 6105 Fax: 6224 4174



From: Mekavathanan Sarangapani
Sent: Friday, March 01, 2019 1:17 PM
To: Hsiao Tong (chewht@lkkauto.com) <chewht@lkkauto.com>; Olivia Lau (olivialau@lkkauto.com) <olivialau@lkkauto.com>
Subject: MCT19010436

Your adjustment for this TP vehicle – not received yet ?

Meka



16/01/2019

02:36



Modern Automotive Pte Ltd	HQ	Blk 3023A Ubi Road 1	#01-61 & #01-58	408717
Modern Automotive Pte Ltd	HQ	Blk 3023A Ubi Road 1	#01-61 & #01-58	408717

Best Regards,

Mekavathanan

HOD

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6105 Fax: 6224 4174



MCT/19070436

	RESERVES			
	TPPD	PRESERVE	61C	
	TPPI	PRESERVE		
	UNINSURED LOSS	PRESERVE		
	SUBRO	PRESERVE		
	LPPN			
	INVESTIGATION FEE			
	SURVEY FEES		3600	
	LEGAL FEES			
	OTHERS			
	FRAUD CHECK			
	UPLOAD TO MERIMEN			
	GRANT RIGHTS			

*** FAX TX REPORT ***

TRANSMISSION OK

JOB NO.	0209
DESTINATION ADDRESS	967476720
SUBADDRESS	
DESTINATION ID	
ST. TIME	01/03 15:26
TX/RX TIME	00' 18
PGS.	1
RESULT	OK

Gabriel Wee

From: Gabriel Wee
Sent: 01 March, 2019 3:26 PM
To: 'Sally'
Cc: Mekavathanan Sarangapani; Manivel Priyadarshini; 'Cynthia Chan'
Subject: Engaging Lawyers is a breach of ARC Agreement [YOUR REF: SKM2117K | OUR REF: MCT19010436]

WITHOUT PREJUDICE

Dear Sir/Madam,

According to GIA-merimen, you are one of the Approved Reporting Centres (ARCs) for Longpac Insurance and NTUC Income.

Please refer to the sample of the ARC Agreement that you have signed with the respective insurers before.

According to Clause 5.2 (d), "as an Approved Reporting Centre, the Nominee ARC shall:

- (d) not under any circumstances refer, sub-contract, transfer, shift and/or assign or reassign any repair tasks and/or claims to any workshop and/or any other entity to allow the workshop and/or entity to initiate third party claims, regardless of whether such third party claims are filed through a law firm or otherwise, and"

'Insurance Company and/or GIA reserve the right to cancel, reject and/or revoke the appointment...' if there is a breach of the agreement.

Moreover, an ARC's contract obligation is stated in Clause 6.2 where the Insurance Company will be compensated for any legal costs as a result of the breach.

Kindly withdraw the property damage claim from the lawyers and send us a notice of withdrawal as soon as possible so there wont be any further complications.

You can settle the case through direct settlement with our Ms Priya (manivel@iii.com.sg).

Thank you.

Gabriel Wee

From: Gabriel Wee
Sent: 01 March, 2019 3:26 PM
To: 'Sally'
Cc: Mekavathanan Sarangapani; Manivel Priyadarshini; 'Cynthia Chan'
Subject: Engaging Lawyers is a breach of ARC Agreement [YOUR REF: SKM2117K | OUR REF: MCT19010436]

WITHOUT PREJUDICE

Dear Sir/Madam,

According to GIA-merimen, you are one of the Approved Reporting Centres (ARCs) for Longpac Insurance and NTUC Income.

Please refer to the sample of the ARC Agreement that you have signed with the respective insurers before.

According to Clause 5.2 (d), "as an Approved Reporting Centre, the Nominee ARC shall:

- (d) not under any circumstances refer, sub-contract, transfer, shift and/or assign or reassign any repair tasks and/or claims to any workshop and/or any other entity to allow the workshop and/or entity to initiate third party claims, regardless of whether such third party claims are filed through a law firm or otherwise, and"

'Insurance Company and/or GIA reserve the right to cancel, reject and/or revoke the appointment...' if there is a breach of the agreement.

Moreover, an ARC's contract obligation is stated in Clause 6.2 where the Insurance Company will be compensated for any legal costs as a result of the breach.

Kindly withdraw the property damage claim from the lawyers and send us a notice of withdrawal as soon as possible so there wont be any further complications.

You can settle the case through direct settlement with our Ms Priya (manivel@iii.com.sg).

Thank you.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

CC- Modern Automotive Pte Ltd

 *** FAX TX REPORT ***

TRANSMISSION OK

JOB NO. 0211
 DESTINATION ADDRESS 964380111
 SUBADDRESS
 DESTINATION ID
 ST. TIME 01/03 17:29
 TX/RX TIME 00' 27
 PGS. 2
 RESULT OK

FAXED
 01 MAR 2019
 MOTCLM DEPT.

Modern
CATHERINE LIM LLC

林 林 ADVOCATES & SOLICITORS
 翠 NOTARY PUBLIC - 公证官
 玲 COMMISSIONER FOR OATHS - 宣誓官
 律 CATHERINE C.L.LIM
 師 DIRECTOR
 館 LL.B (HONS) SINGAPORE - 法律系 - 律師
 M.B.A. (BUSINESS LAW) - 商业系 - 碩士



20 Havelock Road #03-01
 Central Square Singapore 059765
 UEN No. 201310922K

Tel: (65) 6438 5500
 Fax: (65) 6438 0111
 www.catherinelimllc.com
 Email: info@catherinelimllc.com
 CATHERINE LIM LLC is a law
 corporation with limited liability

30324
Lim
 Our Ref: CL/190149/T/PA.sg

26 February 2019

India International Insurance Pte Ltd
 64 Cecil Street #04-05
 IOB Building
 Singapore 049711
 Attn: Motor Claims Dept

Comfort Transportation Pte Ltd
 383 Sin Ming Drive
 GAS Building
 Singapore 575717

Dear Sir

ACCIDENT INVOLVING SKM 2117K / SHA 2935P ON 16.01.2019 ALONG KPE TOWARDS PIE AFTER EXIT PUNGGOL

We act for **Goh Siew Eng Carolyn**, the owner of motor vehicle No. SKM 2117K, which was involved in the above accident.

Our client has suffered loss and damage as a result of your Insured's negligence in the driving of motor vehicle No. SHA 2935P.

We quantify our client's claim as follows:-

1. Cost of Repair	\$12,500.00
2. Loss of use (\$180 x 9 days)	\$ 1,620.00
3. Survey fee	\$ 970.00
4. LTA search fee	\$ 8.00
5. Incidentals, transport & photocopying etc	\$ 53.50
6. Cost contribution	\$ 963.00

 \$16,114.50

WITHOUT PREJUDICE

(to the personal injury claim)

BY HAND

CERTIFICATE OF POSTING
 (Please be informed that all supporting documents
 have been forwarded to your insurer)

We are in receipt of your letter, which is being forwarded to your insurer.
 Our Ref: *MC 119 010436*
 Name: *Prig*
 Date: *11/3/2019*
 India International Insurance Pte Ltd

Modern
CATHERINE LIM LLC

3032A
Lim
林 林 ADVOCATES & SOLICITORS
廖 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS - 宣誓官
律
師 CATHERINE C.L.LIM
館 DIRECTOR
LL.B (HONS) SINGAPORE-法律系-律師
M.B.A. (BUSINESS LAW)-商业系-硕士



20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K

Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law
corporation with limited liability

Our Ref: CL/190149/T/PA.sg

26 February 2019

India International Insurance Pte Ltd
64 Cecil Street #04-05
IOB Building
Singapore 049711
Attn: Motor Claims Dept

Comfort Transportation Pte Ltd
383 Sin Ming Drive
GAS Building
Singapore 575717

Dear Sir

WITHOUT PREJUDICE

(to the personal injury claim)

BY HAND

CERTIFICATE OF POSTING

(Please be informed that all supporting documents
have been forwarded to your insured)

Our Ref:
Name:
Date:

MC T/19 010436

**ACCIDENT INVOLVING SKM 2117K / SHA 2935P ON 16.01.2019 ALONG KPE TOWARDS PIE AFTER
EXIT PUNGGOL**

We act for **Goh Siew Eng Carolyn**, the owner of motor vehicle No. SKM 2117K, which was involved in the above
accident.

Our client has suffered loss and damage as a result of your Insured's negligence in the driving of motor vehicle No.
SHA 2935P.

We quantify our client's claim as follows:-

1. Cost of Repair	\$12,500.00
2. Loss of use (\$180 x 9 days)	\$ 1,620.00
3. Survey fee	\$ 970.00
4. LTA search fee	\$ 8.00
5. Incidentals, transport & photocopying etc	\$ 53.50
6. Cost contribution	\$ 963.00

\$16,114.50

We enclose herewith photocopies of our client's accident report, LTA search, final repair bill, survey fee, survey
report and colour photographs of our client's damaged vehicle for your immediate attention.

Please let us know within the next 14 days from the receipt of this letter, whether you are prepared to admit liability
and revert with a settlement proposal, failing which our clients shall have no alternative but to commence legal
proceedings against your insured.

Yours faithfully

Encs
cc: clients

(Please note that if your motor vehicle was not driven by you, there is a presumption in law that the said driver was driving as your agent/ servant
unless you let us know the particulars of your driver if your motor vehicle was not driven by you.)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/01/2019 15:02
Date Of Accident	16/01/2019 10:10
Exact Location Of Accident	KPE TOWARDS PIE AFTER EXIT PUNGGOL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM2117K
Insured/Policyholder	
Name Of Registered Owner	GOH SIEW ENG CAROLYN
NRIC No	S8622420H
Email Address	CAROLYN.WXY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96588801
Alternative Phone No	OFFICE-96588801

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	A200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05017504
Cover Note Number	

Driver

Name of Driver	GOH SIEW ENG CAROLYN
NRIC No	S8622420H
Date Of Birth	04/08/1986
Occupation	OUTDOOR
Date Of Driving Pass	15/07/2017
Driving Experience	1 YEAR AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96588801
Fax Number	
Contact Number	OFFICE-96588801
Email Address	CAROLYN.WXY@GMAIL.COM

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHB6389J
Vehicle Make/Model/Colour	TAXI / MERCEDES
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	DANIEL
NRIC/Passport Number	
Contact Number	96695129
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 2

SKETCH PLAN

KPE Towards DIE

1 C 1 A 1 B

A = SKM2117K
B = SHA2935P
C = SHB6389J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along KPE at extreme right lane, just entering KPE, a suddenly brake from vehicle 'C'. I manage to slow down. But, I was heavily bang by vehicle 'B' from behind and was forced my car to push forward and hit vehicle 'C'.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 16/1/2019 12:37pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

PRESTIGE AUTO AIR CON ACCESSORIES

191 Tanjong Katong Road

SINGAPORE 436993

FAX: 6842 3217

FINAL REPAIR BILL

Goh Siew Eng Carolyn
Blk 643 Punggol Central
#13-328
Singapore 820643

VEHICLE REG NO : SKM 2117K

To supply necessary parts and labour to repair the
above vehicle at a lump sum of

\$12,500.00

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

Automobile Inspection Report

To: Goh Siew Eng Carolyn
c/o 191 Tanjong Katong Road
Singapore 436993

Date : 31/01/2019

Reference No : CAS/19-01/065

General Information

Registration No. : SKM 2117K
Accident Date : 16/01/2019

Particulars of Damaged Vehicle

Colour	: White	Make & Model	: Mercedes Benz A200
Engine Capacity	: 1595 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 27529	Engine No.	: 27091030260331
Chassis No.	: WDD1760432J175509	Steering	: In Order
Registration Date	: 05/02/2014	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	225/45R17	CONTINENTAL	90%
L/H Front Tyre	225/45R17	CONTINENTAL	90%
R/H Rear Tyre	225/45R17	CONTINENTAL	80%
L/H Rear Tyre	225/45R17	CONTINENTAL	80%

Inspection

Repairer : Prestige Motor Pte Ltd
191 Tanjong Katong Road, Singapore 436993

Ubl #01-64.

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$19,602.46
Revised Amount : \$12,500.00
Less Excess : -
Nett Total : \$12,500.00

Same L/k

Remarks

- (A) Survey was done on 16/01/2019
- (B) Re-survey was done on 18/01/2019
- (C) Re-survey after repair was done on 24/01/2019
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Vehicle No : SKM 2117K

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
PARTS REPLACEMENT – LIST ITEMS						
1	1pc	Front bumper	Dented/Torn	1,318.07	✓ 1,318.07	DDV
2	1pc	Front bumper lower grille	Serviceable	147.66	-	
3	1pc	Front bumper grille RH	Deformed	61.27	✓ 61.27	CAP
4	1pc	Front bumper grille LH	Deformed	61.27	✓ 61.27	CAP
5	1pc	Front bumper emblem (logo)	Necessary	67.08	✓ 67.08	NEC
6	1pc	Front bumper reinforcement	Repair	396.60	-	
7	1pc	Front bumper top seal	Necessary	24.28	-24.28	NNX
8	1pc	Front bumper under cover	Serviceable	283.45	-	
9	6pcs	Front parking sensor @-\$314.20 x 2 pcs	4pcs Damaged	1,885.20	336.00 1,256.80	QTV
10	4pcs	Front parking sensor seal @ \$6.29 x 2 pcs	Necessary x 2 pcs	25.16	25.16	NEC
11	1pc	Front grille	Broken	844.38	460.00 844.38	BRV
12	1pc	Front grille emblem	Broken	406.32	160.00 406.32	BRV
13	1pc	Front impact sensor (radar sensor)	Damaged	1,238.78	✓ 1,238.78	BRV
14	2pcs	Headlamp @ \$976.52	N/S Grazed	1,953.04	780.00 976.52	QTV
15	1pc	Tailgate	Dented/Warped	1,976.23	1,976.23	RX
16	1pc	Tailgate emblem (logo)	Necessary	52.38	49.00 52.38	
17	1pc	Tailgate emblem (A200)	Necessary	84.48	58.00 84.48	NEC
18	1pc	Tailgate emblem (C&C)	Necessary	62.10	✓ 62.10	
19	1pc	Tailgate glass moulding C/W glass	Necessary	601.25	601.25	NN
20	1pc	Tailgate lock	Serviceable	200.03	-	
21	1pc	Tailgate weatherstrip	Distorted	193.78	193.78	NNX
22	1pc	Rear bumper	Dented/Broken	1,698.00	1,021.00 1,698.00	BRV
23	1pc	Rear bumper lower lid	Grazed/Deformed	302.36	228.00 302.36	DLV
24	1pc	Rear bumper center guide	Broken	101.98	101.98	BTV
25	1pc	Rear bumper reinforcement	Dented/Bent	497.20	485.00 497.20	BTV
26	2pcs	Rear bumper side guide @ \$53.62	Broken	107.24	✓ 107.24	BRV
27	4pcs	Rear bumper parking sensor @ \$314.20 x 2	Damaged x 2 pcs	1,256.80	336.00 1,256.80	QTV
28	4pcs	Rear bumper parking sensor seal @ \$6.29	Necessary	25.16	✓ 25.16	NEC
29	1pc	Rear end panel	Repair	967.46	-	
				16,839.01	13,238.89	
Less 10%				(1,683.90)	(1,323.88)	
Sub total				15,155.11	11,915.01	

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1set	Front bumper clip	Necessary	58.00	32.00 58.00
2	1pc	Front licence plate	Broken	50.00	25.00 45.00
3	1pc	Tailgate glass sealant	Necessary	80.00	80.00
4	1set	Tailgate inner trim board clip	Necessary	32.00	32.00
5	1set	Rear bumper clip	Necessary	55.00	32 55.00
6	3pcs	Tailgate emblem (logo) clip @ \$7.45	Necessary	22.35	✓ 22.35
Sub total				15,452.46	12,207.36
<u>LABOUR & MISC. CHARGES</u>					
1		Repair & replace damaged parts		1,400.00	500.00 1,200.00
2		Spray painting on affected area		1,700.00	1,400.00
3		Remove & refix rear trim board & garnish		120.00	80.00
4		Remove & refix tailgate mechanism		100.00	80.00
5		Remove & refix tailgate glass		140.00	120.00
6		Check wiring & refocus headlamp		50.00	20.00
7		Remove & renew parking sensor		100.00	60.00
8		Diagnose & reset system after repair		420.00	250.00 380.00
9		Spray anti rust on affected area		120.00	60.00 90.00
Grand total				19,602.46	15,637.36
Recommended cost of lump sum repair (To its pre-accident condition)					12,500.00

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$12,500.00** on a contractual basis. Under normal circumstances, the repair period would be about **9 (Nine)** working days.

7 days

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

TCG in Min
8/5/19




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III19001060/Btd3s2-1		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 08-03-2019		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2935P	Veh. Inspected	SKM 2117K	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT19010436	Excess (\$)	0.00	
Assign From	STANLEY LAI	Assign Date	04/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD1760432J175509	Colour	WHITE	
Odometer	27532	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/45R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/45R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/45R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/01/2019	Inspection Date	17/01/2019	
Survey held at	PRESTIGE AUTO 191 TANJONG KATONG ROAD SINGAPORE 436993			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 2117K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DENTED	1,318.07	1,318.07
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	147.66	-
1	FRONT BUMPER GRILLE RH	CRACKED	61.27	61.27
1	FRONT BUMPER GRILLE LH	CRACKED	61.27	61.27
1	FRONT BUMPER EMBLEM (LOGO)	NECESSARY	67.08	67.08
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	396.60	-
1	FRONT BUMPER TOP SEAL	NOT NECESSARY	24.28	-
1	FRONT BUMPER UNDER COVER	SERVICEABLE	283.45	-
6	FRONT PARKING SENSOR @ \$314.20	CUT	1,885.20	330.00
4	FRONT PARKING SENSOR SEAL @ \$6.29	NECESSARY	25.16	25.16
1	FRONT GRILLE	BROKEN	844.38	460.00
1	FRONT GRILLE EMBLEM	BROKEN	406.32	160.00
1	FRONT IMPACT SENSOR (RADAR SENSOR)	BROKEN	1,238.78	1,238.78
2	HEADLAMP @ \$976.52	N/S GRAZED	1,953.04	700.00
1	TAILGATE	TO REPAIR SEE LABOUR	1,976.23	-
1	TAILGATE EMBLEM (LOGO)	NECESSARY	52.38	47.00
1	TAILGATE EMBLEM (A200)	NECESSARY	84.48	58.00
1	TAILGATE EMBLEM (C&C)	NECESSARY	62.10	62.10
1	TAILGATE GLASS MOULDING C/W GLASS	NOT NECESSARY	601.25	-
1	TAILGATE LOCK	SERVICEABLE	200.03	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	193.78	-
1	REAR BUMPER	BROKEN	1,698.00	1,021.00
1	REAR BUMPER LOWER LID	DISLODGE	302.36	228.00
1	REAR BUMPER CENTER GUIDE	BENT	101.98	101.98
1	REAR BUMPER REINFORCEMENT	BENT	497.20	485.00
2	REAR BUMPER SIDE GUIDE @ \$53.62	BROKEN	107.24	107.24
4	REAR BUMPER PARKING SENSOR @ \$314.20	CUT 2PCS ONLY	1,256.80	330.00
4	REAR BUMPER PARKING SENSOR SEAL @ \$6.29	NECESSARY	25.16	25.16
1	REAR END PANEL	TO REPAIR SEE LABOUR	967.46	-

Report Ref No. CS3/III19001060/Btd3s2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,683.90	-688.72
			15,155.11	6,198.39
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	58.00	32.00
1	FRONT LICENCE PLATE (SN)	BROKEN	50.00	25.00
1	TAILGATE GLASS SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET TAILGATE INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	32.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	55.00	32.00
3	TAILGATE EMBLEM (LOGO) CLIP @ \$7.45 (SN)	NECESSARY	22.35	22.35
			297.35	111.35
	<u>LABOUR</u>			
	REPAIR & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT, TAILGATE AND REAR END PANEL.		1,400.00	800.00
	SPRAY PAINTING ON AFFECTED AREA.		1,700.00	800.00
	REMOVE & REFIX REAR TRIM BOARD & GARNISH.		120.00	50.00
	REMOVE & REFIX TAILGATE MECHANISM.	NOT NECESSARY	100.00	-
	REMOVE & REFIX TAILGATE GLASS.	NOT NECESSARY	140.00	-
	CHECK WIRING & REFOCUS HEADLAMP.		50.00	20.00
	REMOVE & RENEW PARKING SENSOR.		100.00	60.00
	DIAGNOSE & RESET SYSTEM AFTER REPAIR.		420.00	250.00
	SPRAY ANTI RUST ON AFFECTED AREA.		120.00	60.00
			4,150.00	2,040.00
GRAND TOTAL			19,602.46	8,349.74
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,650.00

Report Ref No. CS3/III19001060/Btd3s2-1

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.