

REPAIR ESTIMATE*

VEHICLE NO : SHA 810D (Supplementary)



DATE : 7.03.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Sponge <i>ton</i>			\$ 99.20
	SUB TOTAL			\$ 99.20
	LESS 20%			\$ 19.84
	DISCOUNTED TOTAL			\$ 79.36
	<i>07/03/2019</i>  <i>2kk Auto</i> 			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.