

ASS. REC. BY:

REF:

TM1/ CO3/TM1/900484/KD3 n2

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Soon:

Est. Repairs:

Lum Sum:

Consistent?: Yes or No

Consistent?: Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M/T S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.


L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

1/ File pass to

9359.00 (led. 322446; 80%)

SID 8504 x

SLR 80910 x

7/3- Revert via email GIA report and estimate.

RECEIVED 14 MAR 2019

Date/Time, File Pass to?

14/3 Typist

Date/Time, File Return to?

2)

☐: Prel. Report☒: Final Report

Days Of Repair: 5

Resurvey No. of Trip: -

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐: Site Insp (\$)☐: Interview (\$)☐: Tech Invs (\$)☐: Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

93591-

250

10

260

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Thursday, 7 March 2019 3:02 PM  
**To:** Motor Claims  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 5/3/2019 , SHD 850Y (TP Vehicle), SLQ 8091C (OI Vehicle)  
**Attachments:** GIA SHD 850Y.pdf; SHD 850Y ESTIMATE.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 850Y at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 6/3/2019  
Enclosed herewith a copy of TP's GIA report and estimated cost of repair .

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHD850Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 Mar 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003415
Chassis No.:	VF1ABL15AUC283391
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	01 Mar 2017
First Registration Date:	01 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Feb 2025
PARF Rebate Amount:	\$14,998.00

**Intended COE Rebate Details**

COE Expiry Date:	28 Feb 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,544.00
COE Rebate Amount:	\$29,584.00
<b>Total Rebate Amount:</b>	<b>\$44,582.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/03/2019 11:16
Date Of Accident	05/03/2019 09:25
Exact Location Of Accident	CANTONMENT LINK SLIP ROAD TOWARDS CANTONMENT ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD850Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	CHIA SENG SAI LAWRENCE
NRIC No	S7030985H
Date Of Birth	03/09/1970
Occupation	OUTDOOR
Date Of Driving Pass	01/02/2011
Driving Experience	8 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81002983
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 312 YISHUN RING ROAD #02-1196
Postcode	760312
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 05.03.2019 at about 0925hours, I was travelling straight on the extreme right lane along Cantonment Link slip Road towards Cantonment Road. I slow down and made a stop when I saw pedestrian crossing. While stationary, suddenly I felt an impact. Vehicle B (SLQ8091C) hit onto my taxi's rear portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ8091C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach GIA Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SHD 850Y****AAD1903-032***Not Authored**Reserve B4 paint**89358.00*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

**SHD 850Y**

VF1ABL15AUC283391

RENAULT

LATITUDE

5.3.2019

**TOKIO MARINE**

1/3/2017

**PART****LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPR BRACKET SIDE RH REAR
- 5 1 BUMPR RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPR BRACKET SIDE LH REAR
- 8 1 BUMPR RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

- |    |            |          |     |
|----|------------|----------|-----|
| \$ | <i>Bu</i>  | 1,108.46 | ✓   |
| \$ | <i>bu</i>  | 768.84   | ✓   |
| \$ | <i>SL</i>  | 113.47   | X   |
| \$ | <i>SL</i>  | 135.97   | X   |
| \$ | <i>SL</i>  | 44.99    | X   |
| \$ | <i>SL</i>  | 43.61    | X   |
| \$ | <i>SL</i>  | 135.97   | X   |
| \$ | <i>SL</i>  | 44.99    | X   |
| \$ | <i>SL</i>  | 43.61    | X   |
| \$ | <i>Bu</i>  | 777.52   | ✓   |
| \$ | <i>D.1</i> | 225.95   | ✓   |
| \$ | <i>D.1</i> | 225.95   | ✓   |
| \$ | <i>Bu</i>  | 2,872.68 | ✓   |
| \$ | <i>SL</i>  | 470.06   | X   |
| \$ | <i>SL</i>  | 323.05   | X   |
| \$ | <i>SL</i>  | 493.35   | X   |
| \$ | <i>SL</i>  | 493.35   | X   |
| \$ | <i>bu</i>  | 225.36   | ✓   |
| \$ | <i>bu</i>  | 225.36   | ✓   |
| \$ | <i>SL</i>  | 276.08   | } X |
| \$ | <i>SL</i>  | 276.08   |     |
| \$ | <i>R</i>   | 367.84   |     |
| \$ | <i>R</i>   | 367.84   |     |
| \$ | <i>SL</i>  | 586.45   |     |
| \$ | <i>SL</i>  | 168.13   |     |
| \$ | <i>R</i>   | 202.67   |     |
| \$ | <i>R</i>   | 74.40    |     |
| \$ | <i>SL</i>  | 50.52    |     |
| \$ | <i>SL</i>  | 221.81   |     |



**Trans-cab Auto Services Pte Ltd**

AAD1903-032

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 850Y**

30	1 FENDER PANEL REAR RH	\$	<i>R</i>	3,299.13	X
31	1 WHEELARCH REAR RH	\$	<i>SL</i>	543.47	X
32	1 FENDER PANEL REAR LH	\$	<i>R</i>	3,299.13	X
33	1 WHEELARCH REAR LH	\$	<i>SL</i>	543.47	X
34	1 TAILLAMP LH	\$	<i>SL</i>	552.55	X
35	1 TAILLAMP PANEL LH	\$	<i>R</i>	986.70	X
36	1 TAILLAMP RH	\$	<i>ngem</i>	552.55	✓
37	1 TAILLAMP PANEL RH	\$	<i>R</i>	986.70	X
38	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i>	1,471.77	✓
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i>	404.56	X
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i>	2,189.88	X
41	1 SPARE WHEEL PANEL TRIM	\$	<i>SL</i>	612.21	X
42	1 EXHAUST REAR	\$	<i>SL</i>	7,489.05	X
43	1 EXHAUST CAP REAR	\$	<i>SL</i>	230.49	X

02

<b>TOTAL</b>	\$	<b>34,526.04</b>
<b>10%</b>	\$	<b>3,452.60</b>
	\$	<b>31,073.44</b>

**Special Nett**

1	1SET PARKING AID	\$	<i>SL</i>	700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>na</i>	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>SL</i>	17.82	X
11	1SET BOOT FINISHER CLIP	\$	<i>na</i>	24.20	X
12	1 BOOT ADVERTISEMENT STICKER	\$	<i>na</i>	300.00	X
13	1 REAR BUMPER ADVERTISEMENT STICKER	\$	<i>na</i>	200.00	<i>done</i>

**Trans-cab Auto Services Pte Ltd****AAD1903-032**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 850Y**

14	1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
15	1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
16	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
18	1 TAILLAMP CLIP RH	\$	nn	5.00	
19	1 TAILLAMP CLIP LH	\$	nn	5.00	
20	2 REAR WINDSCREEN SELANT	\$	nn	80.00	
21	1 WINDSCREEN MOULDING	\$	nn	100.00	
22	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
23	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	
24	1 SPARE TYRE	\$	nn	330.00	
25	1 REAR LEFT FENDER ADVERTISEMENT STICKER	\$	nn	300.00	
26	1 REAR RIGHT FENDER ADVERTISEMENT STICKER	\$	nn	300.00	
<b>TOTAL</b>		<b>\$</b>		<b>3,220.02</b>	

<b>TOTAL PARTS</b>	<b>\$</b>	<b>34,293.46</b>
--------------------	-----------	------------------

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	600
To Rust-Proofing Of The Affected Areas.	\$	170.00	60
To reinstall rear bumper parking sensor.	\$	170.00	60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60
To repair and realign rear exhaust pipe.	\$	nn	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn	170.00 X

**Trans-cab Auto Services Pte Ltd****AAD1903-032**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 850Y**

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~ 380.00	X

**TOTAL \$ 14,340.00****Over All Total \$ 48,633.46**

49013.44

**(LUMP SUM)****Repair Days****20 DAYS**

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19004184/KTD3N2

Date: 15/03/2019

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000195
Claimant Vehicle No :	SHD850Y	Insured Vehicle No :	SLQ8091C
Date of Loss:	05/03/2019	Nature of Claim:	TP
		Claim No:	M1901430

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD850Y	Engine No:	M9R8839C003415
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC283391
Reg. Date:	01/03/2017 (Man. Year: 2016)	Odometer:	239312 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,293.44	7,859.00	26,434.44	77.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,720.00	1,500.00	13,220.00	89.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>49,013.44</b>	<b>9,359.00</b>	<b>39,654.44</b>	<b>80.91</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,430.94</b>	<b>655.13</b>	<b>2,775.81</b>	<b>80.91</b>
<b>Nett Amount (S\$)</b>	<b>52,444.38</b>	<b>10,014.13</b>	<b>42,430.25</b>	<b>80.91</b>

## INSPECTION

Date of Assignment:	08/03/2019	
Date Inspected:	06/03/2019	Inspected At:
		Trans Cab Auto Services Pte Ltd - Amk (HQ)
		No 2 Ang Mo Kio St 63
		Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2019)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD850Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1	*BUMPER LOWER REAR	Dented	768.84 FL	*768.84 FL
3	1	*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1	*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1	*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1	*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1	*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Distorted	225.95 FL	*225.95 FL
12	1	*BUMPER BEAM BRACKET RH REAR	Distorted	225.95 FL	*225.95 FL
13	1	*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1	*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1	*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1	*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1	*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1	*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1	*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1	*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1	*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1	*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1	*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1	*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1	*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1	*BOOT LOCK	Repair	202.67 FL	*- FL
27	1	*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2	*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2	*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1	*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
31	1	*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
32	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
33	1	*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
34	1	*TAILLAMP LH	Serviceable	552.55 FL	*- FL
35	1	*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
36	1	*TAILLAMP RH	Mtg Cracked	552.55 FL	*552.55 FL
37	1	*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
38	1	*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
39	1	*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
40	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
41	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
42	1	*EXHAUST REAR	Serviceable	7,489.05 FL	*- FL
43	1	*EXHAUST CAP REAR	Serviceable	230.49 FL	*- FL
44	1	*SET PARKING AID	Serviceable	700.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
46	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
47	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
48	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
49	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
50	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
51	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
52	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
53	1	*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
54	1	*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
55	1	*BOOT ADVERTISEMENT STICKER	Not Necessary	300.00 FS	*- FS
56	1	*REAR BUMPER ADVERTISEMENT STICKER	Necessary	200.00 FS	*80.00 FS
57	1	*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
58	1	*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
59	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
60	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
61	1	*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS
62	1	*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
63	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
64	1	*WINDSCREEN MOULDING	Serviceable	100.00 FS	*- FS
65	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
66	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
67	1	*SPARE TYRE	Serviceable	330.00 FS	*- FS
68	1	*REAR LEFT FENDER ADVERTISEMENT STICKER	Serviceable	300.00 FS	*- FS
69	1	*REAR RIGHT FENDER ADVERTISEMENT STICKER	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>37,746.04</b>	<b>8,704.44</b>
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,452.60	845.44
<b>Total Parts (\$\$)</b>	<b>34,293.44</b>	<b>7,859.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	660.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	600.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
11	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
14	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>14,720.00</b>	<b>1,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >