

ASS. REC. BY:

REF:

Tm1/ CC3/TM119004185/KW13

n2

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.


L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

7/3/19

File pass to
 1/1/19 8 2700k
 SHC 5587E to
 SLX 8158H to

(Red 44,993.46, 9490)

RECEIVED 10 MAR 2019

7/3/19

Email GIA to TMI

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 8/3 - typist

Report Format:

Lump Sum / I.B.I. (\$) 2700/-

Days Of Repair: 2

Resurvey No. of Trip: -

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

250

10

260

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2019		08 Mar 2019 11:19 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SH AUTO RENTAL AND LEASING PTE. LTD., Co. Reg. No.: 201438489C		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHC5587E	Date of Loss:	02/03/2019 10:00 - :59
Claim Type:	TP / M1901465	Policy/Cover Note No.:	MJ001118 (Comprehensive) Coverage: 21/08/2018 - 20/08/2019
Vehicle Reg. No. (Insured):	SLX8158H	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 19/03/2019]		
Adj Asg. Remarks:	OUR INSD HAS NOT REPORT THE ACCIDENT.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 7 March 2019 2:19 PM
To: calvin.er@transcab.com.sg; Ng Wai Yin
Cc: jasminetan@transcab.com.sg; SUR
Subject: SHB 5587E-DOA: 2/3/2019
Attachments: MARK EST.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Lump Sum \$2700/- before GST @ 2 days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Too Joon Hwa <shirleytoo@tokiomarine.com.sg>
Sent: Friday, 8 March 2019 11:17 AM
To: Motor Claims; Veron Chen (LKKAuto); SUR
Subject: RE: M190165-DS -RE: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 2/3/2019, SHC 5587E (TP VEHICLE), SLX 8158H (OI VEHICLE)

Claim no:M1901465-DS.

Thks

Shirley Too

Administrative Assistant, Motor Claims

Tokio Marine Insurance Singapore Ltd.
20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046
T (65) 6592 6409 | F (65) 6221 2101 |
E shirleytoo@tokiomarine.com.sg | W www.tokiomarine.com

A member of the
Tokio Marine Group

Please note that all personal information provided to Tokio Marine Insurance Singapore Ltd. is subject to the Personal Data Protection Policy Statement posted at www.tokiomarine.com.

From: Too Joon Hwa **On Behalf Of** Motor Claims
Sent: Friday, 8 March, 2019 11:16 AM
To: 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Motor Claims <motorclaims@tokiomarine.com.sg>
Subject: M190165-DS -RE: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 2/3/2019, SHC 5587E (TP VEHICLE), SLX 8158H (OI VEHICLE)

Hi Veron

Our insured have not report the accident.

We have assigned through Merimen.

Thanks.

Shirley Too

Administrative Assistant, Motor Claims

Tokio Marine Insurance Singapore Ltd.
20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046
T (65) 6592 6409 | F (65) 6221 2101 |
E shirleytoo@tokiomarine.com.sg | W www.tokiomarine.com

A member of the
Tokio Marine Group

Please note that all personal information provided to Tokio Marine Insurance Singapore Ltd. is subject to the Personal Data Protection Policy Statement posted at www.tokiomarine.com.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Thursday, 7 March, 2019 2:12 PM

To: SUR <sur@lkkauto.com>; Motor Claims <motorclaims@tokiomarine.com.sg>

Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 2/3/2019, SHC 5587E (TP VEHICLE), SLX 8158H (OI VEHICLE)

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5587E at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 6/3/2019

Enclosed herewith a copy of TP's GIA report ,police report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This message contains confidential information and is intended only for the addressee named. If you are not the named addressee (or authorised to receive for the addressee) you must not disseminate, distribute or copy this email. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 7 March 2019 2:12 PM
To: SUR; motorclaims@tokiomarine.com.sg
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD,
DOA: 2/3/2019, SHC 5587E (TP VEHICLE), SLX 8158H (OI VEHICLE)
Attachments: GIA.pdf; MARK EST.pdf; POLICE REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5587E at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 6/3/2019

Enclosed herewith a copy of TP's GIA report ,police report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5587E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 Mar 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001945
Chassis No.:	VF1ABL15AUC279379
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	29 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$22,605.00
Total Rebate Amount:	\$31,978.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2019 15:19
Date Of Accident	02/03/2019 10:00
Exact Location Of Accident	MARINA ONE WEST TOWER DROP-OFF POINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5587E
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	YAP YIN MAIN
NRIC No	S6920362J
Date Of Birth	03/07/1969
Occupation	OUTDOOR
Date Of Driving Pass	26/08/2010
Driving Experience	8 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96887368
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	888B SEMBAWANG ROAD
Postcode	758492
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHANGKAT NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 109 TAMPINES STREET 11 #01-261 , POSTCODE: 521109 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7819999 - FAX NO: 67832722
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX8158H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name YAP YIN MAIN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5587E

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Zheni
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190304/2134

1 of 3

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

Report No. T/20190304/2134

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/03/2019 17:16		Vide Report No.:		Station Diary No.: 28	
Informant's Particulars					
Name of Informant: YAP YIN MAIN			Address: 888B SEMBAWANG ROAD SINGAPORE 758492		
ID Type / ID No.: NRIC NO / S6920362J			Contact No.: Home/Office: Mobile: 96887368		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 49	Date of Birth: 03/07/1969	Type of Informant: Driver		
Race: Chinese		Language:		Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3A		Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 02/03/2019 10:00	Type of Location: DROP OFF
Location: Along Road 1 Traveling Toward Road 2 MARINA WAY STRAITS VIEW, MARINA ONE WEST TOWER DROP OFF ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC5587E	Car	RENAULT	LATITUDE 2.0L DCI AUTO D/AB 4DR	Red	Seriously Damaged	0
SLX8158H	Car	TOYOTA	PRIUS HYBRID 1.8S A	White	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20190304/2134

2 of 3

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

Report No. T/20190304/2134

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	YAP YIN MAIN	ID No.	S6920362J
Related Vehicle	SHC5587E (Car)	Contact No.	96887368
Hospital/Clinic	Y M CHAN CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	04/03/2019	Date Discharge	04/03/2019
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Name			
ONG CHO EE		ID No.	S0173132G
Related Vehicle	NIL	Contact No.	97775499
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 02/03/2019 at 2200hrs, I was on my taxi night shift duty (SHC5587E). I was at the Marina One West drop off point, alighting a passenger with many belongings. After everything was done, I moved forward and stopped before the stop line, waiting for oncoming traffic to clear before proceeding

As I was waiting, suddenly, a vehicle (SLX8158H) from the rear collided to me. The collision resulted in my vehicle's boot unable to close, tail light broken and the four doors were unable to close completely. The impact surged my body towards the steering wheel. We exchanged particulars and subsequently left the scene.

Due to the accident, I experienced headaches and numbness on my limbs and neck. I went to Y M Chan Clinic and was given 2 days of MC from 04/03/2019 to 05/03/2019. I will be going to the clinic again to get 3 days of MC. I am lodging this report for insurance purposes.



**SINGAPORE
POLICE FORCE**



T/20190304/2134

3 of 3

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

Report No. T/20190304/2134

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 NG ZHONG QIAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Contact No.:

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

04/03/2019 17:16

Classification Of Case:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5587E**AAD1903-034***Not Not hauled
L/Imp & 2700h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5587E

VF1ABL15AUC279379

RENAULT

LATITUDE

2.3.2019

TOKIO MARINE

30/9/2014

PART**LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEP R BRACKET SIDE RH REAR
- 5 1 BUMEP R RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEP R BRACKET SIDE LH REAR
- 8 1 BUMEP R RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

\$	<i>Bu</i>	1,108.46	✓
\$	<i>Net 10/1</i>	768.84	✓
\$	<i>Sm</i>	113.47	X
\$	<i>Sm</i>	135.97	X
\$	<i>Sm</i>	44.99	X
\$	<i>Sm</i>	43.61	X
\$	<i>Sm</i>	135.97	X
\$	<i>Sm</i>	44.99	X
\$	<i>Sm</i>	43.61	X
\$	<i>Bu</i>	777.52	✓
\$	<i>N</i>	225.95	X
\$	<i>n</i>	225.95	X
\$	<i>N Sm</i>	2,872.68	} X
\$	<i>Sm</i>	470.06	
\$	<i>Sm</i>	323.05	
\$	<i>Sm</i>	493.35	
\$	<i>Sm</i>	493.35	
\$	<i>na</i>	225.36	
\$	<i>na</i>	225.36	
\$	<i>Sm</i>	276.08	
\$	<i>Sm</i>	276.08	
\$	<i>N</i>	367.84	
\$	<i>N</i>	367.84	
\$	<i>Sm</i>	586.45	
\$	<i>N</i>	168.13	
\$	<i>N</i>	202.67	
\$	<i>N</i>	74.40	
\$	<i>Sm</i>	50.52	
\$	<i>Sm</i>	221.81	

Trans-cab Auto Services Pte Ltd

AAD1903-034

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5587E

30	1 FENDER PANEL REAR RH	\$	<i>n</i> 3,299.13	}	<i>X</i>
31	1 WHEELARCH REAR RH	\$	<i>sn</i> 543.47		
32	1 FENDER PANEL REAR LH	\$	<i>n</i> 3,299.13		
33	1 WHEELARCH REAR LH	\$	<i>sn</i> 543.47		
34	1 TAILLAMP LH	\$	<i>sn</i> 552.55		
35	1 TAILLAMP PANEL LH	\$	<i>n</i> 986.70		
36	1 TAILLAMP RH	\$	<i>sn</i> 552.55		
37	1 TAILLAMP PANEL RH	\$	<i>n</i> 986.70		
38	1 OUTER PANEL REAR (End Panel)	\$	<i>n</i> 1,471.77		
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>sn</i> 404.56		
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>n</i> 2,189.88		
41	1 SPARE WHEEL PANEL TRIM	\$	<i>sn</i> 612.21		
42	1 EXHAUST REAR	\$	<i>n</i> 7,489.05		
43	1 EXHAUST CAP REAR	\$	<i>n</i> 230.49		

			02
TOTAL	\$	34,526.04	
10%	\$	3,452.60	
	\$	31,073.44	

Special Nett

1	1SET PARKING AID	\$	<i>sn</i> 700.00	<i>X</i>
2	1SET REAR BUMPER CLIP	\$	<i>sn</i> 66.00	<i>—</i>
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>n</i> 33.00	<i>✓</i>
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00	<i>X</i>
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>nn</i> 20.00	<i>X</i>
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 10.00	<i>X</i>
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>nn</i> 20.00	<i>X</i>
8	1SET BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00	<i>✓</i>
9	1SET BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00	<i>✓</i>
10	1 EXHAUST MOUNTING REAR	\$	<i>sn</i> 17.82	<i>X</i>
11	1SET BOOT FINISHER CLIP	\$	<i>nn</i> 24.20	<i>X</i>
12	1 REAR BOOT STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00	<i>X</i>
13	1 REAR BOOT STICKER '6555-3333'	\$	<i>nn</i> 80.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1903-034**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5587E

14 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	}	X
15 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00		
16 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00		
17 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00		
18 1 TAILLAMP CLIP RH	\$	nn	5.00		
19 1 TAILLAMP CLIP LH	\$	nn	5.00		
20 2 REAR WINDSCREEN SELANT	\$	nn	80.00		
21 1 WINDSCREEN MOULDING	\$	nn	100.00		
22 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
23 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00		
24 1 SPARE TYRE	\$	nn	330.00		

TOTAL \$ 2,280.02**TOTAL PARTS \$ 33,353.46****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	3001
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1903-034**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5587E

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	NA 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	↪ 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	↪ 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	↪ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	↪ 170.00	X
To check steering geometry and computer wheel alignment	\$	↪ 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	↪ 380.00	X

TOTAL \$ 14,340.00**Over All Total \$ 47,693.46**

48073.44

(LUMP SUM)**Repair Days****20 DAYS**

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19004185/KVD3N2
Date: 13/03/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ001118
Claimant Vehicle No :	SHC5587E	Insured Vehicle No :	SLX8158H
Date of Loss:	02/03/2019	Nature of Claim:	TP
		Claim No:	M1901465

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5587E	Engine No:	M9R8839C001945
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC279379
Reg. Date:	30/09/2014 (Man. Year: 2014)	Odometer:	827033 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	33,353.44	2,554.34	30,799.10	92.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,720.00	800.00	13,920.00	94.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,073.44	3,354.34	44,719.10	93.02
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	48,073.44	2,700.00	45,373.44	94.38
+ GST 7.00/7.00% (S\$)	3,365.14	189.00	3,176.14	94.38
Nett Amount (S\$)	51,438.58	2,889.00	48,549.58	94.38

INSPECTION

Date of Assignment:	08/03/2019	
Date Inspected:	06/03/2019 Inspected At:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

Adjuster Report

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2019)
Parts:	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5587E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented/Distorted	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
19	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Repair	168.13 FL	*- FL
26	1		*BOOT LOCK	Repair	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
31	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
32	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
33	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
34	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
35	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
36	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
37	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
38	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
39	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
40	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
41	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
42	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
44	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
45	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
46	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
47	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
48	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
49	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
50	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
51	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
52	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
53	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
54	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
55	1		*REAR BOOT STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
56	1		*REAR BOOT STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
57	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
58	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
59	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
60	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
61	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
62	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
63	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
64	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
65	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
66	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
67	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	36,806.04	2,819.82
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,452.60	265.48
Total Parts (\$\$)	33,353.44	2,554.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	300.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
11	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
14	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
Gross Labour Cost (\$\$)			14,720.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >