

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 11 Mar 2019

**Preliminary Advice**

Insured Vehicle No	: FU4397Y	Accident Date	: 02/03/2019
TP Vehicle No	: SKU6498S	Assignment Date	: 07/03/2019
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 5.00
Date of Inspection	: 08/03/2019		
Inspection At	: TEAMWORK GARAGE PTE LTD (HQ) 53 UBI AVE 1 #01-24, PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,146.79
Revised Amount	:S\$	4,177.53
Check Items (Estimated)	:S\$	
Total	:S\$	4,177.53
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.