

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Thelma Choo

Date: 12 Mar 2019

**Preliminary Advice**

Insured Vehicle No	: GBC548Y	Accident Date	: 05/03/2019
TP Vehicle No	: SMF7539G	Assignment Date	: 07/03/2019
Make	: BMW 428I	Est. Duration of Repair	: 8.00
Date of Inspection	: 07/03/2019		
Inspection At	: CAS GARAGE PTE LTD (HQ) NO.1, KAKI BUKIT AVE 6, #02-22 AUTOBAY SINGAPORE 417883		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	21,808.79
Revised Amount	:S\$	7,186.99
Check Items (Estimated)	:S\$	8,303.19
Total	:S\$	15,490.18

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :The above survey was conducted on a 'Without Prejudice' basis.