

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                |
|--------------------------------------------------------------------------------|
| <b>From :</b>                                                                  |
| PEGASUS ENGINEERING & TRADING PTE LTD<br>74 KIAN TECK ROAD<br>SINGAPORE 628800 |
| Officer in Charge : CHEW HUP SENG<br>Tel :<br>Email :                          |

|                                                                                     |
|-------------------------------------------------------------------------------------|
| <b>Customer :</b>                                                                   |
| GRAB RENTALS PTE LTD<br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960 |
| Attn :<br>Tel :<br>Fax No. :                                                        |

|                              |                                 |                           |
|------------------------------|---------------------------------|---------------------------|
| Quotation No. : QO19/03-1129 | Quotation Date : 12/03/2019     | Terms : 30 DAYS           |
| Vehicle No. : SLP2082Z       | Chassis No. : JM6BN22A8H0154297 | Third Party Insurer : AXA |
| Model : MAZDA 3              | Date of Accident : 06/03/2019   |                           |
| Remarks :                    |                                 |                           |

| ITEM | DESCRIPTION                                                   | Qty | UNIT PRICE | AMOUNT (SGD) |
|------|---------------------------------------------------------------|-----|------------|--------------|
| 1    | FRONT BUMPER                                                  | 1   | 830.0000   | de ✓ 830.00  |
| 2    | FRONT BUMPER SIDE RETAINER (RHS)                              | 1   | 70.0000    | ne ✓ 70.00   |
| 3    | FRONT BUMPER RIVET @ 02PC                                     | 2   | 5.0000     | ne ✓ 10.00   |
| 4    | FRONT BUMPER CLIPS @ 10PC                                     | 10  | 4.0000     | ne ✓ 40.00   |
| 5    | FRONT FENDER (RHS)                                            | 1   | 395.0000   | bt ✓ 395.00  |
| 6    | FRONT HEADLAMP (RHS)                                          | 1   | 1,020.0000 | R 1,020.00   |
| 7    | (LESS 20% 1-6) Washer tank de ✓ 125                           | 1   | 639.0000   | ? 639.00     |
| 8    | Fender bracket bt ✓ 45                                        | 1   | 830.0000   | ? 830.00     |
| 9    | TO REMOVE & REFOCUS FRONT HEADLAMP                            | 1   | 120.0000   | 30 120.00    |
| 10   | TO PANEL BEAT & KNOCKING                                      | 1   | 800.0000   | 500 800.00   |
| 11   | TO PUTTY & SPRAY PAINT ON THE FRONT BUMPER & RHS FRONT FENDER | 1   | 600.0000   | 500. 600.00  |
| 12   | TO APPLY RUST PROOFING & TUFFOCATING TREATMENT                | 1   | 100.0000   | 30 100.00    |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tagline 97495749 / 67.418434  
WP' 04 days  
13/3/19 @ 110pm  
# surveillkkauto.com  
Lumpsum  
Resurvey after repair

**Sub Total** 5,454.00  
**GST(7.00%)** 381.78  
**Total (SGD)** 5,835.78

Please conduct the survey at  
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800