



VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-123, Enterprise Hub

Singapore 608586

Repair Estimate

Tel: 6267 9916

Fax: 6267 9313

www.avantage.sg

Date : 4-Mar-2019

Vehicle Num : SKL4200U

Make/Model : VW GOLF VARIANT

Chassis No : WVVZZZAUZGP578579

S/N	PARTS	QTY	PRICE	TOTAL
1	REAR BUMPER	1	\$ 1,500.00	\$ 1,500.00
2	REAR ATTACHMENT STRIP	1	\$ 70.00	\$ 70.00
3	IMPACT BEAM	1	\$ 500.00	\$ 500.00
4	LH GUIDE PIECE	1	\$ 50.00	\$ 50.00
5	RH GUIDE PIECE	1	\$ 50.00	\$ 50.00
6	LH GUIDE PIECE FOR TAILLIGHT	1	\$ 50.00	\$ 50.00
7	RH GUIDE PIECE FOR TAILLIGHT	1	\$ 50.00	\$ 50.00
8	REAR DIFFUSOR	1	\$ 350.00	\$ 350.00
9	REAR TRUCK LID	1	\$ 1,800.00	\$ 1,800.00
10	REAR TRUCK WEATHERSTRIP	1	\$ 410.00	\$ 410.00
11	REAR GAS FILLED STRUT	2	\$ 100.00	\$ 200.00
12	REAR TRUCK HINGE	2	\$ 90.00	\$ 90.00
13	REAR TRUCK STICKER PLATE	1	\$ 50.00	\$ 50.00
14	REAR TRUCK LATCH LOCK	1	\$ 209.00	\$ 209.00
15	REAR APRON	1	\$ 650.00	\$ 650.00
16	END PLATE	1	\$ 140.00	\$ 140.00
17	REAR BUMPER HOLDER	2	\$ 30.00	\$ 60.00
18	REAR TRUCK WIRING GROMMET	2	\$ 35.00	\$ 70.00
19	REAR PARKING SENSOR	2	\$ 170.00	\$ 340.00
20	REAR PARKING SENSOR SEAL RING	2	\$ 5.00	\$ 10.00
21	GOLF R BADGE	1	\$ 90.00	\$ 90.00
22	REAR EXHAUST	1	\$ 810.00	\$ 810.00
23	BRACKET FOR EXHAUST	1	\$ 60.00	\$ 60.00
24	EXHAUST HANGER	1	\$ 30.00	\$ 30.00
25	EXHAUST CLAMP	1	\$ 55.00	\$ 55.00
26	LH OUTER TAILLAMP	1	\$ 240.00	\$ 240.00
27	REAR BUMPER WIRING HARNESS FOR PARKING AID	1	\$ 320.00	\$ 320.00
	TOTAL PARTS			\$ 8,254.00
	TOTAL AMOUNT			\$ 8,254.00
	MISCELLANEOUS ITEM			
	LABOUR			
1	To remove/refit/panel beat of rear bumper, rear lid, rear apron , rear end panel & other affect areas.		\$ 1,500.00	\$ 1,500.00
2	To putty and spray rear bumper, rear lid, rear end panel and other affected area (LH and RH rear quarter panel)		\$ 1,000.00	\$ 1,000.00
3	To diagnose on wiring harness issue due to impact.		\$ 60.00	\$ 60.00
4	To clear faults after repair is done.		\$ 50.00	\$ 50.00
	TOTAL			\$ 10,864.00
	GST 7%			\$ 760.48
	GRAND TOTAL			\$ 11,624.48