



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Rasul
Hp 96000568
3 days
4/3
06/03/19 @ 1540
Resy after repair

Date: 06.03.2019

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2817G PRIUS HYBRID 1.8L A (2012)

To Supply

1)	1pc	Front bumper <i>cut</i>	\$	1,230.00
2)	1set	Front bumper clips <i>re-</i>	\$	30.00
3)	1pc	Front bumper lower garnish <i>cut</i>	\$	225.50
4)	1pc	Front grille "Toyota" emblem <i>re-</i>	\$	62.00
5)	1pc	Left head lamp <i>X (old damage) inconsistent</i>	\$	1,060.00
			Sub total parts	\$ 2,607.50
			Less: 25% discount	\$ (651.88)
				\$ 1,955.62

To supply S.Nett Parts

1)	1pc	Front license no. plate <i>CR4</i>	\$	30.00
			Sub total S.Nett parts	\$ 30.00

L/charges

1)	To focus left head lamp.	\$	30.00
2)	To remove front bumper & left head lamp. Replace the above parts. Align & adjust front bumper.	\$	250.00
3)	To putty, respray painting front bumper.	\$	250.00 <i>200</i>
		Sub total L/charges	\$ 530.00
			\$ 2,515.62