



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33762

INDIA INTERNATIONAL INSURANCE P.L.

64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711

DATE : 05/03/2019

CLAIM NO. : 11285

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBL3617P
MAKE/MODEL : HON / PCX150 A

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BRAKE LEVER AFTER MARKET	REPLACE	1.00	\$108.00	108.00
2	COVER FOOTREST LH P/N: 49600	REPLACE	1.00	\$77.00	77.00
3	COVER FOOTREST LOWER LH	REPLACE	1.00	\$119.00	119.00
4	COVER L FR	REPLACE	1.00	\$140.00	140.00
5	COVER SIDE LH P/N: 52550	REPLACE	1.00	\$383.00	383.00
6	COVER SUB ASSY.	REPLACE	1.00	\$35.00	35.00
7	COVER, R. FR.	REPLACE	1.00	\$135.00	135.00
8	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	6.00	\$35.00	210.00
9	SIDE MIRROR 1SET	REPLACE	1.00	\$108.00	108.00

SUB TOTAL

\$1,315.00

GST @ 7 %

\$92.05

GRAND TOTAL

\$1,407.05

50% deposit required before ordering of parts.

Validity: 30 days



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001: 2015

S/N Description**Action****Qty****Unit Price****Amount**

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD**RAYMOND**

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No ill-to-modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

