



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 19700288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33762

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711

DATE : 05/03/2019
CLAIM NO. : 11285
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBL3617P
MAKE/MODEL : HON / PCX150 A

*not Authorised
Link
The, the other 4-
3-
11/3/19*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BRAKE LEVER AFTER MARKET	REPLACE	1.00	\$108.00	108.00
2	COVER FOOTREST LH P/N: 49600	REPLACE	1.00	\$77.00	77.00
3	COVER FOOTREST LOWER LH	REPLACE	1.00	\$119.00	119.00
4	COVER L FR	REPLACE	1.00	\$140.00	140.00
5	COVER SIDE LH P/N: 52550	REPLACE	1.00	\$383.00	383.00
6	COVER SUB ASSY	REPLACE	1.00	\$35.00	35.00
7	COVER, R. FR	REPLACE	1.00	\$135.00	135.00
8	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	Supply/Install	6.00	\$35.00	210.00
9	SIDE MIRROR 1SET	REPLACE	1.00	\$108.00	108.00

SUB TOTAL

\$1,315.00

GST @ 7 %

\$92.05

GRAND TOTAL

\$1,407.05

50% deposit required before ordering of parts.

Validity: 30 days



- To ensure delivery of parts on time
- To ensure delivery of parts on time
- To ensure delivery of parts on time
- To ensure delivery of parts on time
- To ensure delivery of parts on time
- To ensure delivery of parts on time
- To ensure delivery of parts on time
- To ensure delivery of parts on time



CERT NO. 2005-10083
ISO 9001:2015

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

9-672
102
604.60
784.60



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000268K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33762

- Rev. 1

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711

DATE : 05/03/2019
CLAIM NO. : 11285
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBL3617P
MAKE/MODEL : HON / PCX150 A

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER FOOTREST LOWER LH	REPLACE	1.00	\$119.00	107.10
				Disc %: 10.00	
2	COVER SIDE LH P/N: 52550	REPLACE	1.00	\$383.00	344.70
				Disc %: 10.00	
3	COVER SUB ASSY.	REPLACE	1.00	\$35.00	31.50
				Disc %: 10.00	
4	COVER, R. FR.	REPLACE	1.00	\$135.00	121.50
				Disc %: 10.00	
5	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	6.00	\$30.00	180.00

SUB TOTAL	\$784.80
GST @ 7 %	\$54.94
GRAND TOTAL	\$839.74

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0303
ISO 9001 : 2015