

### REPAIR ESTIMATE\*

MAKE :

**MODEL : HYUNDAI i40**

DATE 6/3/2019 15:00

4/Sum  
CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Under Cover			\$ 228.00
	<b>SUB TOTAL</b>			<b>\$ 803.00</b>
	<b>LESS 20%</b>			<b>\$ 160.60</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 642.40</b>
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Bumper Reverse Sensor			\$ 135.70
				<b>\$ 185.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 80.00
	<b>TOTAL LABOUR</b>			<b>\$ 810.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,638.10</b>
	NAZ LKLC			
	6/3/19 1610			
	- LIS			
	3 DAYS			
	AFTER REPAIR PHOTOS			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.