

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 462J**AAD1903-030**

Not Notarized
Recovery By paint
85911.54

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 462J

VF1ABL15AUC283405

RENAULT

LATITUDE

4.3.2019

AXA

31/7/2017

PART**LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEP R BRACKET SIDE RH REAR
- 5 1 BUMEP R RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEP R BRACKET SIDE LH REAR
- 8 1 BUMEP R RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

\$	<i>Bu</i>	1,108.46	✓
\$	<i>nd 1011</i>	768.84	✓
\$	<i>SL</i>	113.47	X
\$	<i>SL</i>	135.97	X
\$	<i>SL</i>	44.99	X
\$	<i>CM</i>	43.61	✓
\$	<i>SL</i>	135.97	X
\$	<i>SL</i>	44.99	X
\$	<i>SL</i>	43.61	X
\$	<i>B</i>	777.52	✓
\$	<i>N</i>	225.95	X
\$	<i>D.1</i>	225.95	✓
\$	<i>K</i>	2,872.68	} X
\$	<i>SL</i>	470.06	
\$	<i>SL</i>	323.05	
\$	<i>SL</i>	493.35	
\$	<i>SL</i>	493.35	
\$	<i>SL</i>	225.36	
\$	<i>SL</i>	225.36	
\$	<i>SL</i>	276.08	
\$	<i>SL</i>	276.08	
\$	<i>N</i>	367.84	
\$	<i>N</i>	367.84	
\$	<i>SL</i>	586.45	
\$	<i>N</i>	168.13	
\$	<i>N</i>	202.67	
\$	<i>SL</i>	74.40	
\$	<i>SL</i>	50.52	
\$	<i>SL</i>	221.81	

Trans-cab Auto Services Pte Ltd

AAD1903-030

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 462J

30	1 FENDER PANEL REAR RH	\$	<i>N</i>	3,299.13	} X
31	1 WHEELARCH REAR RH	\$	<i>Sn</i>	543.47	
32	1 FENDER PANEL REAR LH	\$	<i>N</i>	3,299.13	
33	1 WHEELARCH REAR LH	\$	<i>Sn</i>	543.47	
34	1 TAILLAMP LH	\$	<i>Sn</i>	552.55	
35	1 TAILLAMP PANEL LH	\$	<i>N</i>	986.70	
36	1 TAILLAMP RH	\$	<i>Sn</i>	552.55	}
37	1 TAILLAMP PANEL RH	\$	<i>N</i>	986.70	
38	1 OUTER PANEL REAR (End Panel)	\$	<i>N</i>	1,471.77	✓
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i>	404.56	X
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>N</i>	2,189.88	X
41	1 SPARE WHEEL PANEL TRIM	\$	<i>Sn</i>	612.21	X
42	1 EXHAUST REAR	\$	<i>N</i>	7,489.05	X
43	1 EXHAUST CAP REAR	\$	<i>N</i>	230.49	X

TOTAL	\$	34,526.04
10%	\$	3,452.60
	\$	31,073.44

Special Nett

1	1SET PARKING AID	\$	<i>Sn</i>	700.00	<i>Good</i>
2	1SET REAR BUMPER CLIP	\$	<i>N</i>	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>N</i>	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>N</i>	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>N</i>	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>N</i>	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>N</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>N</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>N</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Sn</i>	17.82	X
11	1SET BOOT FINISHER CLIP	\$	<i>N</i>	24.20	X
12	1 REAR BOOT STICKER 'TRANS-CAB'	\$	<i>N</i>	80.00	X
13	1 REAR BOOT STICKER '6555-3333'	\$	<i>N</i>	80.00	X

Trans-cab Auto Services Pte Ltd**AAD1903-030**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 462J

14 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	}
15 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	
16 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	
17 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	
18 1 TAILLAMP CLIP RH	\$	nn	5.00	
19 1 TAILLAMP CLIP LH	\$	nn	5.00	
20 2 REAR WINDSCREEN SELANT	\$	nn	80.00	
21 1 WINDSCREEN MOULDING	\$	nn	100.00	
22 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
23 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	
24 1 SPARE TYRE	\$	nn	330.00	

TOTAL \$ 2,280.02**TOTAL PARTS \$ 33,353.46****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1903-030**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 462J

To transfer of rear end panel fittings, attachment and perform water seepage test. \$ 170.00 *601*

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test. \$ *nn* 170.00 *X*

To supply and re-do rear luggage floor panel insulation padding. \$ *4* 380.00 *X*

To transfer of rear fender fittings, attachment and perform water seepage test. \$ *4* 380.00 *X*

To transfer of rear windscreen fittings and conduct water seepage test. \$ *4* 170.00 *X*

To check steering geometry and computer wheel alignment \$ *4* 220.00 *X*

To transfer of rear door fittings, attachment and perform water seepage test. \$ *4* 380.00 *X*

TOTAL \$ 14,340.00**Over All Total \$ 47,693.46****(PART-BY-PART)****Repair Days*****20 DAYS******\$4day,***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: