



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

NO. : 33764

DATE : 06/03/2019
CLAIM NO. : 11286
POLICY NO. : AVFMSB0000651800

FROM : RAYMOND

VEHICLE NO. : FBN1513H
MAKE/MODEL : YAM / NMAX155 ABS

*not added
line
to be attached
3 dy.
7/3/19
p/p*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094	REPLACE	1.00	\$35.00	35.00
2	BOARD FOOTREST LH P/N: 59588	REPLACE	1.00	\$52.00	52.00
3	BOARD FOOTREST RH P/N: 59589	REPLACE	1.00	\$52.00	52.00
4	COVER CLUTCH OUTER P/N: 58147	REPLACE	1.00	\$28.00	28.00
5	COVER CLUTCH OUTER DAMPER 1 P/N: 58111	REPLACE	2.00	\$12.00	24.00
6	COVER CLUTCH OUTER DAMPER 2 P/N: 58172	REPLACE	1.00	\$7.00	7.00
7	COVER CLUTCH OUTER DAMPER 3 P/N: 58107	REPLACE	1.00	\$7.00	7.00
8	COVER CLUTCH OUTER DAMPER 4 P/N: 58140	REPLACE	1.00	\$12.00	12.00
9	COVER SIDE CENTRE LH (WHITE) P/N: 58097	REPLACE	1.00	\$30.00	30.00
10	COVER SIDE CENTRE RH (WHITE) P/N: 58117	REPLACE	1.00	\$30.00	30.00
11	COVER SIDE REAR LH (WHITE) P/N: 58170	REPLACE	1.00	\$38.00	38.00
12	COWLING FRONT LH (WHITE) P/N: 58179	REPLACE	1.00	\$34.00	34.00
13	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	1.00	\$12.00	12.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	3.00	\$35.00	100 105.00
15	LAMP SIGNAL FRONT LH P/N: 59587	REPLACE	1.00	\$35.00	50 35.00
16	MUDGUARD FRONT (WHITE) P/N: 58087	REPLACE	1.00	\$52.00	11 52.00 X
17	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$38.00	50 38.00 X
18	SIDE STAND P/N: 58211	REPLACE	1.00	\$25.00	25 25.00 X
19	SPRAY PAINT FRONT MUDGUARD (LACQUER)	Spray	1.00	\$40.00	40 40.00 ✓
20	SPRAY PAINT TAIL COWLING LH (LACQUER)	Spray	1.00	\$60.00	60 60.00 ✓
21	STAND MAIN P/N: 58138	REPLACE	1.00	\$68.00	68 68.00 X
22	STICKER (CERTIS CISCO) SIDE REAR NEW MODEL P/N: 61181	REPLACE	1.00	\$45.00	45 45.00 ✓
23	STICKER (CERTIS CISCO) WINDSHIELD NEW MODEL P/N: 61182	REPLACE	1.00	\$60.00	60 60.00 ✓
24	STICKER (CISCO) MUDGUARD FRONT P/N: 58618	REPLACE	1.00	\$38.00	38 38.00 ✓
25	STICKER (CISCO) SIDE REAR LH NEW MODEL P/N: 61573	REPLACE	1.00	\$15.00	15 15.00 ✓
26	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12 12.00 X
27	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BACK ONCE REPAIR DONE.		1.00	\$35.00	35 35.00 ✓
28	WINDSHIELD P/N: 58073	REPLACE	1.00	\$60.00	11 60.00 X

SUB TOTAL

\$1,049.00

GST @ 7 %

\$73.43

GRAND TOTAL

\$1,122.43

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Acknowledge & Accepted By



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	 RAYMOND				

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

